

CONTROL BLOCK:

						1
--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1																											
REPORT SOURCE		L	6	0	5	0	0	0	2	5	9	7	0	8	2	8	8	1	8	0	9	2	2	8	1	9		
		60	61	DOCKET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

0 2 During refueling outage, while performing SI 4.2.B-69, recirculation pump trip reactor high pressure switch (1-PS-3-204B) was found 0.5 percent above the limit of T.S.

Table 3.2.B. There was no danger to the health or safety of the public. Redundant

systems were available and operable. Previous similar events: BFRO-50-260/78023,

80030

0	6	
---	---	--


0	7	
---	---	--

0 3 | 7 8 9 80

SYSTEM CODE 0 9		CAUSE CODE J A		CAUSE SUBCODE X		COMPONENT CODE I N S T R U						COMP. SUBCODE S		VALVE SUBCODE Z			
7	8	9	10	11	12	12	13	13	14	15	16	17	18	19	20		
(17) LER/PO REPORT NUMBER		EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 4 8		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0							
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN E		FUTURE ACTION F		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER L		COMPONENT MANUFACTURER S 3 8 2	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

1	0	Setpoint drift. Reset 1-PS-3-204B to proper setpoint and successfully completed
---	---	---

SI 4.2.B-69. DCR 1398 will replace this switch with an analog transmitter and

 , bistable switch.

1	2	BIOGRAPHICAL SKETCH	
---	---	---------------------	--

1	3	
---	---	--

1 4
J R 9

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 5 H 28 0 0 0 29 NA B 31 Surveillance testing 32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 33 34

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

45 80

PERSONNEL EXPOSURES									
NUMBER				TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	

ISSUED 2 11 44 45 DESCRIPTION NA NRC USE ONLY

NRC USE ONLY

(205) 729-6134

8109240281 810922
PDR ADCK 05000259
S PDR

Gene Holder

PHONE

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81048 Technical Specification Involved Table 3.2.B
Reported Under Technical Specification 6.7.2.b(2) *Date due NRC: 9/27/81
Date of Occurrence 8/28/81 Time of Occurrence 0940 Unit 1

Identification and Description of Occurrence:

During performance of SI 4.2.B-69 recirculation pump trip reactor high pressure switch (1-PS-3-204B) was found 0.5 percent above the limit of T.S. Table 3.2.B.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 at 99%.

Unit 3 at 98%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Setpoint drift.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Reset 1-PS-3-204B to proper setpoint and successfully completed SI 4.2.B-69. DCP 1398 will replace this switch with an analog transmitter and bistable switch.

Failure Data: BFRO-50-260/78023, 80030.

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: ALL