

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D D C 1 2 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5

CONT

0 1 L 6 0 5 0 0 0 3 1 5 7 0 7 2 1 8 1 8 0 9 1 8 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 DURING ROUTINE TOUR, A SUPPLY BREAKER FOR HEAT TRACE CIRCUITS WAS FOUND TRIPPED. THIS  
0 3 BREAKER SUPPLIES POWER TO TRAIN "B" HEAT TRACE CIRCUITS FOR THE BORON INJECTION TANK.  
0 4 ON TWO OTHER OCCASSIONS, THIS BREAKER HAS BEEN FOUND TRIPPED. THESE CONDITIONS ARE  
0 5 NON-CONSERVATIVE WITH REGARDS TO T.S. 3.5.4.2. THE FIRST EVENT ON 7-21-81 WAS NOT  
0 6 DETERMINED REPORTABLE UNTIL 9-17-81.

0 7  
0 8

0 9 P C 11 X 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16  
17 8 1 0 3 9 0 3 L 0  
X 18 X 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 Z 9 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 INVESTIGATION HAS BEEN UNABLE TO DETERMINE THE CAUSE OF THE BREAKER TRIPPING. CON-  
1 1 TINUED MONITORING OF THE PANEL TO INSURE THE PANEL IS OPERABLE WILL ENDURE UNTIL THE  
1 2 CAUSE CAN BE DETERMINED. UPDATED LER WILL FOLLOW WHEN CAUSE IS DETERMINED.

1 3  
1 4

1 5 H 28 0 0 0 29 NA 30 B 31 OPERATOR OBSERVATION 32

1 6 Z 33 Z 34 NA 35 NA 36

1 7 0 0 0 37 Z 38 NA 39

1 8 0 0 0 40 NA 41

1 9 Z 42 NA 43

2 0 N 44 NA 45

8109290292 810918  
 PDR ADOCK 05000315  
 S PDR

R. A. PALMER

PHONE: 616-465-5901

GPO 91-7-925