

## LICENSEE EVENT REPORT

CONTROL BLOCK:                      (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	C	O	F	S	V	1	2	0	0	-	0	0	0	0	0	-	C	0	3	4	1	1	2	0	4		5												
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33													
LICENSEE CODE										LICENSE NUMBER										LICENSE TYPE										CAT 58									

CON'T

01	L	6	0	5	0	0	0	2	6	7	7	0	8	1	2	8	1	8	0	9	1	1	8	1	9														
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32														
REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 One of the two bearing water makeup pumps was removed from service to repair a valve

03 bonnet leak with the plant at power. The valve leak had not rendered the pump inoper-

04 able. Degraded mode of LCO 4.2.2. Reportable per Fort St. Vrain Technical Specifi-

05 cation AC 7.5.2(b)2. Redundant equipment operable and available. No effect on public

06 health or safety. Similar events reported in RO 79-26 and RO 80-77.

07

08

09	C	B	11	X	12	Z	13	V	A	L	V	E	X	14	C	15	A	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47																																		
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE		VALVE SUBCODE		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																																					
9		10		11		12								13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47	
C		B		X		Z								V		A		L		V		E		X		C		A		1		8		1		0		5		2		0		3		L		-		0		Y		Z		Z		0		0		0		0		Y		N		N		W		0		3		0					

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause for this event was the removal from service of a bearing water makeup pump

11 with the reactor at power. After valve repair was completed, the pump was returned to

12 service. The valve is a carbon steel, 150 pound, 3 inch check valve, Model 5341 WE,

13 manufactured by Walworth.

14

15 E 28 0 4 6 29 N/A 30 A 31 Operator Observation 32

16 Z 33 Z 34 N/A 35 N/A 36

17 0 0 0 37 Z 38 N/A 39

18 0 0 0 40 N/A 41

19 Z 42 N/A 43

20 N 44 N/A 45

8109290407 810911  
PDR ADOCK 05000267  
S PDR

NRC USE ONLY

NAME OF PREPARER

M. H. McBride

PHONE: (303) 785-2224