

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT	58

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 6 6 7 0 8 2 9 8 1 8 0 9 1 5 8 1 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While the plant was in steady state operation at 1160 MWt and while per-
0 3 forming control board walkdown, one of the redundant torus/drywell vac-
0 4 uum breaker closed position indicators for 2T48-A0F-323H, was found to be
0 5 inoperative. Tech Specs 3.6.4.1.b requires all torus/drywell vacuum
0 6 breaker position indicators to be operable. Plant operation nor the
0 7 health and safety of the public was affected. This is a repetitive occ-
0 8 urrence as last reported on Reportable Occurrence No. 50-366/1980-124.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
[0][9]		[S][A]		[E]		[X]		[V][A][L][V][E][X]				[X]		[C]	
7 8		9 10		11 12		13 14		15 16 17 18				19 20		21 22	
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
[17]		[8][1]		[0][8][0]		[0][3]		[L]		[0]					
21 22		23 24		25 26		27 28		29 30		31 32					
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER	
[Z]		[X]		[Z]		[Z]		[0][0][0][0]		[Y]		[N]		[N]	
33 34		35 36		37 38		39 40		41 42		43 44		45 46		47 48	
18 19		20 21		22 23		24 25		26 27		28 29		30 31		32 33	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this occurrence is unknown at this time due to the inacces-

1 1 | sibility of the valves. Testing of the vacuum breaker valve, 2T48-AOF-

1 2 | 323H, will be performed per Tech Specs 3.6.4.1, ACTION e, until the next

1 3 | reactor cold shutdown, at which time inspection and repairs will be made

1	4	8	9											80						
FACILITY STATUS				% POWER				OTHER STATUS (30)				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION (32)				80
1	5	E	28	0	4	8	29	NA	44	B	31	Operator Observation				36	80			
ACTIVITY CONTENT				RELEASED OF RELEASE				AMOUNT OF ACTIVITY (35)				LOCATION OF RELEASE (36)				80				
1	6	Z	33	Z	34	NA				44	NA				45	80				
PERSONNEL EXPOSURES				TYPE				DESCRIPTION (39)								80				
1	7	0	0	0	37	Z	38	NA	44					80						
PERSONNEL INJURIES				DESCRIPTION (41)												80				
1	8	0	0	0	40	NA				44					80					
LOSS OF OR DAMAGE TO FACILITY				DESCRIPTION (43)												80				
1	9	Z	42	NA				44					80							
PUBLICITY				ISSUED DESCRIPTION (45)												80				
2	0	N	44	NA				44									80			
8109290453 810915 PDR ADOCK 05000066 S PDR												NRC USE ONLY				80				
												68	69			100				

NAME OF PREPARER C. L. Coggin - Supt. Plt. Eng. Serv.

PHONE: 912-367-7851

LER #: 50-366/1981-080
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1981-080

On August 29, 1981, while the plant was in steady state operation at 1160 MWt and while performing control board walkdown, one of the redundant torus/drywell vacuum breaker closed position indicators for 2T48-AOF-323H, torus/drywell vacuum breaker valve, was found to be inoperative. Tech Specs 3.6.4.1.b requires all torus/drywell vacuum breakers to be operable and closed with the redundant position indicators operable. Plant operation nor the health and safety of the public was affected. This is a repetitive occurrence as last reported on Reportable Occurrence Report No. 50-366/1980-124.

The cause of this occurrence is unknown at this time due to the inaccessibility of the valves. Testing of the vacuum breaker valve, 2T48-AOF-323H, will be performed per Tech Specs 3.6.4.1, ACTION e, until the next reactor cold shutdown. The torus/drywell vacuum breaker closed position indicator will be inspected and repaired as necessary at that time.