

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	3	1	7	0	5	2	7	8	3	8	0	6	1	0	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

02 | During normal operation channel B of the containment H<sub>2</sub>O<sub>2</sub> analyzer was

03 | rendered inop on 5/21. Difficulties in calibrating channel A on 5/27 ren

04 | dered A inop. Power reduction commenced per T.S. 3.6. New PASS system op

05 | erable and capable of determining H<sub>2</sub>O<sub>2</sub> concentrations. No effect on H&S.

06 | A returned to operable at 1430 hours ending LCO. Note that standard T.S.

07 | do not require an LCO w/PASS operable. Previous report RO 82-10.

08 |

0 9

SYSTEM CODE [S] [E] (11)

CAUSE CODE [E] (12)

CAUSE SUBCODE [B] (13)

COMPONENT CODE [X] [X] [X] [X] [X] [X] (14)

COMP SUBCODE [Z] (15)

VALVE SUBCODE [Z] (16)

LER/RO REPORT NUMBER (17) [8] [3]

EVENT YEAR [8] [3]

SEQUENTIAL REPORT NO. [0] [2] [1]

OCCURRENCE CODE [0] [1]

REPORT TYPE [T]

REVISION NO. [0]

ACTION TAKEN [B] (18)

FUTURE ACTION [Z] (19)

EFFECT ON PLANT [B] (20)

SHUTDOWN METHOD [Z] (21)

HOURS [0] [0] [0] [2]

ATTACHMENT SUBMITTED [Y] (22)

NPRO-4 FORM SUB. [N] (24)

PRIME COMP. SUPPLIER [L] (25)

COMPONENT MANUFACTURER [C] [5] [3] [0] (26)

1 0 System contamination fouled pressure regulators as a result of system op  
1 1 eration during recent refueling outage. A was returned to service by cor  
1 2 rective maintenance. B returned following receipt of new regulators - A  
1 3 regulators also replaced. Tech Spec change to credit PASS monitoring bei  
1 4 ng prepared.

7 8 3

FACILITY STATUS 1 5 E 28

% POWER 10 9 4 29

OTHER STATUS 30 NA

METHOD OF DISCOVERY B 31

DISCOVERY DESCRIPTION 32 Cal problems during surveillance

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NA

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (38)

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	?	0	0	0	37	Z	38	NA	39

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	4	0	0
0	0	0	0
40		NA	41

1		2		3		4		5		6		7		8		9		10		11		12	
LOSS OF OR DAMAGE TO FACILITY												(43)											
TYPE												DESCRIPTION											
1		3		Z		(42)		NA															

8 9 10 30  
PUBLICITY  
ISSUED DESCRIPTION (45)  
2 0 UN (44) NA  
8306170337 830610  
PDR ADOCK 05000331  
S PDR  
NRC USE ONLY

PHONE: 319-851-7238

Iowa Electric Light and Power Company  
June 10, 1983  
DAEC-83- 427

Mr. James G. Keppler  
Regional Administrator  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Subject: Licensee Event Report No. 83-021  
(14 day)

File: A-118a, TE-2

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications, Section 6.11.2.a(2), and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report.

As noted in the attached LER, reactor shutdown was initiated in accordance with DAEC Technical Specification 3.7.a.6(c) at 1346 hours on May 27, 1983, when with one division of H<sub>2</sub>O<sub>2</sub> analyzer serving containment inoperable, the second division experienced operability problems. The controlled shutdown was terminated at 1630 hours when one division was returned to operable status. Although this report is being classified as a 14 day LER (since a parameter was less conservative than the least conservative aspect of the LCO) the DAEC technical specifications do not credit the recently installed post accident sampling system (PASS). The PASS system was operable throughout the periods of inoperability of the H<sub>2</sub>O<sub>2</sub> analyzers and provides the capability to obtain and analyze in less than one hour containment and torus atmosphere H<sub>2</sub> and O<sub>2</sub> concentrations. We anticipate revising the DAEC technical specifications to reflect the redundancy of the PASS system to the H<sub>2</sub>O<sub>2</sub> analyzers and negate the need for shutdown or an LER should the above circumstances repeat themselves.

Very truly yours,

*BR York for*

Daniel L. Mineck  
Plant Superintendent - Nuclear  
Duane Arnold Energy Center

DLM/WJM/pf  
Docket 50-331  
attachment

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector - DAEC

JUN 13 1983

IE22  
11

DUANE ARNOLD ENERGY CENTER

Iowa Electric Light and Power Company

Licensee Event Report - Supplemental Data

Docket No. 050-0331

Licensee Event Report Date: 6-10-83

Reportable Occurrence No: 83-021

Description of Event

On May 21, 1983, channel B of the DAEC H<sub>2</sub>O<sub>2</sub> analyzers serving containment and torus atmosphere was declared inoperable. In accordance with DAEC technical specification 4.7.A.6.c., operability testing of the Channel A H<sub>2</sub> and O<sub>2</sub> analyzers was increased in frequency. While performing calibration of the A channel on May 27, 1983, difficulties were experienced in calibration of the A channel. Investigation revealed that pressure regulators within the A channel were fouling due to contamination by particulate matter. In accordance with DAEC specification 3.7.A.6.c, a controlled shutdown was initiated at 1346 hours on May 27, 1983. This controlled shutdown was terminated at 1630 hours when division A was returned to operable status following cleaning of the regulators and successful performance of the surveillance test procedure for the A H<sub>2</sub>O<sub>2</sub> analyzer.

Cause of Event

As noted above, contamination entered the H<sub>2</sub>O<sub>2</sub> analyzer system during the recent refueling outage. This contamination was caused by particulate matter from outage activities such as painting, welding, and grinding. The contamination eventually collected in the regulators resulting in slow deterioration of system response.

Corrective Action

The A analyzer was returned to operable status following minor maintenance on the regulator. The B channel was returned to operable status following replacement of regulators several days later. The Post Accident Monitoring System (PASS) which is not currently credited in DAEC technical specifications provided redundant diverse indication of containment and torus atmosphere H<sub>2</sub> and O<sub>2</sub> concentrations. Upon returning the A system to service on May 27, 1983, the PASS system and H<sub>2</sub>O<sub>2</sub> analyzers demonstrated excellent agreement on sample test results. DAEC Technical Specifications under review in anticipation of a proposed technical specification amendment to credit the PASS system capabilities.