

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 N Y I P S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
8 9 14 15 25 26 57 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

N/T
1 L 6 0 5 0 0 0 2 4 7 7 0 4 2 2 8 3 8 0 5 2 2 8 3 9
60 61 68 69 74 75 80
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
2 During power reduction, Boron Injection Tank (Tech. Spec. 3.3.A) level channel 944F
3 became inoperable. There was no adverse effect on the public's health and safety
4 since two redundant channels remained functional. Similar events LER 82-12, LER 82-23,
5 LER 82-27.
6 _____
7 _____
8 _____

SYSTEM CODE S F 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE T 15 VALVE SUBCODE Z 16
9 10 11 12 13 18 19 20
 LER/RO REPORT NUMBER 8 3 21 22 SEQUENTIAL REPORT NO. 0 1 6 24 26 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 REVISION NO. 0 32
17 21 22 23 24 26 27 28 29 30 31 32
 ACTION TAKEN B 33 FUTURE ACTION F 34 EFFECT ON PLANT Z 35 SHUTDOWN METHOD Z 36 HOURS 0 0 0 37 40 ATTACHMENT SUBMITTED N 41 NPD-4 FORM SUB. Y 42 PRIME COMP. SUPPLIER N 43 COMPONENT MANUFACTURER B 0 8 0 44 47 25
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
0 Solidification of boric acid in instrument impulse line resulted in erroneous indication
1 of level. The affected impulse line was cleared and the channel returned to service.
2 An engineering evaluation of the associated heat tracing is underway.
3 _____
4 _____

FACILITY STATUS F 28 % POWER 0 8 9 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32
8 9 10 12 13 44 45 46 80
 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
8 9 10 11 44 45 80
 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE NA 38 DESCRIPTION NA 39
8 9 11 12 13 80
 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
8 9 11 12 80
 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
8 9 10 80
 PURITY CITY NA 44 DESCRIPTION NA 45
8 9 10 80
 ISSUED N 44

8306170397 830522
 PDR ADOCK 05000247
 S PDR

7522

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

May 22, 1983

Re: Indian Point Unit No. 2
Docket No. 50-247
LER-83-016/03L-0


Mr. James M. Allan,
Acting Regional Administrator-Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. Allan:

The attached Licensee Event Report LER-83-016/03L-0 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.7. This event is of the type described in Technical Specification 6.9.1.7.2.b.

Three copies of this letter and attachment are enclosed as required.

Very truly yours,



attach.

cc:

Mr. Richard DeYoung, Director (30 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. William G. McDonald, Director (3 copies)
Office of Management Information and Program Control
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Thomas Foley, Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

IE22
11