

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M A P P S I												2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE												14	LICENSE NUMBER												25	LICENSE TYPE				30	CAT 56			

CON'T

REPORT SOURCE L 6 05 0 - 0 2 9 3 7 0 5 1 8 8 3 8 0 6 1 6 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a routine inspection, a folding fire door was found to be not completely
0 3 | operable. A fire patrol required by T.S. 3.12.F was initiated immediately.

0 4 | The door was in its actuated (closed) position at the time of this event.

0 5 | This event caused no threat to the public health and safety. The door was
0 6 | supplied by Bolton Gate Co., Ltd.; Bolton, England.

0 7 |

0 8 |

SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE						COMP. SUBCODE	VALVE SUBCODE		
0	9	A	B	E	E	X	X	X	X	X	X	Z	Z
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
17	8	3	—	0	2	7	—	0	3	L	—	0	
21	22	23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS		ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
B	E	Z	Z	0	0	0	N	N	X	X	9	9	9
33	34	35	36	37	38	39	40	41	42	43	44	45	46

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Slack in the operating cable allowed the cable to become detached from the
1 1 pulley. The cable was re-attached, the operating mechanism adjusted, and the
1 2 door tested satisfactorily. It is believed the adjustment will prevent a
1 3 recurrence of the event.
1 4

FACILITY STATUS (1) 5 (2) E (28) 0 9 9 (29) N/A (30) METHOD OF DISCOVERY (31) B Routine inspection (32) DISCOVERY DESCRIPTION
 ACTIVITY CONTENT RELEASED OF RELEASE (33) Z (34) N/A (35) AMOUNT OF ACTIVITY (36) LOCATION OF RELEASE
 N/A

PERSONNEL EXPOSURE NUMBER		TYPE		DESCRIPTION
1	7	0	0	N/A

PERSONNEL INJURIES		NUMBER		DESCRIPTION		(41)	
1	8	0	0	0	(40)	N/A	

7 8 9 11 12
LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43)
1 9 Z (42) N/A
8307010134 830616
PDR ADOCK 05000293
S PDR

PUBLICATION		ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	44	N/A			

NAME OF PREPARER G. G. Whitney

PHONE: (617) 746-7900

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

June 16, 1983

BECO. Ltr. #83-155

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406


Docket No. 50-293
License DPR-35

Dear Sir:

The attached Licensee Event Report 83-027/03L-0, "Folding Fire Door" is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.b.

If there are any questions on this subject, please contact us.

Respectfully submitted,



William D. Harrington

WDH/tg

Enclosure: LER 83-027/03L-0

cc: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Standard BECo. LER distribution

HE22
11