

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58	

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	6	6	7	0	6	0	3	8	3	8	0	6	2	8	8	3	9
60	61									68	69						74	75						80
DOCKET NUMBER											EVENT DATE						REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	During performance of the "HONEYWELL CONTROLLER MODEL 806" procedure
0	3	(HNP-2-5622), personnel noted that the hydrogen recombiner controllers
0	4	(2T49-R601 A&B, 2T49-R602 A&B and 2T49-R603 A&B) were out of calibration.
0	5	This event is contrary to the requirements of Tech. Specs. section
0	6	4.6.6.2.b.1. The recombiners were not required to be operable at this
0	7	time because the unit was in cold shutdown. The health and safety of
0	8	the public were not affected by this non-repetitive event.

09		SYSTEM CODE 12		CAUSE CODE E12		CAUSE SUBCODE E13		COMPONENT CODE INSTRU14						COMP. SUBCODE C15		VALVE SUBCODE Z16	
17		LER/RO REPORT NUMBER 83		EVENT YEAR 83		SEQUENTIAL REPORT NO. 037		OCCURRENCE CODE 03		REPORT TYPE 1		REVISION NO. 0					
ACTION TAKEN A18		FUTURE ACTION Z19		EFFECT ON PLANT Z20		SHUTDOWN METHOD Z21		HOURS 0600		ATTACHMENT SUBMITTED Y23		NPRD FORM SUB. N24		PRIME COMP. SUPPLIER A25		COMPONENT MANUFACTURER A53026	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Controllers 2T49-R603 A&B were out of calibration due to setpoint drift.
1	1	Controllers 2T49-R601 A&B and 2T49-R602 A&B were out of calibration due
1	2	to miscellaneous failed parts. Controllers 2T49-R603 A&B were re-cali-
1	3	brated per HNP-2-5622. Controllers 2T49-R601 A&B and 2T49-R602 A&B were
1	4	repaired and then calibrated per HNP-2-5622.

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	5	H	28	0	0	0	29	NA				B	31	Surveillance Testing					
ACTIVITY CONTENT				RELEASED OF RELEASE				AMOUNT OF ACTIVITY				LOCATION OF RELEASE							
1	6	Z	33	Z	34			NA				NA							
PERSONNEL EXPOSURES				PERSONNEL INJURIES				LOSS OF OR DAMAGE TO FACILITY				<div style="text-align: center;"> <p>IE22</p> <p>11</p> </div>							
NUMBER				NUMBER				TYPE											
1	7	0	0	0	37	Z	38	NA											
PUBLICITY				ISSUED				PDR ADOCK				NRC USE ONLY							
2	0	N	44					S											

NAME OF PREPARER S. B. Tipps

PHONE: (912) 367-7851

NARRATIVE REPORT  
FOR LER 50-366/1983-037

LICENSEE : GEORGIA POWER COMPANY  
FACILITY NAME : EDWIN I. HATCH  
DOCKET NUMBER : 50-366

Tech. Specs. section(s) which requires report:

This 30-day LER is required by Tech. Specs. section 6.9.1.9.b due to the event's showing that the unit was not meeting the requirements of Tech. Specs. section 4.6.6.2.b.1.

Plant conditions at the time of the event(s):

This event occurred on 06/03/83 with the unit in cold shutdown for a refueling outage.

Detailed description of the event(s):

On 06/03/83, during performance of the "HONEYWELL CONTROLLER MODEL 305" procedure (HNP-2-5622), personnel noted that the hydrogen recombiner controllers (2T49-R601 A&B, 2T49-R602 A&B and 2T49-R603 A&B) were out of calibration.

Consequences of the event(s):

The plant was in cold shutdown for a refueling outage when this event was discovered. Thus, the hydrogen recombiners were not required to be operable. The health and safety of the public were not affected by this event.

Status of redundant or backup subsystems and/or systems:

There is no backup system.

Justification for continued operation:

None required - the hydrogen recombiners are not required to be operable with the unit in cold shutdown.

If repetitive, number of previous LER:

This is a non-repetitive event.

Narrative Report for LER 50-366/1983-037  
Page Two

Impact to other systems and/or Unit:

This event had no effect on any other Unit 2 system. This event had no effect on Unit 1.

Cause(s) of the event(s):

Controllers 2T49-R603 A&B were found to be out of calibration due to setpoint drift. Controllers 2T49-R601 A&B and 2T49-R602 A&B were found to be out of calibration due to miscellaneous failed parts.

Immediate Corrective Action:

Controllers 2T49-R603 A&B were recalibrated by HNP-2-5622. Controllers 2T49-R601 A and 2T49-R602A were repaired by replacing the controllers. Controllers 2T49-R601B and 2T49-R602B were repaired by replacing the failed characterizer boards. After the necessary repairs were made, the hydrogen recombiner controllers were calibrated by the HNP-2-5622 procedure and returned to service on 06/20/83.

Supplemental Corrective Action:

No supplemental corrective action is required.

Scheduled (future) corrective action:

No future corrective action is required.

Action to prevent recurrence (if different from corrective actions):

N/A

Georgia Power Company  
Post Office Box 439  
Baxley, Georgia 31513  
Telephone 912 367-7781  
912 537-9444

USNRC REGION II  
ATLANTA, GEORGIA



Georgia Power

83 JUL 8 49:52  
Edwin I. Hatch Nuclear Plant


June 28, 1983  
GM-83-590

PLANT E. I. HATCH  
Licensee Event Report  
Docket No. 50-366

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Pursuant to Section 6.9.1.9.b of Hatch Unit 2 Technical  
Specifications, please find attached Reportable Occurrence  
Report No. 50-366/1983-037.

  
H. C. Nix  
General Manager

*SB1*  
HCN/SBT/amh

xc: R. J. Kelly  
G. F. Head  
J. T. Beckham, Jr.  
P. D. Rice  
K. M. Gillespie  
S. B. Tipps  
R. D. Baker  
Control Room  
Document Control

~~OFFICIAL COPY~~

JE22

1/1