

3150-0011

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	P	A	S	E	S	I	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9	LICENSE CODE						14	15	LICENSE NUMBER								25	26	LICENSE TYPE				30	37	CAT 39	

CON'T

01 REPORT SOURCE L 05000387705258380624839

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While maintenance was being performed on the Turbine Building side of the air lock

0 3 | to the Reactor Building, the Reactor Building door was open. This resulted in a

0 4 | momentary loss of secondary containment. There were no occurrences which could

0 5 | have had consequential effects to public health and safety.

0 6 |

0 7 |

0 8 |

09		SYSTEM CODE S A		(11)	CAUSE CODE A		(12)	CAUSE SUBCODE X		(13)	COMPONENT CODE Z Z Z Z Z Z						(14)	COMP. SUBCODE Z		(15)	VALVE SUBCODE Z		(16)
7	8	9	10		11		12	13	14	15	16	17	18	19	20	21	22	23	24	25	26		
(17) LER/RO REPORT NUMBER		EVENT YEAR 8 3			SEQUENTIAL REPORT NO. 0 8 6			OCCURRENCE CODE /			REPORT TYPE L			REVISION NO. 0									
		21	22	23	24	25	26	27	28	29	30	31	32										
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER														
H	Z	Z	Z	0000	N		N	Z	Z999														
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The personnel who exited the Reactor Building did not follow the airlock lights

1 1 which indicated the Turbine Building door was open. An individual with radio

1 2 communication was placed inside the Reactor Building to provide for greater con-

1 3 trol. Typical maintenance on door requires one-half hour, for future jobs an

1 4 individual with radio communication will be posted.

FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 B (28) 0 C 8 (29) NA A (31) Observation

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 34

7 8 9 10 11 44

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPOSURES										
NUMBER			TYPE		DESCRIPTION					
1	7	0	0	37	Z	38	NA			

PERSONNEL INJURIES									
NUMBER				DESCRIPTION					
1	8	0	0	0	40	NA			
7	8	9	0	1.1	1.2				

IEZZ

LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43)

1 9 Z (42) NA

7 8 9 10

ISSUED PUBLICITY DESCRIPTION (45)
 2 0 N (44) _____
 7 8 9 10

8307120442 830624
 PDR ADDCK 05000387
 S PDR

NRC USE ONLY
 _____ 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER A.P. Piemontese

PHONE (717) 542-2181



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

June 24, 1983

Mr. J.M. Allan
Acting Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 83-086/03L-0
ER 100450 FILE 841-23
PLA-1730

Docket No. 50-387
License No. NPF-14

Dear Mr. Allan:

Attached please find a copy of Licensee Event Report No. 83-086/03L-0. This event was determined to be reportable per Technical Specification 6.9.1.9.b, in that while performing maintenance on Turbine Building door on airlock to Reactor Building, personnel exited through the Reactor Building door.

H.W. Keiser
Superintendent of Plant-Susquehanna

APP/pjg

cc. G.G. Rhoads
Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

11 IE22