

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

June 29, 1983
G01-83-343

Nuclear Regulatory Commission
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596

Attention: D.M. Sternberg, Chief
Reactor Projects Branch No. 1

Subject: NUCLEAR PROJECT NOS. 1 & 4
DOCKET NOS. 50-460 AND 50-513
POTENTIALLY REPORTABLE CONDITION 10CFR50.55(e)
EMERGENCY DIESEL GENERATOR STARTING AIR VALVE ASSEMBLY


Reference: A) Telecon CR Edwards, Supply System to PP Narbut; dated
6/18/82.
B) G01-82-0436, same subject, dated July 16, 1982.

In reference A) the Supply System informed your office of a potentially reportable condition under the provisions of 10CFR50.55(e) and Reference B was an interim report on the subject condition. Attachment A has been updated to identify that the design change has been documented but is not yet implemented.

As described in the attachment, the Supply System will take the most conservative approach and replace the capscrews. As a result, the reportability status of this potential defect will remain indeterminate.

Due to the current construction delay on WNP-1, the Supply System will not be able to implement the required hardware modifications and issue a final report. As a result the Supply System will provide the next interim report at construction restart.

If you have any questions or desire further information, please advise.



R.A. De Lorenzo
WNP-1 Program Director (821)

RAD/LCO/cmh

Attachment

cc: CR Bryant, BPA (399)
TA Mangelsdorf, Bechtel (861)
V Mani, UE&C (897)
V Stello, Director of Inspection, NRC
FDCC (899)
ORM (847)
A. Toth, NRC

8307120499 830629
PDR ADOCK 05000460
S PDR

11 IE-27

WNP-1/4

DOCKET NOS. 50-460 & 50-513

REPORTABLE CONDITION PER 10CFR50.55(e)
EMERGENCY DIESEL GENERATOR STARTING AIR VALVE ASSEMBLY

BACKGROUND

The Supply System purchased Emergency Diesel Generators, two per plant, from Transamerica Delaval. Transamerica Delaval has reported under the requirements of 10CFR Part 21, a deficiency associated with the starting air valve assembly, which is described in detail under "Description of the Deficiency".

The starting air valve assembly was manufactured and installed in the cylinder head by Transamerica Delaval.

Following receipt of the 10CFR Part 21 notification from Transamerica Delaval, Supply System Contract 53, it was determined that this deficiency was potentially reportable under the requirements of 10CFR50.55(e).

DESCRIPTION OF THE DEFICIENCY

The design deficiency is related to the length of the capscrew which holds the starting air valve assembly in the cylinder head.

If all dimension tolerances are stacked in one direction, the installed clearance is less than desirable.

SAFETY IMPLICATIONS

If the capscrew bottoms out in the tapped hole in the cylinder head before the assembly is properly seated, the torque wrench reading would be misleading and the assembly could fail.

CORRECTIVE ACTION

Transamerica Delaval has revised the design configuration to specify capscrews 2-3/4" long rather than 3" long. A 1/4" shorter capscrew still gives adequate thread engagement and eliminates any possibility that the capscrew will bottom out in the tapped hole.

For our Emergency Diesel Generators the 3" capscrews will all be removed and replaced with the 2-3/4" capscrews. This change will be accomplished at the site through a field change (QFPCP 01Q25231).

Based on the current WNP-1 construction delay the procurement and installation of the shorter capscrews will not take place until after construction is resumed.

Tracking of the deficiency and correction of the WNP-4 equipment has been assured by generation of a nonconformance report against the hardware (4-BNCR-53-02).