

PREVIOUS REPORT ISSUED ON 2/22/79

NRC FORM 366
(12-81)
10 CFR 50

U.S. NUCLEAR REGULATORY COMMISSION
LICENSEE EVENT REPORT

APPROVED BY OMB
3150-0011

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	A	P	P	S	1	2	0	0	5	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	LICENSE NUMBER											25	LICENSE TYPE				30	57 CAT 58			

CON'T

REPORT SOURCE L 6 0 5 0 - 0 2 9 3 7 0 2 1 2 7 9 8 0 6 2 1 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On 2/12/79 while performing surveillance test 8.7.4.3, Test (Open and Close) Isolation Valves Except MSIVs, the following valves failed to give proper position indication when cycled. AO-5033A, CV-5065-10, 16 & 17, CV-5065-15 failed to close within the specified tolerance. A similar occurrence was reported in LER 78-046/03L-0.

0	8		8 C
---	---	--	-----

0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

S D 11 X 12 X 13 V A L V E X 14 X 15 0 16

17	LER/RO REPORT NUMBER	EVENT YEAR			SEQUENTIAL REPORT NO.			OCCURRENCE CODE		REPORT TYPE			REPORT NO.									
		7	9		0	0	7	/	0	3	X		1									
		21	22	23	24	25	26	27	28	29	30	31	32									
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						
E	18	G	19	Z	20	Z	21	0	0	0	0	N	23	N	24	A	25	M	3	0	2	26
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Investigation revealed that the situation was not an alignment problem. Each valve was cycled several times and operated properly. Proper indication was verified as each valve was subsequently cycled. The surveillance frequency for these valves has been increased from quarterly to monthly with the exception of AO-5033-A valve which was satisfactorily repaired on 5/24/79.

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION							
1	5	E	28	1	0	0	29	N/A	B	31	Surveillance Test	32

ACTIVITY CONTENT RELEASED OF RELEASE		AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	6	Z	33
Z	34	N/A	N/A

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	N/A	

PERSONNEL INJURIES		DESCRIPTION (41)	
NUMBER			
18	0000	(40)	N/A

1		2		3		4		5		6		7		8		9		10		11		12	
LOSS OF OR DAMAGE TO FACILITY																							
TYPE		DESCRIPTION																					
1	9	Z	(42)	N/A																			

IE 22
41

PUBLICITY		ISSUED		DESCRIPTION		(45)		NRC USE ONLY									
2	0	N	(44)	N/A													

NAME OF PREPARER

G. G. Whitney

PHONE: (617) 746-7900

8307120507 830621
PDR ADCK 05000293
S PDR

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

June 21, 1983

BECO. Ltr. #83-132

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Docket No. 50-293
License DPR-35


Dear Sir:

The attached Update Licensee Event Report 79-007/03X-1 "Oxygen Analyzer Valves", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.b.

As a result of an internal audit to very completion of corrective actions, it was recently determined that committed actions associated with AO-5033A were rescinded shortly after issuance of the original LER. This update report serves to clarify actual corrective actions.

If there are any questions on this subject, please contact us.

Respectfully submitted,



William D. Harrington

WDH/mg

Enclosure: Update LER 79-007/03X-1

cc: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Standard BECO. LER distribution

11 IE22