

LICENSEE EVENT REPORT

Attachment to AECM-83/0366

Page 1 of 1

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | S | G | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | # | 5

7 8 9 14 15 25 26 30 57 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CONT

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 4 | 1 | 6 | 7 | 0 | 6 | 0 | 7 | 8 | 3 | 8 | 0 | 6 | 2 | 7 | 8 | 3 | 9

7 8 60 61 66 67 74 75 80

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On June 7, 1983, the shutdown cooling mode of RHR isolated when

0 3 | isolation valve E12-F009 closed due to a blown fuse (1C71-F36 in panel

0 4 | 1H13-P693). This event resulted in entering the action statement of

0 5 | T.S.3.4.9.2 and is being reported pursuant to T.S.6.9.1.13.b. The event

0 6 | had no affect on the health and safety of the public and did not

0 7 | constitute a threat to plant safety.

0 8 |

7 8 9 80

0 9 |

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

LER RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This event was caused by a blown fuse. The fuse was replaced in 53

1 1 | minutes and the shutdown cooling mode of RHR was placed in operable

1 2 | status per T.S.3.4.9.2. This event occurred during normal operation of

1 3 | the system and no further corrective action is considered necessary.

1 4 | This is a final report.

1 5 |

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

PERSONNEL INJURIES NUMBER DESCRIPTION

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

PUBLICITY ISSUED DESCRIPTION

ISSUED DESCRIPTION

6307120592 830627
PDR ADOCK 05000416
S PDR

NRC USE ONLY

NAME OF PREPARER David Black

PHONE



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

June 27, 1983

JAMES P. MCGAUGHY, JR.
VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Shutdown Cooling Mode of RHR
Isolated
LER 83-071/03 L-0
AECM-83/0366

On June 7, 1983, the shutdown cooling mode of RHR isolated when isolation valve E12-F009 closed due to a blown fuse (1C71-F36 in panel 1H13-P693). This event resulted in entering the action statement of Technical Specification 3.4.9.2 and is being reported pursuant to Technical Specification 6.9.1.13.b. Attached is LER 83-071/03 L-0.

Yours truly,

L. F. DeYoung
for J. P. McGaughy

JPM:sap
Attachment

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Connor (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY