

U.S. NUCLEAR REGULATORY COMMISSION  
LICENSEE EVENT REPORTAPPROVED BY OMB  
3150-0011  
EXPIRES 4-30-82

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | S | C | V | C | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 4 | 0 | 0 | 0 | 4 | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE 57 CAT 58

CONT

01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 9 | 5 | 7 | 0 | 6 | 0 | 3 | 8 | 3 | 8 | 0 | 7 | 2 | 9 | 8 | 3 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | With the Plant in Mode 1, the "A" Emergency Diesel Generator was connected to  
03 | Vital Bus 1DA and loaded to 4250kw during its operability surveillance test. The  
04 | normal 115kv power supply to the vital bus was lost and the diesel generator out-  
05 | put breaker tripped open. The diesel was shut down and locked out by a phase  
06 | differential relay, thereby losing all A.C. power input to the vital bus. No  
07 | adverse consequences resulted as the redundant vital bus remained operable for  
08 | plant safeguards.

09 | SYSTEM CODE | E | A | 11 | CAUSE CODE | C | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | Z | Z | Z | Z | Z | Z | 14 | COMP. SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
LER/RO REPORT NUMBER | 8 | 3 | 17 | SEQUENTIAL REPORT NO. | 0 | 7 | 4 | 18 | OCCURRENCE CODE | 0 | 3 | 19 | REPORT TYPE | L | 20 | REVISION NO. | 0 | 31  
ACTION TAKEN | E | 18 | FUTURE ACTION | F | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NRC-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | Z | 25 | COMPONENT MANUFACTURER | Z | 9 | 9 | 9 | 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The event was caused by an electrical surge from a lightning storm. The surge  
11 | tripped: 1) The normal power feed breaker for Vital Bus 1DA open on over-  
12 | current. 2) The diesel generator output breaker open on overcurrent and phase  
13 | differential. The licensee will evaluate additional surge suppression circuitry  
14 | to protect the diesel generator circuitry.

15 | FACILITY STATUS | E | 28 | % POWER | 0 | 9 | 5 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator Observation | 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | N/A | 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 | PUBLICITY ISSUED DESCRIPTION | N | 44 | 8308080001 830729  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PDR ADOCK 05000395  
S PDR

NAME OF PREPARER

H. C. Fields

PHONE: (803) 345-5209

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.  
VICE PRESIDENT  
NUCLEAR OPERATIONS

July 29, 1983

USNRC REGION III  
ATLANTA, GEORGIA

83 AUG 3 A10:12

Mr. James P. O'Reilly  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region II, Suite 2900  
101 Marietta Street, N.W.  
Atlanta, Georgia 30303


SUBJECT: Virgil C. Summer Nuclear Station  
Docket No. 50/395  
Operating License No. NPF-12  
Thirty Day Written Report  
LER 83-074

Dear Mr. O'Reilly:

Please find attached Licensee Event Report #83-074 for Virgil C. Summer Nuclear Station. This Thirty Day Report is required by Technical Specification 6.9.1.13.(b) as a result of entry into Action Statement (b) of Technical Specification 3.8.1.1, "Electrical Power Systems, A.C. Sources," and Action Statement (a) of Technical Specification 3.8.3.1, "Electrical Power Systems, Onsite Power Distribution," on July 3, 1983.

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

HCF:OWD/mac/fjc  
Attachment

cc: V. C. Summer  
E. H. Crews, Jr.  
T. C. Nichols, Jr., /O. W. Dixon, Jr.  
E. C. Roberts  
H. N. Cyrus  
Group/General Managers  
O. S. Bradham  
R. B. Clary  
C. A. Price  
A. R. Koon  
D. A. Lavigne

C. L. Ligon (NSRC)  
G. J. Braddick  
J. C. Miller  
J. L. Skolds  
J. B. Knotts, Jr.  
I&E (Washington)  
Document Management  
Branch  
INPO Records Center  
NPCF  
File (Lic./Eng.)

OFFICIAL COPY

IE 22 11

Mr. James P. O'Reilly  
LER No. 83-074  
Page Two  
July 29, 1983

#### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

At 2315 hours on July 3, 1983, the Plant was operating in Mode 1. The "A" Emergency Diesel Generator (XEG001A) was connected to Engineered Safety Feature (ESF) Bus 1DA and was loaded to 4250kw for the performance of an operability surveillance test. A lightning storm caused an electrical surge on the 115kv offsite power source for ESF Bus 1DA which tripped OCB 1802 (located at the source of the 115kv line) open on overcurrent. Simultaneously, the power surge caused the XEG001A output breaker to trip open on both "overcurrent" (51VDG relay) and "phase differential" (87DGA relay). This de-energized ESF Bus 1DA and shutdown the diesel due to the actuation of the phase differential relay.

The Engineered Safety Features Load Sequencer (ESFLS) actuated in response to the dead bus and sequenced through Output #7, which opened both the Normal and Alternate offsite power supply breakers for ESF Bus 1DA. At this step, the ESFLS stopped sequencing because XEG001A was shutdown and locked out by the phase differential trip. OCB 1802 automatically reclosed and re-energized the 115kv line. However, the ESFLS had locked out the Normal and Alternate Power Supply Breakers and prevented their reclosure from the Main Control Board. ESF Bus 1DA remained de-energized until 0025 hours, July 4, 1983, for a total time of one hour and ten minutes. By this time, all lockouts had been reset and the Normal offsite power supply breaker was closed to energize ESF Bus 1DA.

During the period that ESF Bus 1DA was inoperable, all Train "B" ESF systems remained operable and the minimum number of systems required for safe plant shutdown, as evaluated in the Accident Analysis, was satisfied. No adverse consequences to the safety of the public or the plant resulted from this event.

#### CORRECTIVE ACTION

Due to the loss of ESF Bus 1DA, Technical Specification 3.8.3.1, Action Statement (a), was applied. Power was restored prior to the fourteen (14) hour time limit for proceeding to cold shutdown. Technical Specification 3.8.1.1, Action Statement (b), was also applied. An electrical alignment verification for the "B" train ESF had just been completed at 2200 hours on July 3, 1983. The "B" Diesel Generator Operability Test had been completed at 2232 hours, July 3, 1983.

Mr. James P. O'Reilly  
LER No. 83-074  
Page Three  
July 29, 1983

CORRECTIVE ACTION - Continued

Component Cooling Water Train A (powered by LDA) was supplying Reactor Coolant Pump cooling water. Component Cooling Water Train B was started and cooling water was restored to the Reactor Coolant Pump in less than ten (10) minutes.

Defective parts in XEG-001A were repaired and the equipment was declared operable at 0820 hours, July 5, 1983, after the satisfactory performance of the applicable surveillance procedure.

The Licensee plans to evaluate the need for developing additional surge suppression circuitry to protect the emergency diesel generator circuitry from lightning induced surges. This evaluation will be completed by October 31, 1983. Any resulting modifications will be implemented upon design approval and material procurement.