

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

REPORT SOURCE L 6 0 5 0 0 0 3 9 5 7 0 7 0 7 8 3 8 0 8 0 1 8 3 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

0 2 | On July 7, 1983, at 0300 hours, with the Plant in Mode 1, Pressurizer Power

0 3 | Operated Relief Valve PCV-444B-RC would not fully stroke when operated from the

0 4 | Main Control Board. The low pressure Nitrogen reservoir for PCV-444B-RC would

0 5 | not charge up to normal pressure. There were no adverse consequences as the

0 6 | Plant was in compliance with Technical Specification 3.4.4, Action Statement (a)

0 7 | and the Pressurizer Code Safety Valves were OPERABLE.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)	
1	0
1	1
1	2
1	3

Nitrogen Supply Header Pressure Control Valve (IPV-6307B) and Nitrogen Supply Header Isolation Valve (XVX-6309B), both for PORV PCV-444B-RC, will be inspected and repaired/adjusted, as necessary, when plant conditions permit. At that time, a follow-up report will be made indicating actual cause and corrective actions.

1	4		
7	8	9	10
FACILITY STATUS		POWER	OTHER STATUS (30)
1	5	B (28)	096 (29)
		METHOD OF DISCOVERY	
		A (31)	DISCOVERY DESCRIPTION (32)
		Operator Observation	

ACTIVITY CONTENT RELEASED OF RELEASE (33) (34) AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 2 N/A N/A

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION					
1	7			37	38	N/A			

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	40	N/A

7	8	9	11	12
LOSS OF OR DAMAGE TO FACILITY				
TYPE		DESCRIPTION		
			(43)	N/A

1 9 42 1.0 8308080229 830801

ISSUED PUBLICITY DESCRIPTION (45) PDR ADCK 05000395 PDR NRC USE ONLY

2 0 44 *L E K* (803) "345-5209 TC22"

NAME OF PREPARER L. E. Kolb

PHONE: 1E00

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

USNRC REGION II
ATLANTA, GEORGIA

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

August 1, 1983

83 AUG 3 A10:12

Mr. James P. O'Reilly
Regional Administrator
U.S. Nuclear Regulatory Commission
Region II, Suite 2900
101 Marietta Street, N.W.
Atlanta, Georgia 30303


SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
Thirty Day Written Report
LER 83-076

Dear Mr. O'Reilly:

Please find attached Licensee Event Report #83-076 for Virgil C. Summer Nuclear Station. This Thirty Day Report is required by Technical Specification 6.9.1.13.(b) as a result of entry into Action Statement (a) of Technical Specification 3.4.4, "Relief Valves," on July 7, 1983.

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

LEK:OWD/mac/fjc
Attachment

cc: V. C. Summer
E. H. Crews, Jr.
T. C. Nichols, Jr., / O. W. Dixon, Jr.
E. C. Roberts
H. N. Cyrus
Group/General Managers
O. S. Bradham
R. B. Clary
C. A. Price
A. R. Koon
D. A. Lavigne
J. L. Heilman

C. L. Ligon (NSRC)
G. J. Braddick
J. C. Miller
J. L. Skolds
J. B. Knotts, Jr.
I&E (Washington)
Document Management
Branch
INPO Records Center
NPCF
File (Lic./Eng.)

OFFICIAL COPY
ZE 22
1/1

Mr. James P. O'Reilly
LER No. 83-076
Page Two
August 1, 1983

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

On July 7, 1983, at 0300 hours, with the Plant in Mode 1, Pressurizer Power Operated Relief Valve (PORV) PCV-444B-RC would not fully stroke when operated from the Main Control Board. The low pressure Nitrogen reservoir for PCV-444B-RC would not charge up to normal pressure. Within ten (10) minutes, the block valve for PCV-444B-RC (XVG-8000B) was closed and power removed.

Technical Specification 3.4.4, Action Statement (a), requires that with one (1) or more PORV(s) inoperable, within one (1) hour either restore the PORV(s) to OPERABLE status or close the associated block valve(s) and remove power from the block valve(s); otherwise, be in at least HOT STANDBY within the next six (6) hours and in COLD SHUTDOWN within the following thirty (30) hours. Technical Specification 3.4.4 is applicable in Modes 1, 2, and 3.

There were no adverse consequences as the Plant was in compliance with the applicable Technical Specification Action Statement and the Pressurizer Code Safety Valves were OPERABLE.

CAUSE AND CORRECTIVE ACTIONS

Nitrogen Supply Header Pressure Control Valve (IPV-6307B) and Nitrogen Supply Header Isolation Valve (XVX-6309B), both for PORV PCV-444B-RC, will be inspected and repaired/adjusted, as necessary, when plant conditions permit. At that time, a follow-up report will be made indicating actual cause and corrective actions as well as action taken to prevent recurrence.