

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 C A S O S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 3 6 2 7 0 7 1 4 8 3 8 0 8 0 1 8 3 9  
7 8 DOCKET NUMBER 55 56 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 1015, with the Unit in Mode 4, a review of an incomplete Abnormal Valve Align-  
03 ment record in the Control Room revealed the possibility that valves MU-075 and  
04 MU-076 were improperly closed during operations to transfer fuel from Diesel Fuel  
05 Storage Tank, T-036 for Diesel Generator (DG) 3G003 to Diesel Fuel Storage Tank,  
06 T-035 for DG 3G002. The valve condition was verified at 1100. This alignment  
07 isolated the normal supply from the respective fuel transfer pumps to each of the  
08 day fuel tanks rendering both diesel generators inoperable. (See attachment).

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
E E 11 A 12 B 13 VALVEX 14 E 15 D 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 LER/RO REPORT NUMBER 8 3 21 22 0 4 6 24 26 0 1 28 29 T 30 31 0 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NRC-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER 26  
X 18 H 19 Z 20 Z 21 0 0 0 0 40 Y 23 N 24 A 25 A 3 9 1 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Inoperability of both diesels was as a result of improper execution of  
11 administrative controls for the Abnormal Valve Alignment required for the  
12 transfer of diesel fuel. Administrative controls include the requirement for  
13 Senior Reactor Operator approval of Abnormal Valve Alignments. The lineup was  
14 instead approved by a nonlicensed operator. (See attachment).

15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32  
B 28 0 0 0 29 NA A 31 Review of valve alignment records

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
Z 33 Z 34 NA NA

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
0 0 0 37 Z 38 NA

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41  
0 0 0 40 NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
Z 42 NA

20 PUBLICITY ISSUED DESCRIPTION 45  
N 44  
8308150081 830801  
PDR ADOCK 05000362  
S PDR

NAME OF PREPARER

H. B. RAY HBRay / NRC  
PHONE: 714/492-7700

ATTACHMENT TO LER 83-046  
SOUTHERN CALIFORNIA EDISON COMPANY  
SAN ONOFRE NUCLEAR GENERATING STATION  
UNIT NO. 3, DOCKET NO. 50-362

SUPPLEMENTAL INFORMATION FOR EVENT DESCRIPTION AND PROBABLE  
CONSEQUENCES

Pursuant to Limiting Condition for Operation (LCO) 3.0.3, as a precautionary measure, cooldown to Mode 5 was immediately initiated while the records were being reviewed. At 1100, an Unusual Event was declared. Public health and safety were not affected.

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION AND CORRECTIVE  
ACTIONS

The valves were correctly aligned and the cooldown and Unusual Event were terminated at 1110. As corrective action, the operator who authorized the incorrect valve lineup has been counseled as to his performance leading to this event and appropriate disciplinary action has been taken. The Operations Superintendent is personally briefing all Operations personnel on the administrative controls pertaining to safety related valves, locked valves and breakers, abnormal valve lineups, and procedural compliance. These briefings will be completed by August 3, 1983. Additionally, these subjects will be part of the normal licensing training and retraining programs.

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 125

SAN CLEMENTE, CALIFORNIA 92072

H. B. RAY  
STATION MANAGER

August 1, 1983

RECEIVED  
NRC

1983 AUG -4 PM 12:36

SCE

REGION VISE

TELEPHONE  
(714) 492-7700

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. J.B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-362  
14-Day Follow-Up Report  
Licensee Event Report No. 83-046  
San Onofre Nuclear Generating Station, Unit 3

Reference: Letter, H. B. Ray (SCE) to J. B. Martin (NRC),  
dated July 15, 1983

The referenced letter provided you with confirmation of our prompt notification of a reportable occurrence involving emergency Diesel Generators.

Pursuant to Section 6.9.1.12.b of Appendix A, Technical Specifications to Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required 14-day follow-up report and copy of the Licensee Event Report (LER) No. 83-046 to address this event.

If there are any questions regarding the above, please contact me.

Sincerely,

*HB Ray / TLM*

Enclosure: LER No. 83-046

IE-22

Mr. J.B. Martin

-2-

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)  
J.P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission  
Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)