

EXHIBIT A

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

REPORT SOURCE 60 DOCKET NUMBER 68 EVENT DATE 74 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

On 8/19/83, while ANO-1 was at 100% full power (FP) and ANO-2 was at 24% FP, maintenance personnel discovered that the wind direction indication at the 40' elevation was indicating 180° from actual wind direction. It is believed that the error existed since the last surveillance which was conducted on 7/20/83. Therefore, since the indication was effectively inoperable for greater than 7 days ANO-2 Technical Specification (T.S.) 3.3.3.4 requires that this occurrence be reported per T.S. 6.9.2. The wind direction indication at 190' level was indicating properly at the time of the occurrence.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP SUBCODE		VALVE SUBCODE				
0	9	I	F	A	12	C	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16
7	8	9	10	11		12		13										

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
1 X 18	1 X 19	1 Z 20	1 Z 21	1 0 1 0 1 0 1 0 1 22	1 Y 23	1 N 24	1 Z 25	1 Z 1 9 1 9 1 9 1 26
33	34	35	36	37 40	41	42	43	44 47

1 0 | DURING MAINTENANCE OF THE 40' WIND DIRECTION EQUIPMENT, THE TRANSMITTER WAS REMOVED FOR REPAIR OF THE MOUNTING
1 1 | BRACKET. WHEN THE TRANSMITTER WAS REPLACED, A MISINTERPRETATION OF THE OUTPUT SIGNAL CAUSED THE TECHNICIAN TO
1 2 | BELIEVE THAT THE TRANSMITTER WAS INSTALLED 180° FROM THE CORRECT POSITION. THIS WAS COMPOUNDED BY THE MOUNTING
1 3 | BRACKET BEING INSTALLED 180° FROM THE ORIGINAL POSITION. AS A RESULT THE TRANSMITTER WAS REMOVED, ROTATED 180°
1 4 | AND RE-INSTALLED. WHEN THE ERROR WAS DISCOVERED, THE TRANSMITTER WAS REMOVED, ROTATED TO ITS CORRECT POSITION
7 8 9

ACTIVITY RELEASED	CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
I Z I33	I Z I34	I NA		I35	I NA	I36
9	10	11		44	45	80

PERSONNEL INJURIES				80
NUMBER		DESCRIPTION		
10	00040	NA		
9	11 12			41
LOSS OF OR DAMAGE TO PROPERTY				80

[illegible]

PHONE: (501) 964-3100

8309080053 830829
PDR ADDCK 05000368
S PDR

LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-368/83-036/04T-0

Occurrence Date: 08/19/83

Cause Description and Corrective Actions (Continued):

and reinstalled. The indication was then verified to be correct. Survey instruments were used to provide a reference bearing line to facilitate transmitter alignment verification. Both the 40' and 190' instruments were aligned to the reference bearing line, secured in place and marked for future reference. To prevent recurrence, procedures will be modified to ensure proper installation of the wind direction instrumentation.




ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

August 29, 1983

2CAN088315

Mr. W. C. Seidle, Chief
Reactor Project Branch #2
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011




Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report
No. 83-036/04T-0

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.2, attached is the subject report concerning improper indication of wind direction.

Very truly yours,


John R. Marshall
Manager, Licensing

JRM:RJS:s1

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555