

# LICENSEE EVENT REPORT

CONTROL BLOCK:                      (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M S G S I 2000-0000000000000000 341111 4 5  
7 8 9 14 15 26 26 30 57 CAT 58

CON'T  
01 L 6050004167073083 082983 9  
7 8 80 81 86 87 88 89 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During the performance of a work order to correct a malfunction with the  
03 Division I isolation reset status lights, an amphenol type signal cable  
04 connector in a C/R panel was disconnected. Unexpectedly, the shutdown  
05 cooling and control room fresh air HVAC systems isolated, and SGBT "A"  
06 train initiated. This had no affect on the health and safety of the  
07 public and did not constitute a threat to plant safety. This is reported  
08 pursuant to T.S.6.9.1.13.c.  
7 8 9 80

09 I B A A Z Z Z Z Z Z Z Z  
9 10 11 12 13 18 19 20  
17 83 111 03 L 0  
21 22 24 26 27 28 29 30 31 32  
ACTION FUTURE EFFECT SHUTDOWN SEQUENTIAL OCCURRENCE REPORT REVISION  
TAKEN ACTION ON PLANT METHOD REPORT NO. CODE TYPE NO.  
X X Z Z 0000 N N Z Z 999  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The cause was personnel error. The impact of the MWO was not realized  
11 before the fact. An administrative method of preventing this type of  
12 event is under consideration at this time. This is an interim report.  
13 An update report is expected to be submitted by October 31, 1983.  
7 8 9 80

14 1  
7 8 9 80  
FACILITY STATUS 8 28 0000 29 NA 30 Z 31 Operator Observation 32  
7 8 9 10 12 13 44 45 46 80  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
7 8 9 10 11 44 45 80  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 38  
17 000 37 Z 38 NA  
7 8 9 11 12 13 80  
PERSONNEL INJURIES NUMBER DESCRIPTION 41  
18 000 40 NA  
7 8 9 11 12 80  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
19 Z 42 NA  
7 8 9 10 80  
PUBLICATION ISSUED DESCRIPTION 45  
20 N 44 NA  
7 8 9 10 80  
8309090058 830829  
PDR ADOCK 05000416  
S PDR  
NRC USE ONLY  
68 69 80



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

August 29, 1983

USNRO REGIONAL  
ATLANTA  
GEORGIA  
SEP 6 48:55

NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 2900  
Atlanta, Georgia 30303


Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-13  
File 0260/L-835.0  
Unexpected Isolation of  
Shutdown Cooling and  
Control Room Fresh Air HVAC  
Systems and Initiation of  
SBGT "A"  
LER 83-111/03 L-0  
AECM-83/0501

On July 30, 1983, during the performance of a work order, the shutdown cooling and Control Room fresh air systems isolated and the Standby Gas Treatment System "A" train initiated unexpectedly. The event is reported pursuant to Technical Specification 6.9.1.13.c. Attached is LER 83-111/03 L-0 which is an interim report.

Yours truly,

  
for L. F. Dale  
Manager of Nuclear Services

EBS/SHH:sap  
Attachment

cc: Mr. J. B. Richard (w/a)  
Mr. R. B. McGehee (w/o)  
Mr. T. B. Conner (w/o)  
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Document Control Desk (w/a)  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Member Middle South Utilities System

OFFICIAL COPY

102211