

CONTROL BLOCK: 

--	--	--	--	--	--	--

 ①

0	1	F	L	S	L	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5																																																														
7	3	9						14														15														25														26														37														38													
		LICENSEE CODE																				LICENSE NUMBER																												LICENSE TYPE														CAT																											

REPORT SOURCE: 01 L 5 0 5 0 0 0 3 8 9 7 0 8 0 2 8 3 3 0 9 0 1 8 3 9  
DOCKET NUMBER: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
EVENT DATE: 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
REPORT DATE: 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120

012 At 2200 hours on Aug. 2, 1983 while at 100% power with the "A" charging  
013 pump out of service for maintenance, the "C" charging pump failed and  
014 was placed out of service. This left only one charging pump operable  
015 which is not in accordance with T.S. 3.1.2.4. The "A" charging pump was  
016 placed back in service approx. 8.5 hours later, well within the 72 hours  
017 T.S. limit. The health and safety of the public were not in jeopardy.  
018 This is the third LER of this type, see LERs 389-016 and 043.

0	3
2	5

SYSTEM CODE P   C		(11)	CAUSE CODE E		(12)	CAUSE SUBCODE X		(13)	COMPONENT CODE P   U   M   P   X   X				(14)	COMP TURCODE E		(15)	VALVE SUBCODE Z		(16)							
EVENT YEAR 8   3		(17)	SEQUENTIAL REPORT NO. —		(18)	OCCURRENCE CODE 0   3		(19)	REPORT TYPE L		(20)	REVISION NO. 0		(21)												
ACTION TAKEN A		(22)	FUTURE ACTION Z		(23)	EFFECT ON PLANT Z		(24)	SHUTDOWN METHOD Z		(25)	HOURS 0   0   0   0		(26)	ATTACHMENT SUBMITTED N		(27)	VPRO FORM SUB. N		(28)	PRIME COMP SUPPLIER A		(29)	COMPONENT MANUFACTURER U   0   5   5		(30)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0	Investigation revealed that the "C" pump had developed a head gasket leak.
1 1	The gasket was replaced, the pump was tested satisfactorily and placed
1 2	back in service.
1 3	
1 4	

8 9  
FACILITY STATUS 5 POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
1 5 E (3) 1 0 0 (29) NA A (31) Operator Observation  
7 2 9 10 12 13 44 45 46

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (25)

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(27)	Z	(28)	NA	

		9	10	11	12	13	
		PERSONNEL INJURIES					
		NUMBER			DESCRIPTION		
1	2	3	4	5	6	7	8
		10	01	01	(40)		NIA


7	8	9	10	11	12
					NA
LOSS OF OR DAMAGE TO FACILITY (3)					
TYPE DESCRIPTION					

1 9 Z 12 NA  
3 2 10  
PUBLICITY 15

ISSUED DESCRIPTION NA NPC USE ONLY

NAME OF PREPARER J. P. Brannin

24CNE. 305 465-3550 X3427



Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street N.W., Suite 2900  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 389-83-44

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: AUGUST 2, 1983

TECHNICAL SPECIFICATION 3.1.2.4

"C" CHARGING PUMP

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

A handwritten signature in cursive script, which appears to read 'J. W. Williams, Jr.', followed by a large, stylized closing mark resembling a question mark or a large '3'.

J. W. Williams, Jr.  
Vice President  
Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Harold F. Reis, Esquire  
File 933.1 SL

OFFICIAL COPY

IE 22  
11