

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES: (10)

(17) LER/NO REPORT NUMBER	EVENT YEAR 21 8 22	SEQUENTIAL REPORT NO. 23 0 9 24 2	OCCURRENCE CODE 25 0 26 3	REPORT TYPE 27 L 28	REVISION NO. 29 0
ACTION TAKEN 33 F 34 (18)	FUTURE ACTION 35 H 36 (19)	EFFECT ON PLANT 37 Z 38 (20)	SHUTDOWN METHOD 39 Z 40 (21)	HOURS 41 0 42 0 43 0 44 0	(22) ATTACHMENT SUBMITTED 45 Y 46 (23)
HPRD-4 FORM SUB. 47 N 48 (24)		PRIME COMP. SUPPLIER 49 Z 50 (25)	COMPONENT MANUFACTURER 51 Z 52 9 53 9 54 9		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	3	
1	4	

8309090500 830831
PDR ADOCK 05000395
S PDR

ISSUED PUBLICITY DESCRIPTION (45)
N (44)

NRC USE ONLY

NAME OF PREPARER

L. E. Kolb / *[Signature]*
L. E. Kolb

PHONE (803) 345-5209

Mr. James P. O'Reilly
LER No. 83-092
Page Two
August 31, 1983

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

On August 17, 1983, at 1230 hours, with the Plant in Mode 1, the East Wall Fire Barrier in Control Building Room CB-36-02 was declared DEGRADED when an unsealed conduit in a newly installed junction box was found by Operations personnel. Work was in progress to downgrade the wall to Non-Fire Rated, but the conduit was installed prior to the downgrade. There were no adverse consequences as a result of this occurrence because the smoke detectors were OPERABLE and an hourly fire watch was established.

Action Statement (a) of Technical Specification 3.7.10 requires that with one or more of the required fire-rated assemblies and/or sealing devices inoperable, within one hour, either establish a continuous fire watch on at least one side of the affected assembly, or verify the OPERABILITY of the fire detectors on at least one side of the inoperable assembly and establish an hourly fire watch patrol. Technical Specification 3.7.10 is applicable at all times.

CAUSE AND CORRECTIVE ACTIONS

The cause of this occurrence is attributed to personnel error. The occurrence was discussed with the personnel involved and on August 23, 1983, the subject Fire Barrier was downgraded.

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

USNRC REGION II
ATLANTA, GEORGIA

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

August 31, 1983 SEP 6 A9:34

Mr. James P. O'Reilly
Regional Administrator
U.S. Nuclear Regulatory Commission
Region II, Suite 2900
101 Marietta Street, N.W.
Atlanta, Georgia 30303


SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
Thirty Day Written Report
LER 83-092

Dear Mr. O'Reilly:

Please find attached Licensee Event Report #83-092 for Virgil C. Summer Nuclear Station. This Thirty Day Report is required by Technical Specification 6.9.1.13.(b) as a result of entry into Action Statement (a) of Technical Specification 3.7.10, "Fire Rated Assemblies," on August 17, 1983.

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

LEK:OWD/mac/fjc
Attachment

cc: V. C. Summer
E. H. Crews, Jr.
T. C. Nichols, Jr.,/O. W. Dixon, Jr.
E. C. Roberts
H. N. Cyrus
Group/General Managers
O. S. Bradham
R. B. Clary
C. A. Price
A. R. Koon
D. A. Lavigne
J. F. Heilman

C. L. Ligon (NSRC)
G. J. Braddick
J. C. Miller
J. L. Skolds
J. B. Knotts, Jr.
I&E (Washington)
Document Management
Branch
INPO Records Center
NPCF
File (Lic./Eng.)

OFFICIAL COPY

IE 2211