

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 A L B R F 3 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT

01 REPORT SOURCE L 0 5 0 0 0 2 9 6 7 0 8 0 4 8 3 8 0 9 0 4 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal reactor operation, both off-gas post-treatment radiation
03 monitors (3-RM-90-265/266) became inoperable due to sample pump power
04 failure (T.S. 3.2.D.1.b and c). Monitors were out-of-service for one
05 hour. There was no effect on public health and safety. The stack
06 radiation monitor was operable and no release limits were exceeded. A
07 review of SI 4.8.B.1.a.1, Airborne Effluent Release Rate, indicated
08 no significant increase in building effluent activity levels during this event.

09 SYSTEM CODE I E 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE P U M P X X 14 COMP. SUBCODE G 15 VALVE SUBCODE Z 15
17 LER/RO REPORT NUMBER 8 3 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
ACTION TAKEN X 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPD-4 FORM SUB N 24 PRIME COMP. SUPPLIER L 25 COMPONENT MANUFACTURER G 0 8 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Sample pump was inoperable due to trip of Motor Control Center A
11 normal feeder breaker (GE trip unit TJK636T400) which supplies power to
12 the pump. No reason for the breaker trip could be found. Breaker
13 was reset. Currents were verified to be below trip value. This was
14 a random failure and no recurrence control is required.

15 FACILITY STATUS E 28 % POWER 0 9 6 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Control Room Alarm 32
16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
20 PUBLICITY ISSUED DESCRIPTION N 44 8309090555 830902 PDR ADOCK 05000296 S PDR NRC USE ONLY

NAME OF PREPARER Stan W. Solley

PHONE (205) 729-0891

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 83048 Technical Specification Involved 3.2.D

Reported Under Technical Specification 6.7.2.b(2) * Date Due NRC 9/3/83

Event Narrative:

Unit 1 was in a refueling outage, Unit 2 was operating normally at 95 percent power, and Unit 3 was operating at 96 percent power. Only Unit 3 was affected by this event. An off-gas sample flow abnormal alarm was observed. The alarm was due to power loss to the off-gas motor control center (MCC) board A. Since this provides power to the off-gas sample pump this made both radiation monitors (3-RM-90-265/266) inoperable (T. S. 3.2.D.1.b and c).

The loss of power was due to a trip on the normal feeder breaker (GE type TJK636F000 with trip unit TJK636T400). The alternate feeder breaker was closed, then the board was transferred back to the normal feeder breaker. This restored power to the board and all loads were returned to service. The load on the board was later measured to be approximately 100 amps. No reason for the trip of the 400 amp trip unit was found. The off-gas post treatment monitors were inoperable for 1 hour.

There was no effect on public health or safety. During the time both off-gas post treatment monitors were inoperable, the off-gas pre-treatment and stack radiation monitors were operable. No significant increase in activity levels was detected by these monitors during this time. The load on the board was later measured to be approximately 100 amps.

* Previous Similar Events:

BFRO-50-259/78032
296/83027

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

USNRC REGION II
ATLANTA, GEORGIA

83 SEP 6 48:55

September 2, 1983

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRO-50-296/83048

The enclosed report provides details concerning off-gas post-treatment
radiation monitors which became inoperable because of sample pump power
failure. This report is submitted in accordance with Browns Ferry
unit 3 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY



H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

OFFICIAL COPY

IE 22 1/1