



## Nebraska Public Power District

COOPER NUCLEAR STATION  
P.O. BOX 98, BROWNVILLE, NEBRASKA 68321  
TELEPHONE (402)825-3811  
FAX (402)825-5211

CNSS913666

April 23, 1991

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Dear Sir:

Cooper Nuclear Station Licensee Event Report 91-002, Revision 0, is being forwarded as an attachment to this letter.

Sincerely,

J. M. Meacham  
Division Manager  
Nuclear Operations  
Cooper Nuclear Station

JMM/bjs

Attachment

cc: R. D. Martin  
G. R. Horn  
R. E. Wilbur  
V. L. Wolstenholme  
D. A. Whitman  
INPO Records Center  
ANI Library  
NRC Resident Inspector  
R. J. Singer  
CNS Training  
CNS Quality Assurance

9104290206 910423  
PDR ADOCK 05000298  
S PDR

290019

Powerful Pride in Nebraska

IE22  
11

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Cooper Nuclear Station										DOCKET NUMBER (2) 0 5 0 0 0 2 9 8										PAGE (3) 1 OF 0 5																													
TITLE (4) Reactor Water Cleanup Isolation Due to High System Temperature During Plant Cooldown Caused by Failed Temperature Indication and Potential Equipment Failure																																																	
EVENT DATE (5) MONTH DAY YEAR 0 3 2 4 9 1										LER NUMBER (6) YEAR SEQUENTIAL NUMBER REVISION NUMBER 9 1 0 0 2 0 0 0 4 2 3 9 1										REPORT DATE (7) MONTH DAY YEAR 0 3 2 4 9 1										OTHER FACILITIES INVOLVED (8) FACILITY NAMES DOCKET NUMBER(S) 0 5 0 0 0 0																			
OPERATING MODE (9) N										THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																																							
POWER LEVEL (10) 0 0 0										20.402(b)										20.406(a)										X 50.73(a)(2)(iv)										73.71(b)									
										20.406(a)(1)(i)										50.36(a)(1)																				73.71(e)									
										20.406(a)(1)(ii)										50.36(a)(2)																				OTHER (Specify in Abstract below and in Text, NRC Form 366A)									
										20.406(a)(1)(iii)										50.73(a)(2)(i)																													
										20.406(a)(1)(iv)										50.73(a)(2)(ii)																													
										20.406(a)(1)(v)										50.73(a)(2)(iii)																													
LICENSEE CONTACT FOR THIS LER (12) NAME John R. Myers																														TELEPHONE NUMBER AREA CODE 4 0 2 8 2 5 - 3 8 1 1																			
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																																	
CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NRC																				
X	C	E	T	E	N	2	7	5	N																																								
E	C	T	T	S	M	2	3	5	N																																								
SUPPLEMENTAL REPORT EXPECTED (14) YES (If yes, complete EXPECTED SUBMISSION DATE) X NO																														EXPECTED SUBMISSION DATE (15) MONTH DAY YEAR																			

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On March 24, 1991, at 2:38 am and, again, at 4:15 am, Reactor Water Cleanup (RWCU) System isolations occurred as a result of high temperature conditions (140 degrees Fahrenheit) downstream of the RWCU Non-Regenerative Heat Exchangers (NRHX). At the time of these occurrences, the reactor was shutdown with the Residual Heat Removal (RHR) System in the Shutdown Cooling mode of operation. Reactor water temperature was approximately 185 degrees F. The RWCU system was aligned with a flow path open to the condenser hotwell to provide for reactor vessel level control. However, to facilitate Feedwater System maintenance, the pumps were not in operation.

Since reactor vessel level control was well established, minimal flow existed in the RWCU System. It is probable that the high temperature condition occurred due to the input of residual heat from RWCU piping and components. This condition may have been compounded had there been any backflow through the check valve in the 3/4 inch subcooling line installed between the NRHX outlet and the RWCU system inlet piping. (See attached sketch). With virtually no system differential pressure, this backflow could have existed, allowing direct input of hot water.

Neither of these isolations were preceded by any indication of system high temperature. Had such indications existed, operator action could have been taken to isolate the system. It was subsequently determined that the alarm switch and temperature indicator were defective. The root cause of these equipment failures is lack of preventive maintenance and random equipment failure. Corrective actions taken included replacement of the defective components and initiation of improvements to the Preventive Maintenance (PM) program for these components to assure their operation in the future.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Cooper Nuclear Station	DOCKET NUMBER (2)  0 5 0 0 0 2 9 8	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		91	002	00	02	OF 05

TEXT (if more space is required, use additional NRC Form 366A's) (17)

A. Event Description

On March 24, 1991, at 2:38 am and 4:15 am, Reactor Water Cleanup (RWCU) System isolations occurred due to high temperature in the RWCU piping downstream of the Non-Regenerative Heat Exchangers (NRHX). In both instances, the system temperature indication was normal and no alarms were received prior to the isolation. The reactor had been shut down the preceding day and was in cold shutdown. The RWCU System had been secured at approximately 2:21 am (i.e., the demineralizers isolated, the crossover valve [MO74] opened, and the RWCU pumps secured) to allow isolating the Feedwater System for maintenance.

Following the first isolation, the operating staff reviewed the available indications in the Control Room and could determine no reason for the isolation. The isolation was reset and the isolation valves reopened at 3:48 am. Following the second isolation, a station operator investigated, and determined that the high temperature isolation switch (TIS-99) was tripped. Subsequent investigation by the system engineer indicated the piping in the area was hot, and the temperature switch (TIS-99) indicated approximately 137 degrees Fahrenheit. System isolation occurs at 140 degrees F.

Based on the observed temperature difference between the Control Room and local indications, the temperature sensing elements in the piping were tested. TE-97, the thermocouple which provides Control Room indication, was found to have a grounded lead. TS-115, a temperature switch which provides the high temperature alarm, was found to be worn internally and would not actuate within the required range.

B. Plant Status

The reactor was in cold shutdown, at approximately 185 degrees F and vented. The RWCU System had been secured, with the containment isolation valves open. The RWCU System was aligned to drain to the condenser.

C. Basis for Report

Closure of the RWCU inlet isolation valves (ESF components) due to high NRHX outlet temperature, a non-ESF trip function. These events are being reported in accordance with criteria prescribed by 10CFR50.73(a)(2)(iv).

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20585, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Cooper Nuclear Station	DOCKET NUMBER (2)  0 5 0 0 0 2 9 8	LER NUMBER (6) <table border="1"><thead><tr><th data-bbox="1075 324 1155 358">YEAR</th><th data-bbox="1155 324 1317 358">SEQUENTIAL NUMBER</th><th data-bbox="1317 324 1433 358">REVISION NUMBER</th></tr></thead><tbody><tr><td data-bbox="1075 358 1155 421">9 1</td><td data-bbox="1155 358 1317 421">— 0 0 2 —</td><td data-bbox="1317 358 1433 421">0 0</td></tr></tbody></table>	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	9 1	— 0 0 2 —	0 0	PAGE (3)  0 3 OF 0 5
YEAR	SEQUENTIAL NUMBER	REVISION NUMBER							
9 1	— 0 0 2 —	0 0							

TEXT (If more space is required, use additional NRC Form 386A's) (17)

D. CAUSE

The isolations were caused by a high temperature condition in the piping downstream of the RWCU NRHX.

The RWCU System was aligned with a flow path open to the condenser hotwell to provide for reactor vessel level control. However, to facilitate Feedwater System maintenance, the pumps were not in operation. Since reactor vessel level control was well established, minimal flow existed in the RWCU System. It is probable that the high temperature condition occurred due to the input of residual heat from RWCU piping and components. This condition may have been compounded had there been any backflow through the check valve in the 3/4 inch subcooling line installed between the NRHX outlet and the RWCU System inlet piping. With virtually no system differential pressure, this backflow could have existed, allowing direct input of hot (185 degree F) water into this section of piping. (See attached sketch). The subcooling line is designed to prevent flashing at the RWCU pump suction by providing cooled water from the outlet of the NRHX. Contributing to this condition was the lack of correct indication (TE-97) and annunciation (TS-115) of a high temperature condition.

Testing of the thermocouple indicated a lead was grounded, causing the indication in the Control Room to read a constant 80 degrees F. It is not known how long the ground had existed. The root cause of this failure is considered to be an isolated, random failure of the component.

The internal mechanisms of the temperature switch were found to be worn, preventing actuation of the microswitch. This switch, installed in 1985, is calibrated on a four year frequency, and had satisfactorily passed its last calibration in 1988. The root cause of the switch failure is an inadequate Preventive Maintenance Program, as the switch should have been replaced prior to reaching the end of its life.

F. Safety Significance

No significant effect. The RWCU high temperature isolation is a non-safety related signal which serves to protect the RWCU demineralizer resin from the effects of high temperature. Although the temperature indication and alarm did not function as designed, the isolation function of the RWCU System performed correctly upon the high temperature condition, and the isolation valves closed as designed.

F. Safety Implications

The effect of a high temperature isolation at other plant conditions would not be significantly different. In the event of an isolation with the RWCU Pumps operating, the pumps automatically trip. Removal of the RWCU System from operation has no short term impact on reactor operation.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20556, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

Cooper Nuclear Station

0 5 0 0 0 2 9 8 9 1 - 0 0 2 - 0 0 0 4 OF 0 5

TEXT (If more space is required, use additional NRC Form 305A's) (17)

G. Corrective Action

The failed thermocouple and temperature switch were replaced and calibrated prior to startup from the maintenance outage. The isolation switch was confirmed to be operating correctly.

A Preventive Maintenance activity will be initiated to periodically replace the temperature switch. The frequency of the switch calibration will also be increased. Based upon recent documented calibration and response checks of installed thermocouples, the failure of TE-97 is considered to be an isolated incident. Therefore, no further corrective action is warranted.

H. Similar Events

None.

## SUPPLEMENTAL INFORMATION

TE-92 is a Type T Copper Constantan 300 Series thermocouple, manufactured by Nuclear Engineering Company, Incorporated. EHS component Code - TE

TS-115 is a Model DA-7036-153 temperature switch, manufactured by Mercoid Corporation. EHS Component Code - TS.

EHS System Codes

Reactor Water Cleanup - CE

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DISC KEY NUMBER (2)


LE 附 刊 附 刊 附 刊 (五)

PAGE 13

Cooper Nuclear Station

0	5	0	0	0	2	9	8	9	1	—	0	0	2	—	0	0	0	5	OF	0	1
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	----	---	---

TEXT (if more space is required, use additional NRC Form 300A's) (17)



CX A00387

## REACTOR WATER CLEAN-UP