

Mr. Boyce H. Grier, Director  
Office of Inspection & Enforcement, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

No. 3-79-6/3L-0

Dear Mr. Grier:

This L.E.R. refers to setpoint drift of a timer relay. The governing Technical Specification is Table 3.2.B.

LICENSEE EVENT REPORT

U. S. NUCLEAR REGULATORY COMMISSION

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: P A P B S 3 LICENSE NUMBER: 0 0 - 0 0 0 0 - 0 0 LICENSE TYPE: 3 CAT: 5

REPORT SOURCE: 0 1 DOCKET NUMBER: 0 0 5 0 - 0 2 7 8 EVENT DATE: 0 2 1 2 7 9 REPORT DATE: 0 3 0 5 7 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES: While at power, during performance of a surveillance test the setpoint of the B Core Spray Pump start timer was found to be 0.32 seconds less than the Tech Spec limit of 5.0 seconds. Safety significance was minimal since the redundant system was operable.

SYSTEM CODE: S F CAUSE CODE: E CAUSE SUBCODE: A COMPONENT CODE: R E L A Y X COMP. SUBCODE: M VALVE SUBCODE: Z

LEAD REPORT NUMBER: 7 9 SEQUENTIAL REPORT NO.: 0 0 6 OCCURRENCE CODE: 0 3 REPORT TYPE: L REVISION NO.: 0

ACTION TAKEN: E FUTURE ACTION: Z EFFECT ON PLANT: Z SHUTDOWN METHOD: Z HOURS: 0 0 5 0 ATTACHMENT SUBMITTED: N NPD-4 FORM SUB.: N PRIME COMP. SUPPLIER: N COMPONENT MANUFACTURER: A 1 0 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS: The cause was setpoint drift on Agastat timer relay Model CR2320. The timer relay was immediately readjusted, tested satisfactorily, and returned to service.

FACILITY STATUS: E % POWER: 1 0 0 OTHER STATUS: N/A METHOD OF DISCOVERY: B DISCOVERY DESCRIPTION: Surveillance Test

ACTIVITY: Z CONTENT: Z AMOUNT OF ACTIVITY: N/A LOCATION OF RELEASE: N/A

PERSONNEL EXPOSURES: NUMBER: 0 0 0 TYPE: Z DESCRIPTION: N/A

PERSONNEL INJURIES: NUMBER: 0 0 0 DESCRIPTION: N/A

LOSS OF OR DAMAGE TO FACILITY: TYPE: N/A DESCRIPTION: N/A

NAME OF PREPARER: M. J. Cooney PHONE: (215) 841-5020