

CONTROL BLOCK:

--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	6	6	7	0	8	0	6	8	2	8	0	9	0	2	8	2	9
60	61									68	69					74	75							80
DOCKET NUMBER											EVENT DATE						REPORT DATE							

0 2 While the plant was at hot shutdown, a control rod reed switch position
0 3 indicator was found to be inoperable during the performance of the
0 4 "Normal Startup" procedure. This event is contrary to TS 3.1.3.7 which
0 5 states that all control rod switch position indicators shall be operable.
C 6 Continued operation is permitted under a LCO as per TS sections
0 7 3.1.3.7.a.1.a and b. The health and safety of the public were not
0 8 affected. This event is non-repetitive.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE			
I E		E		A		I N S T R U				S		Z					
11		12		13		14				15		16					
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
8 2		0 8 8		0 3		L		0									
21 22		23		24 26		27		28 29		30 31		32					
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
Z A		Z		Z		0 0 0 0		Y		N		N		G 0 8 0			
32 34		35		36		37 40		41		42		43		44 47			

1 0 The cause of this event has been attributed to component failure. The
1 1 cause of this failure has not been determined. An update report will
1 2 be submitted upon completion of the corrective action. This action will
1 2 be completed during the 1983 refueling outage.

1	4											80		
7	8	9												
FACILITY STATUS			% POWER			OTHER STATUS (30)			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION (32)		
1	5	G (28)	0	0	0 (29)	NA			B (31)	Normal startup procedure				
7	8	9	10	11	12	13	44			45	46	80		

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 Z 33 Z 34 NA
7 8 9 10 11 44

LOCATION OF RELEASE (36)
NA
45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	NA

1		2		3		4		5		6		7		8		9		10		11		12	
LOSS OF OR DAMAGE TO FACILITY (43)																							
TYPE		DESCRIPTION																					
1	9	Z	(42)	NA																			

7 8 9 10 80

PUBLICITY

ISSUED DESCRIPTION (45)

2 0 N (44) NA S

8209160237
PDR ADOCK 05000366
PDR

NRC USE ONLY

NAME OF PREPARER S. B. Tipps

PHONE: (912) 367-7851

8209160239 820902
PDR ADOCK 05000366
S PDR

NRC USE ONLY

60

LER NO.: 50-366/1982-088
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1982-088

On August 6, 1982, with the unit in hot standby, a control rod reed switch position indicator was found to be inoperable during the performance of the "Normal Startup" procedure. This event is contrary to Technical Specification 3.1.3.7 which states that all control rod reed switch position indicators shall be operable. Continued operation was permitted under a limiting condition of operation (LCO) as per Tech. Spec. sections 3.1.3.7.a.1.a and b. Section (a) requires that the position of the control rod be determined by an alternate method (full-in indication was functional). When the unit was brought back up in power, operation was permitted under T.S. section (b) which permits continued operation if the control rod is moved to a position with an operable reed switch position indicator. The health and safety of the public were not affected. This event is non-repetitive.

The cause of this event has been attributed to component failure. The cause of the failure has not been determined. An update report will be submitted upon completion of the corrective action. This action will be completed during the 1983 refueling outage.