

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5						
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35							
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE										CAT 58	

CON'T

0	1	REPORT SOURCE	L	6	0	5	0	0	0	2	7	2	7	0	8	0	7	8	2	8	0	8	2	5	8	2	9		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
DOCKET NUMBER										EVENT DATE										REPORT DATE									

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On August 7, 1982, a Control Operator, attempting to perform a containment pressure relief, discovered Valve LVC5 would not open from the control console. Before repair of the valve could be performed, containment pressure reached the specification limit of 0.3 psig, and Action Statement 3.6.1.4 was entered. Valve LVC5 was blocked open with an air jumper, and Action Statement 3.6.3.1.a was entered. The occurrence involved operation in a degraded mode in accordance with Technical Specification 6.9.1.9.b.

0	9	SYSTEM CODE	S	A	11	CAUSE CODE	E	12	CAUSE SUBCODE	A	13	COMPONENT CODE	V	A	L	V	O	P	14	COMP. SUBCODE	E	15	VALVE SUBCODE	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.															
17		8 2		0 6 0		0 3		L		0															
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER									
A 18		Z 19		Z 20		Z 21		0 0 0 0		Y 23		Y 24		A 25		M 1 2 0 0 26									
33		34		35		36		37		40		41		42		43		44		45		46		47	

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The inoperability of Valve LVC5 resulted from the failure of a control air solenoid valve on the actuator. With LVC5 open, a pressure relief was conducted and containment pressure reduced to within specification. Upon completion, the jumper on Valve LVC5 was removed and the valve closed. The action statements were terminated, and the failed solenoid was subsequently replaced.

1	5	FACILITY STATUS	E	28	% POWER	1	0	0	29	OTHER STATUS	N/A	30	METHOD OF DISCOVERY	A	31	DISCOVERY DESCRIPTION	Operator Observation	32
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE												
1 6		Z 33		Z 34		N/A												
7		8		9		10												
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION												
1 7		0 0 0		Z		N/A												
7		8		9		10												
PERSONNEL INJURIES		NUMBER		DESCRIPTION														
1 8		0 0 0		N/A														
7		8		9		10												
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION														
1 9		Z		N/A														
7		8		9		10												
PUBLICATION		ISSUED		DESCRIPTION														
2 0		N		N/A														
7		8		9		10												

8209160473 820825  
PDR ADOCK 05000272  
S PDR

NRC USE ONLY

NAME OF PREPARER R. Frahm

PHONE: (609) 541-5900 629