

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	F	I	L	I	C	I	R	P	3	2	0	1	0	-	1	0	0	0	0	0	1	-	1	0	0	3	4	1	1	1	1	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

CONT

01	6	0	1	5	0	1	-	1	0	3	1	0	2	7	0	1	8	1	0	8	1	8	2	8	0	1	9	1	0	1	9	8	1	2	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40		

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 At 2100 two individuals reported that the outer door of the reactor
013 building personnel hatch was inoperable. This is contrary to TS 3.6.1.3.
014 Containment closure was maintained by assuring that the inner door
015 functioned properly. There was no effect on public health or safety.
016 This is the first occurrence for this door and the second report under
017 this specification.

018																																								
7	8	9																																						80

019	S	A	11	B	12	A	13	P	E	N	I	E	I	R	14	A	15	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	

17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.										
18	12	01513	1013	L	0										

33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			
A	18	Z	19	Z	20	Z	21	0	1	0	1	0	1	0			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A		18		Z		19		Z		20		Z		21		C 13 1 0	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

110 The cause of this event is attributed to the failure of Cam Roller Bear-
111 ings in the mechanical interlock. The bearings were replaced, and the
112 door functionally tested satisfactorily. A modification was completed on
113 August 31 to eliminate the problem.

114																																								
7	8	9																																						80

115	G	28	0	1	0	1	0	29	N/A	30	A	31	Notification by personnel																				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

116	Z	33	Z	34	N/A	35	N/A	36																									
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

117	0	1	0	1	0	37	Z	38	N/A	39																							
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

118	0	1	0	1	0	40	N/A	41																									
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

119	Z	42	N/A	43																													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

120	N	44	N/A	45																													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

NAME OF PREPARER E. W. FordPHONE (904) 795-6486

8209160486 820907
PDR ADOCK 05000302 PDR
S

SUPPLEMENTARY INFORMATION

REPORT NO: 50-302/82-053/03L-0
FACILITY: Crystal River Unit #3
REPORT DATE: September 9, 1982

OCCURRENCE DATE: August 8, 1982

IDENTIFICATION OF OCCURRENCE:

The outer door of the Reactor Building personnel hatch was inoperable, contrary to Technical Specification 3.6.1.3.

CONDITIONS PRIOR TO OCCURRENCE:

Mode 3, (0%).

DESCRIPTION OF OCCURRENCE:

At 2100, it was identified by two individuals that the outer door of the personnel hatch was inoperable (i.e., full closure was not possible). Redundant levels of containment integrity were not achievable. Maintenance was initiated, and the door functionally tested satisfactorily at 0530 on August 9, 1982.

DESIGNATION OF APPARENT CAUSE:

The cause of this event is attributed to the cam roller bearing in the mechanical interlock failing. The failure is apparently due to an inadequate design of the mechanical interlock system.

ANALYSIS OF OCCURRENCE:

Containment closure was maintained by assuring that the inner door functioned properly. There was no effect upon the health and safety of the public.

CORRECTIVE ACTION:

The bearings were replaced to correct the outer door closure problem. A modification was completed on August 31, 1982, to eliminate this type of malfunction.

FAILURE DATA:

This is the first occurrence for the personnel hatch outer door and the second report under this specification.