

U.S. NUCLEAR REGULATORY COMMISSION
LICENSEE EVENT REPORT Report No. 3-82-030/01T

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 PAPBS2200-00000-0034111145
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
01 6050-027770917828101829
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | With Units 2 and 3 operating at power on Sept. 17, 1982 a small quantity
03 | of slightly contaminated water was released from the recombiner building |
04 | into the storm drain system. The dilution of the small amount of |
05 | radioactive water discharged, by additional water in the storm drain |
06 | system resulted in no detectable release to the river. Previous |
07 | similar occurrence 3-81-13/IT. Applicable Tech Spec is 3.8.B.1 |

08 | _____ 80

0 9	A B 11	E 12	A 13	V A L V I O P 14	F 15	Z 16	
<small>7 8 9</small>	<small>9 10</small>	<small>11</small>	<small>12</small>	<small>13 18</small>	<small>19</small>	<small>20</small>	
	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP SUBCODE	VALVE SUBCODE	
17	8 2	0 3 0	0 1	T	0	0	
<small>7 8 9</small>	<small>21 22</small>	<small>23</small>	<small>24 26</small>	<small>27</small>	<small>28 29</small>	<small>30 31</small>	<small>32</small>
LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.		
X 18 Z 19	Z 20	Z 21	0 0 0 0	Y 23	Y 24	N 25	G 2 5 6 26
<small>33 34</small>	<small>35</small>	<small>36</small>	<small>37 40</small>	<small>41</small>	<small>42</small>	<small>43</small>	<small>44 47</small>
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | The release was caused by the spurious actuation of a Grinnell Model B |
11 | fire suppression valve. The water drained to the floor sump coming in |
12 | contact with radioactive water causing the sump to overflow. A portion |
13 | leaked out the building to storm drain system. The valve was tested and |
14 | reset, door was blocked and storm drain system was cleaned and flushed. |

15 | E28 10029 U3 - 100% A31 Fire pump start indication 32
7 8 9 10 12 13 44 45 46 80

FACILITY STATUS **% POWER** **OTHER STATUS** 30 **METHOD OF DISCOVERY** **DISCOVERY DESCRIPTION** 32

16 | Z33 Z34 NA 35 storm sewer to river 36
7 8 9 10 11 44 45 80

ACTIVITY **CONTENT** **RELEASED OF RELEASE** **AMOUNT OF ACTIVITY** 35 **LOCATION OF RELEASE** 36

17 | 00037 Z38 NA 39
7 8 9 11 12 13 80

PERSONNEL EXPOSURES **NUMBER** **TYPE** **DESCRIPTION** 39

18 | 00040 NA 41
7 8 9 11 12 80

PERSONNEL INJURIES **NUMBER** **DESCRIPTION** 41

19 | Z42 NA 43
7 8 9 10 80

LOSS OF OR DAMAGE TO FACILITY **TYPE** **DESCRIPTION** 43

20 | Y44 Press Release, September 17, 1982 45
7 8 9 10 68 69 80

PUBLICITY **ISSUED** **DESCRIPTION** 45 **NRC USE ONLY**

8210150179 821001 PDR ADOCK 05000277 S PDR M. J. Cooney PHONE: (215) 841-5020