

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	0	9	0	7	8	2	3	1	0	0	5	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

ON A SHIFT TOUR DURING NORMAL OPERATION, THE EQUALIZING VALVE ON THE INNER DOOR OF

THE UPPER CONTAINMENT PERSONNEL AIRLOCK WAS FOUND TO BE LEAKING SLIGHTLY DURING A

CONTAINMENT ENTRY. THIS CONSTITUTED AN INOPERABLE CONTAINMENT AIRLOCK, CONTRARY

TO T.S. 3.6.1.3. THE ACTION REQUIREMENT WAS MET AND PUBLIC HEALTH AND SAFETY WERE

NOT AFFECTED.

3

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

THE CAUSE OF THE CONDITION COULD NOT BE DETERMINED. THE VALVE ACTUATING MECHANISM

1 WAS ADJUSTED AND THE DOOR RETURNED TO SERVICE IN 2 HOURS AND 28 MINUTES. NO FURTHER

ACTION IS PLANNED AT THIS TIME.

NAME OF PREPARER R. H. PIEHL

PHONE 516-465-5901