

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99
LICENSEE CODE														LICENSE NUMBER																LICENSE TYPE										57-CAT 58																																																											

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 4 6 7 0 9 0 4 8 2 8 1 0 0 4 8 2 9
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

07 (NP-33-82-49) On 9/4/82 at 0945 hours, a Control Room operator observed Auxiliary

03 | Feedwater (AFW) Pump 1-1, suction valve FW786 closed for no apparent reason without

0	4
---	---

 | an operator touching the close button. The station entered the action statement of

[9] [5] | Technical Specification 3.7.1.2. There was no danger to the health and safety of the

[06] public or station personnel. The valve was closed for less than a minute during

07 | which the operator was aware of its position.

0 9
 7 8

SYSTEM CODE
 C H (11)
 9 10

CAUSE CODE
 X (12)
 11

CAUSE SUBCODE
 X (13)
 12

COMPONENT CODE
 V A L V E X (14)
 13 18

COMP. SUBCODE
 X (15)
 19

VALVE SUBCODE
 G (16)
 20

(17) LER/RO REPORT NUMBER EVENT YEAR
8 2
 21 22 — 23

SEQUELIAL REPORT NO. 0 4 5 / 27
 24 25

OCCURRENCE CODE 0 3 28 29

REPORT TYPE L 30

REVISION NO. — 31 0 32

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
X	X	Z	Z		Y		N	P 3 1
(18)	(19)	(20)	(21)		(23)	(24)	(25)	
33	34	35	36	37	41	42	43	44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The cause is unknown. Maintenance Work Order 82-2334 was performed on 9/28/82 to in-
---	---	--

1 1 | investigate the control circuit, however, no cause was found as to why the valve went

1 2 closed. FW786 was immediately reopened, and the applicable portion of ST 5071.04 was

1 3 | performed to prove operability. Since 9/4/82, there have been no further random

4 | closures of this valve.

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	(28)	0	2	5	(29)	NA				A	(31)	Operator Observation	(32)
7	8	9		10	11	12		13				45	46		

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 NA

7 8 9 10 11 44

AMOUNT OF ACTIVITY (35)

NA

45 8

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7		2	NA					

PERSONNEL INJURIES										
NUMBER			DESCRIPTION							
1	8					40	NA			
7	8	9	10	11	12	13	14	15	16	17

1 9		7 8		9 10		11 12		13 14		15 16		17 18		19 20		21 22		23 24		25 26		27 28		29 30		31 32		33 34		35 36		37 38		39 40		41 42		43 44		45 46		47 48		49 50		51 52		53 54		55 56		57 58		59 60		61 62		63 64		65 66		67 68		69 70		71 72		73 74		75 76		77 78		79 80		81 82		83 84		85 86		87 88		89 90		91 92		93 94		95 96		97 98		99 100																																																																																																	
1 9		7 8		9 10		11 12		13 14		15 16		17 18		19 20		21 22		23 24		25 26		27 28		29 30		31 32		33 34		35 36		37 38		39 40		41 42		43 44		45 46		47 48		49 50		51 52		53 54		55 56		57 58		59 60		61 62		63 64		65 66		67 68		69 70		71 72		73 74		75 76		77 78		79 80		81 82		83 84		85 86		87 88		89 90		91 92		93 94		95 96		97 98		99 100																																																																																																	
1		9		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		9		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		9		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60																																																																																	

PUBLCITY		ISSUED		DESCRIPTION		8210180137 821004 PDR ADDCK 05000346 S PDR		NRC USE ONLY	
2	0	N	(44)	NA					
7	8	9	10					68	69

DVR 82-100

NAME OF PREPARER

James W. Long

PHONE: (419) 259-5000, Ext. 565

017-976

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-82-49

DATE OF EVENT: September 4, 1982

FACILITY: Davis-Besse Unit L

IDENTIFICATION OF OCCURRENCE: FW786 went closed for no apparent reason

Conditions Prior to Occurrence: The unit was in Mode 1 with Power (MWT) = 693 and Load (Gross MWE) = 180

Description of Occurrence: On September 4, 1982 at 0945 hours, a Control Room operator observed Auxiliary Feedwater Pump (AFP) 1-1 suction valve FW786 go from open to close without an operator touching the close button. The station entered the action statement of Technical Specification 3.7.1.2. At 0945 hours, the valve was reopened by the Control Room operator, and the station was removed from the action statement.

Designation of Apparent Cause of Occurrence: The cause for this spurious occurrence is unknown. Maintenance Work Order 82-2334 was performed on September 28, 1982 to thoroughly investigate the control circuit, however, no cause was found as to why the valve went closed. FW 786 is a locked valve; as such its local controller is locked and the manual valve handwheel on the limitorque operator was locked in the open position. This and the fact that the security computer did not show personnel in the room indicates that the valve was not intentionally closed.

Analysis of Occurrence: There was no danger to the health and safety of the public or station personnel. The valve was closed for less than a minute during which the operator was aware of its position. Auxiliary Feedwater Train 1 could have been manually restored from the Control Room if required. In addition, Auxiliary Feedwater Train 2 was operable during the time of the occurrence.

Corrective Action: The Control Room operator verified that SW 1382 did not open, and the auxiliary feedwater pump trouble alarm did not actuate which indicates it was not the low pressure switch interlock causing the closure. FW786 was reopened, and the applicable portion of Surveillance Test ST 5071.04 was performed to prove operability. Repeated attempts were made to duplicate the initial conditions of the event without success. Relay checks and electrical inspections under MWO 82-2334 did not reveal subsequent problems. Since September 4, 1982, there have been no further random closures of this valve.

Failure Data: A previous similar occurrence was reported in Licensee Event Report NP-33-80-33 (80-024) which described the Auxiliary Feed Pump Turbine 1-2 Main Steam Isolation Valve MS-107 randomly closing for no apparent reason.