

## LICENSEE EVENT REPORT

Attachment to AECM-82/513

Page 1 of 1

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M S G G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 1 0 0 8 2 8 1 0 2 8 8 2 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On October 1, 1982, fire zone 2-04 was deactivated in the Security and Fire Protection  
0 3 Computer due to inability to reset a spurious smoke detector alarm. No fire or smoke  
0 4 was present. An hourly fire watch was established per Technical Specification 3.3.7.9a.  
0 5 This had no affect on the safety of the plant and did not constitute a threat to the  
0 6 health and safety of the public.  
0 7  
0 80 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
A B 11 X 12 Z 13 I N S T R U 14 Z 15 Z 16  
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
8 2 0 9 6 0 3 L 0  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
Z 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 H 2 6 0 26

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Since no component failure could be found, the alarm was reset. The zone was  
1 1 returned to service in the computer on October 4, 1982 and was observed for 2 weeks  
1 2 with no additional problems. The alarm was apparently spurious and no further action  
1 3 will be taken. This is intended as a final report.  
1 41 5 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32  
B 28 0 0 0 29 NA A 31 Alarm in Control Room  
1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
Z 33 Z 34 NA NA  
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
0 0 0 37 Z 38 NA  
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41  
0 0 0 40 NA  
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
Z 42 NA  
2 0 PUBLICITY ISSUED DESCRIPTION 45  
N 44  
8211040331 821028  
PDR ADOCK 05000416  
S PDR  
NRC USE ONLY  
68 69 80

NAME OF PREPARER Original signed by Ken L. Walker

PHONE: 826-1600