

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1	A	L	B	R	F	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
8	9	LICENSEE CODE					14	19	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT 58	

REPORT SOURCE 1 6 0 5 0 0 0 2 6 0 7 1 0 6 4 8 2 3 1 0 2 9 8 2 9

63 61 68 69 74 75 80

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2] While performing source and background check of the reactor and turbine building
3] vent monitor, charcoal filter was found to be out of place (T.S. 3.8.B.6). Sampling
4] requirements were not met for about 24 hours. Last authorized removal of filter
5] was at 1240 on 10/3/82. There was no effect on public health and safety. Monitor
6] was still capable of detecting iodines. A review of SI 4.8.B.1.a.1 indicated no
7] significant releases. There are no redundant systems.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE	
M	C	A		X		Z	Z	Z	Z	Z	Z	Z	Z	Z	
9	10	11	12	13	14	15	16	17	18	19	20	21	22		
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
8	2	0	3	1	0	3	L		0						
21	22	23	24	25	26	27	28	29	30						
ACTION FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A	Z	Z	Z	Z	0	0	0	0	Y	N	N	Z	Z	9	9
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

☐ Cause was personnel error in leaving the filter out of the CAM. Filter was replaced

☐ after source and background check was completed at 1246 on 10-4-82. This incident

☐ had been discussed with the individual involved. This was a random event. No

☐ further recurrence control is required.

FACILITY STATUS			K. POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
H	0	0	0	0	0	NA	NA	NA	B	31	31	Chemical laboratory analyst observation		
ACTIVITY CONTENT			RELEASED OR RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Z	13	13	Z	14	14	NA	NA	NA	NA	NA	NA	NA	NA	NA
PERSONNEL EXPOSURES			PERSONNEL EXPOSURES			PERSONNEL EXPOSURES			PERSONNEL EXPOSURES			PERSONNEL EXPOSURES		
NUMBER			TYPE			DESCRIPTION			NUMBER			DESCRIPTION		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
0	0	0	17	Z	18	NA	NA	NA	NA	NA	NA	NA	NA	NA
PERSONNEL EXPOSURES			PERSONNEL EXPOSURES			PERSONNEL EXPOSURES			PERSONNEL EXPOSURES			PERSONNEL EXPOSURES		
NUMBER			DESCRIPTION			NUMBER			DESCRIPTION			NUMBER		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
0	0	0	100	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
LOG OF MESSAGE TRANSMISSION			LOG OF MESSAGE TRANSMISSION			LOG OF MESSAGE TRANSMISSION			LOG OF MESSAGE TRANSMISSION			LOG OF MESSAGE TRANSMISSION		
TYPE			DESCRIPTION			TYPE			DESCRIPTION			TYPE		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Z	4	4	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA

PUBLICITY
 SETS DESCRIPTION (1)
 N [44]

8211080252 821029
PDR ADDCK 05000260
S PDR

NAC USE ONLY

NAME OF PREPARED David Thorpe

2000 (255) 729-0621

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 82031 Technical Specification Involved 3.8.B.6

Reported Under Technical Specification 6.7.2.b.(2)* Date Due NRC 11/03/82

Event Narrative:

Unit 1 was operating at 98-percent power, unit 2 was in a refueling outage, and unit 3 was operating at 98-percent power. Only unit 2 was affected by the event. During the daily source and background check of continuous air monitor (CAM) 2-90-250, personnel discovered the charcoal filter was not in place. This caused the CAM to operate in a degraded mode (T.S. 3.8.B.6). Last authorized removal of the filter was at 1240 on October 3, 1982 during routine performance of background and source check procedure. Therefore, the filter must be assumed to have been out of the CAM for a maximum 24 hours. The halogen channel was still capable of detecting iodine, though in a less sensitive manner. A review of SI 4.8.B.1.a.1 indicated no significant releases for the 2-90-250 CAM or for any of the other CAM's during this period. There was no effect on public health and safety. There are no redundant systems. The cause of this event was personnel error. The event has been discussed with the individual involved. Upon discovery the filter was replaced. This is considered an isolated occurrence and no further recurrence control is required.

* Previous Similar Events:

NONE

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP