

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

/0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /1/0/0/8/8/2/ (8) /1/1/0/3/8/2/ (9)
SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On October 8, 1982, during a Unit 1 refueling outage, an instrument calibration /
/0/3/ / check showed that the flux penalty input to the Channel 1 overtemperature delta T/
/0/4/ / setpoint was out of tolerance. Channels II and III were correctly calibrated. /
/0/5/ / The Unit would be shutdown in the event delta flux reaches -50 percent and the /
/0/6/ / delta flux penalty for the overtemperature delta T setpoint was conservative for/
/0/7/ / delta flux values less negative than -50 percent. The public health and safety /
/0/8/ / were not affected. This event is reportable pursuant to T.S. 6.9.1.9.a. /

SYSTEM CAUSE CAUSE COMP. VALVE
CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE

/0/9/ /I/A/ (11) /E/ (12) /E/ (13) /I/N/S/T/R/U/ (14) /Y/ (15) /Z/ (16)
SEQUENTIAL OCCURRENCE REPORT REVISION
LER/RO EVENT YEAR REPORT NO. CODE TYPE NO.

(17) REPORT
NUMBER /8/2/ /-/ /0/6/6/ /-/ /0/3/ /L/ /-/ /0/

ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT
TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER

/E/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /Y/ (23) /N/ (24) /N/ (25) /W/1/2/0/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The cause of the event is unknown. Channel drift is the suspected cause. The /
/1/1/ / channel was recalibrated with satisfactory results. /
/1/2/ / /
/1/3/ / /
/1/4/ / /

FACILITY METHOD OF
STATUS %POWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION (32)
/1/5/ /H/ (28) /0/0/0/ (29) / NA / (30) /B/ (31) /Technician Observation/

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
/1/6/ /Z/ (33) /Z/ (34) / NA / / NA /

PERSONNEL EXPOSURES
NUMBER TYPE DESCRIPTION (39)
/1/7/ /0/0/0/ (37) /Z/ (38) / NA /

PERSONNEL INJURIES
NUMBER DESCRIPTION (41)
/1/8/ /0/0/0/ (40) / NA /

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
/1/9/ /Z/ (42) / NA /

PUBLICITY
ISSUED DESCRIPTION (45)
/2/0/ /N/ (44) / NA /

NRC USE ONLY

/ / / / / / / / / / / /

NAME OF PREPARER W. R. CARTWRIGHT

PHONE (703) 894-5151

Description of Event

On October 8, 1982, during a Unit 1 refueling outage, an instrument calibration check showed that the flux penalty input to the Channel I overtemperature delta T setpoint was out of tolerance. For delta flux values more negative than -50 percent, the delta flux penalty input to the overtemperature delta T setpoint was less than the penalty required by T.S. table 2.2-1. The attached graph displays both the desired and as found delta flux penalty functions. This event is reportable pursuant to T.S. 6.9.1.9.a.

Probable Consequences of Occurrence

T.S. Table 2.2-1 requires that:

"for each percent that the magnitude of $(q_t - q_b)$ exceeds - 34 percent, the ΔT trip setpoint shall be automatically reduced by 3 percent of its value at RATED THERMAL POWER".

No maximum penalty or delta flux operating range for the penalty is specified by T.S. table 2.2-1.

The Westinghouse "Precautions, Limitations, and Setpoints" document for North Anna Power Station specified, prior to the current Unit 1 Tavg upgrade, that the "Cutoff" limit for the flux penalty must be greater than or equal to its value at +35 and -50 percent delta flux. The PLS "Cutoff" limits are shown on the attached graph.

The as found delta flux penalty was more conservative than the delta flux penalty required by the PLS. It appears that the as found delta flux penalty was more conservative than the penalty assumed in the safety analysis. The safety analysis is currently being checked for delta flux penalty assumptions.

The as found delta flux penalty was less conservative than the penalty specified in the Technical Specifications. The delta flux penalty function specified in the Technical Specifications is specified without bounds. Currently the delta flux penalty function is calibrated to increase as large as electronically practical. As shown on the attached graph the penalty is allowed to increase to 150 percent.

The disagreement between the as found delta flux overtemperature delta T penalty function and the penalty function specified in the Technical Specifications appears to have no safety implications. An investigation is being conducted to determine the delta flux penalty function "Cutoff" limits used in the safety analysis. If appropriate, a Technical Specification change request will be submitted to incorporate "Cutoff" limits when the investigation is complete.

The Unit would be shutdown in the event delta flux reaches -50 percent and the delta flux penalty for the overtemperature delta T setpoint was conservative for delta flux values less negative than -50 percent. Channels II and III were correctly calibrated and provided required protection (2/3 logic). The public health and safety were not affected.

Cause of Event

A review of past channel calibrations revealed no discrepancies which would have caused a shift in the delta flux overtemperature delta T setpoint penalty. A channel calibration performed on January 8, 1981 showed that the delta flux overtemperature delta T setpoint penalty was correct at that time. It appears that between January 8, 1981 and October 8, 1982 that the Channel I delta flux overtemperature delta T penalty function generator card drifted.

Immediate Corrective Action

The overtemperature delta T setpoint circuit was recalibrated with satisfactory results.

Scheduled Corrective Action

No further action is required.


Actions Taken to Prevent Recurrence

No further actions are required.

Generic Implications

There are no generic implications associated with this event.

UNIT 1 SETPOINT REDUCTION FUNCTION FOR
OVERTEMPERATURE AT TRIP
PRIOR TO TAVG UPGRADE



MINIMUM PLS TRIP RESET CUTOFF LIMIT: +35, -50 % Δq