

LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1	A	L	B	R	F	3	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
8	9	LICENSEE CODE					14	15	LICENSE NUMBER										23	24	LICENSE TYPE					30	57 CAT 58				59

REPORT SOURCE L 0 5 0 0 0 2 9 6 7 1 0 1 1 8 2 2 1 1 0 9 8 2 9

63 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

7] Following a rod pattern adjustment, the calculated "R" factor (RRP/CMFLPD) (0.982)

8] was less than the "R" factor used to set the APRM scram and rod block (1.0) for

9] 2 hours and 15 minutes (T.S. 2.1.A.1.b & d). There was no effect on public health

10] or safety. The calculated scram value was not exceeded during this time.

11] \_\_\_\_\_

12] \_\_\_\_\_

13] \_\_\_\_\_

14] \_\_\_\_\_

8 9

SYSTEM CODE I A (11)		CAUSE CODE X (12)		CAUSE SUBCODE Z (13)		COMPONENT CODE Z Z Z Z Z Z (14)				COMP. SUBCODE Z (15)		VALVE SUBCODE Z (16)	
EVENT YEAR 8 2 (17)		SEQUENTIAL REPORT NO. 0 4 8 (18)		OCCURRENCE CODE 0 3 (19)		REPORT TYPE L (20)		REVISION NO. 0 (21)					
ACTION TAKEN E (22)		FUTURE ACTION G (23)		EFFECT ON PLANT Z (24)		SHUTDOWN METHOD Z (25)		HOURS 0 0 0 0 (26)		ATTACHMENT SUBMITTED Y (27)		NPRD-4 FORM SUB. N (28)	
PRIME COMP. SUPPLIER Z (29)		COMPONENT MANUFACTURER Z 9 9 9 (30)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (31)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

- ☐ Event was due to the insertion of control rods required to maintain operation
- ☐ with prescribed load line. Action was taken to revise the control rod pattern.
- ☐ "R" was within limits in 2 hours and 15 minutes. Tech specs have been submitted
- ☐ for units 2 and 3 (similar to present unit 1 tech specs) to allow 6 hours
- ☐ to correct "R".

FACILITY STATUS										N. POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION									
E										085										NA										B										Engineer observation									
ACTIVITY CONTENT										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																													
Z										Z										NA										NA																			
PERSONNEL EXPENDITURES										DESCRIPTION										NA																													
000										Z										NA																													
PERSONNEL INJURIES										DESCRIPTION										NA																													
000										NA										NA																													
KIND OF DAMAGE TO FACILITY										DESCRIPTION										NA																													
Z										NA										NA																													
PUBLICATION										DESCRIPTION										8211220279 821109 PDR ADOCK 05000296 S PDR										NRC USE ONLY																			
N																																																	

8211220279 821109  
PDR ADOCK 05000296  
S PDR

NAC USE ONLY

NAME OF PREPARED \_\_\_\_\_ Earl Nave

(205) 729--0845

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 82048 Technical Specification Involved 2.1.A.1.b&d

Reported Under Technical Specification 6.7.2.b.(2)\* Date Due NRC 11/10/82

Event Narrative:

Unit 1 was operating at 97-percent power; unit 2 was in a refueling outage. These units were unaffected by this event. Unit 3 was operating at 85-percent power following a control rod pattern adjustment. The unit was prevented from returning to full power following the control rod pattern due to feed pump problems. The delay at low flow caused a gradual load line increase as xenon burned out. When control rods were inserted as required to reduce the load line, "R" was reduced to 0.982 at 0122. This condition was in violation of Technical Specification 2.1.A.1.b and 2.1.A.1.d since the "R" factor setpoint was 1.0. The rod pattern was readjusted and the "R" was within limits (1.008) at 0337. There was no effect on public health or safety. The calculated APRM scram value was not exceeded during this event. A technical specification revision has been proposed and submitted to the NRC to allow up to six hours for "R" factor being less than the "R" setpoint as currently permitted by unit 1 technical specifications.

\* Previous Similar Events:

BFRO-50-259/82019  
260/81037, 82022  
296/81045, 81041, 81040, 82038

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

Revision: J.R.