

11/10 15:07

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	(5)	0	5	1	0	1	0	1	3	2	7	(7)	1	1	0	2	9	8	2	(8)	1	1	1	0	8	2	(9)
---	-----	---	---	---	---	---	---	---	---	---	---	-----	---	---	---	---	---	---	---	-----	---	---	---	---	---	---	-----

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

0 2 | With unit 1 in mode 6 and unit 2 in mode 1 (96% power) at 1500 CST on 10/29/82, the
0 3 | control room emergency ventilation system was declared inoperable due to the common
0 4 | suction dampers 0-31A-102 and -103 partially closing causing the system to be
0 5 | unable to maintain its rated flow of 4000 cfm. A similar event occurred at 0800 CST
0 6 | on 11/09/82. Both events required entry into the action statements of LCO 3.7.7
0 7 | and 3.0.3. There was no effect upon public health and safety. Previous occurrences
0 8 | - one (SQRO-50-327/82071).

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE					
0	9	S	G	E	B	V	A	L	V	E	X	N	G				
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LEA/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.				OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
17	8	2	1	2	3	0	1	T	0								
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NIPD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
E	X	Z	Z	0	0	0	0	Y	N	L	X	9	9	9			
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

110 In both events, it was found that the adjustment screw holding the dampers open had
111 backed out due to vibration in the duct allowing the suction damper to partially
112 close. The screw was immediately readjusted to open the dampers. Design change
113 request (DCR) 1650 is being expedited to provide a new damper. Until work is
114 complete, the damper's position will be verified on a daily basis.

FACILITY STATUS (1) 5 (2) G (28) 0 0 0 0 (29) NA (30) OTHER STATUS
 METHOD OF DISCOVERY (31) B (32) System Walkdown
 ACTIVITY CONTENT RELEASED OF RELEASE (33) Z (34) Z (35) NA
 AMOUNT OF ACTIVITY (36) NA
 PERSONNEL EXPOSURES NUMBER (37) 0 0 0 (38) Z (39) NA
 TYPE DESCRIPTION
 PERSONNEL INJURIES NUMBER (40) 0 0 0 (41) NA
 DESCRIPTION
 LOSS OF OR DAMAGE TO FACILITY TYPE (42) Z (43) NA
 DESCRIPTION
 PUBLICITY ISSUED (44) N (45) NA
 DESCRIPTION
 8211220319 821110
 PDR ADOCK 05000327
 S PDR
 NRC USE ONLY

Name of Preparer: H. J. Fingers / M. R. Harding

Phone: (615) 751-0349

LER SUPPLEMENTAL INFORMATION

SQRO-50-327/82123

Technical Specification Involved: 3.7.7

Reported Under Technical Specification: 6.9.1.12.b

Date of Occurrence: 10/29/82

Time of Occurrence: 1500 CST

Identification and Description of Occurrence:

At 1500 CST on 10/29/82, during a walkdown of the control room emergency ventilation system, suction dampers 0-31A-102 and -103 were found partially closed. This would have prevented the system from maintaining a flow rating of 4000 cfm in the event of control room isolation. A similar event occurred at 0800 CST on 11/09/82. Upon discovery of each event, the unit entered the action statements of LCO 3.7.7 and 3.0.3.

Conditions Prior to Occurrence:

For both events unit 1 was in mode 6 (refueling) and unit 2 was in mode 1 (96% power).

Apparent Cause of Occurrence:

The louvered dampers are held open by an adjustment screw. In each case, vibration of the duct and damper from air flow across the damper caused the adjustment screw to loosen and the damper to partially close.

Analysis of Occurrence:

In the event of control room isolation, the control room emergency ventilation system is designed to provide 4000 cfm (+ 10%) air flow to the control room. Suction dampers 0-31A-102 and -103 are common to both trains of the emergency air cleanup fans. These dampers are preset to ensure 3800 cfm (+ 10%) flow of filtered air to the control room. When the dampers vibrated partially closed, the system would have been unable to meet the needed flow criteria.

Corrective Action:

For each event, the damper was immediately opened to the preset position and the adjustment screw tightened. Measures are being taken to block the damper in the open position to maintain system operability. The design of a new damper is being reviewed by Design through DCR 1650. Until modifications are made, a daily surveillance will be performed to verify the damper setting.

Failure Data:

None.