

EXPIRES 4/30/92

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 500. HIS FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530) U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

Fort Calhoun Station Unit No. 1

DOCKET NUMBER (2)

0 5 0 0 0 2 8 5

PAGE (3)

1 OF 0 5

TITLE (4)

Nonfunctional Fire Barrier Penetrations

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)
0	9	0	7	9	0	9	0	0	N	0 5 0 0 0
0	9	0	7	9	0	9	0	0		0 5 0 0 0
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)							
1			20.402(b)		20.405(e)		50.73(a)(2)(iv)		73.71(b)	
POWER LEVEL (10)			20.406(a)(1)(i)		50.38(c)(1)		50.73(a)(2)(v)		73.71(c)	
1,00			20.406(a)(1)(ii)		50.38(c)(2)		50.73(a)(2)(vi)		X OTHER (Specify in Abstract below and in Text, NRC Form 366A)	
			20.406(a)(1)(iii)		50.73(a)(2)(i)		50.73(a)(2)(vii)(A)		Special and Voluntary Report	
			20.406(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(vii)(B)			
			20.406(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)			

LICENSEE CONTACT FOR THIS LER (12)

NAME

Craig Fritts, System Engineer

TELEPHONE NUMBER

AREA CODE

4 0 2 5 3 3 - 6 5 5 4

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

☐ YES (If yes, complete EXPECTED SUBMISSION DATE)☒ NO

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On September 7, 1990, approximately 460 fire barrier penetration seals, 60 fire dampers and 6 fire doors associated with 25 fire areas were declared nonfunctional due to either lack of documentation to qualify non-verifiable penetration critical parameters, or penetration "as built" configurations which did not match typical configurations previously qualified by fire tests. These nonfunctional penetrations were discovered through a special design basis verification walkdown prompted by NRC Information Notice 88-04.

As required by Technical Specifications, the appropriate compensatory measures were implemented. On November 27, 1990 and on January 2, 1991, additional barrier penetrations were determined to be nonfunctional and the required compensatory measures were established. The compensatory measures will remain in place until the affected fire barrier penetrations are restored to functional status through engineering evaluation, repair, or replacement.

This report is submitted pursuant to Technical Specification 2.19(7) because most of the nonfunctional fire barrier penetrations were not restored to functional status within 7 days. It is being submitted also as a Voluntary LER due to potential regulatory and industry interest.

9102120021 910206
PDR ADOCK 05000285
S PDR

**LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Fort Calhoun Station Unit No. 1	DOCKET NUMBER (2) 0 5 0 0 0 2 8 5	LER NUMBER (6) <table border="1"> <tr> <th data-bbox="1066 324 1155 347">YEAR</th> <th data-bbox="1155 324 1335 347">SEQUENTIAL NUMBER</th> <th data-bbox="1335 324 1424 347">REVISION NUMBER</th> </tr> <tr> <td data-bbox="1066 369 1155 392">9 0</td> <td data-bbox="1155 369 1335 392">— 0 2 2</td> <td data-bbox="1335 369 1424 392">— 0 2 0</td> </tr> </table>	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	9 0	— 0 2 2	— 0 2 0	PAGE (3) 2 OF 0 5
YEAR	SEQUENTIAL NUMBER	REVISION NUMBER							
9 0	— 0 2 2	— 0 2 0							

TEXT (If more space is required, use additional NRC Form 356A's) (17)

NRC Information Notice 88-04, Inadequate Qualification and Documentation of Fire Barrier Penetration Seals, requested utilities to verify the design basis of their fire barrier penetration seals. Omaha Public Power District (OPPD) began a comprehensive walkdown and assessment of all Technical Specification required fire barriers in April of 1990. This walkdown and assessment effort was conducted by contractor personnel under the provisions of OPPD Special Procedures SP-DEN-FP-0001, SP-DEN-FP-0002 and SP-DEN-FP-0003. The scope of the project included fire barrier penetration seals, fire doors, and fire dampers.

The walkdown portion was performed to document the "as built" condition of fire barrier penetration seals, fire doors, and fire dampers. On September 7, 1990 OPPD Systems Engineering and Design Engineering completed the assessment of fire barrier configurations as documented by the Special Procedures. These procedures required that fire barriers penetrations be considered inoperable if no prior documentation of installation was found for critical parameters that could not be field verified, or if any "as built" penetration barrier did not match a fire-tested and qualified configuration. For this screening, each penetration barrier was considered functional if it was considered to meet a minimum 3-hour fire rating.

Based on this assessment, the following fire barrier penetrations associated with 25 fire areas were determined to be nonfunctional:

- (1) approximately 460 of 3500 penetration seals,
- (2) 60 of 79 fire dampers, and
- (3) 6 of 79 fire doors.

As a result, System Engineering initiated Fire Protection Impairment Permits for all areas of the plant where fire barrier penetrations were considered to be nonfunctional. Compensatory measures required by Technical Specification 2.19(7) for inoperable fire barrier penetrations were established. Revision 0 of this report was submitted as required by the Technical Specification on October 8, 1990 because most of the nonfunctional fire barrier penetrations were not restored to functional status within 7 days. It was submitted also as a Voluntary LER due to potential regulatory and industry interest.

A walkdown assessment of seals determined to be nonfunctional continued concurrent with a Quality Control verification of individual penetration as-built drawings. Consequently, additional sealing devices were identified as nonfunctional. On November 27, 1990, one additional barrier impairment permit was issued and the required compensatory measures were established. Revision 1 of this report fulfilled the Special Report requirement of the Technical Specification for the additional nonfunctional penetrations identified.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)										
Fort Calhoun Station Unit No. 1		<table border="1"><tr><th data-bbox="1065 329 1178 351">YEAR</th><th data-bbox="1183 329 1307 351">SEQUENTIAL NUMBER</th><th data-bbox="1312 329 1412 351">REVISION NUMBER</th></tr><tr><td data-bbox="1065 383 1178 405">90</td><td data-bbox="1183 383 1307 405">022</td><td data-bbox="1312 383 1412 405">02</td></tr></table>	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	90	022	02	<table border="1"><tr><th data-bbox="1423 329 1483 351">PAGE</th><th data-bbox="1488 329 1607 351">OF</th></tr><tr><td data-bbox="1423 383 1483 405">03</td><td data-bbox="1488 383 1607 405">05</td></tr></table>	PAGE	OF	03	05
YEAR	SEQUENTIAL NUMBER	REVISION NUMBER											
90	022	02											
PAGE	OF												
03	05												

TEXT (If more space is required, use additional NRC Form 365A's) (17)

The additional assessments added 92 to the total number of inoperable seals, while another 129 seals previously identified were resolved as operable, resulting in a net decrease of 37 for the total. In addition, the number of fire areas involved was increased from 25 to 26. As of the writing of Revision 1 to this report (submitted December 31, 1990), the numbers of nonfunctional fire barrier penetrations were:

- (1) approximately 423 of 3500 penetration seals,
- (2) 60 of 79 fire dampers, and
- (3) 7 of 79 fire doors.

On January 2, 1991, the walkdown inspections were completed. As a result, additional nonfunctional sealing devices were identified and appropriate compensatory measures were verified as implemented. This second revision fulfills the Special Report requirement of the Technical Specification for the additional nonfunctional penetrations identified.

The additional assessments added 36 to the total number of inoperable seals, while another 18 seals previously identified were resolved as operable, resulting in a net increase of 18 for the total. An additional nonfunctional fire damper was discovered. As of the writing of this report revision, the numbers of nonfunctional fire barrier penetrations are:

- (1) 441 of approximately 3500 penetration seals,
- (2) 61 of 79 fire dampers, and
- (3) 7 of 79 fire doors.

The noted fire barrier penetration sealing devices were declared nonfunctional because no prior documentation existed for them, or their configurations did not match those qualified by fire testing. These criteria were used as a result of NRC Information Notice 88-04, and were different from the criteria utilized in performance of periodic fire barrier penetration surveillances as required by Technical Specification 3.15(5).

Previous Technical Specification surveillances (the last completed in March of 1990) have verified that fire barrier penetrations were functional (intact) at least once per 18 months by visual inspection. When degraded barriers were found in the course of these surveillances, Technical Specification compensatory measures were established until the barriers were restored to functional status. Therefore, the cause of the reportable nonfunctional status of the fire barrier penetrations was not an actual short term deterioration of the barriers, but the identification of design basis deficiencies in the construction and/or documentation of the barriers.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Fort Calhoun Station Unit No. 1	DOCKET NUMBER (2) 0 5 0 0 0 2 8 5 9 0 -	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		0 2 2	-	0 2 0 4	OF	0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

As compensatory actions in compliance with Technical Specification 2.19(7), hourly fire watches established based upon verification of operable automatic fire detection on east one side of the affected fire barriers. These measures assure prompt response of the station fire brigade to preclude the spread of fire across any degraded fire barrier.

As noted in the Fire Hazards Analysis, Fort Calhoun Station overall has low fixed combustible loadings within its different fire areas, with the exception of the diesel rooms and the turbine building. The predominant share of inoperable fire barrier penetrations were found in those areas where the total fixed combustible loading is low. In the diesel rooms, additional protection is provided by an automatic dry pipe sprinkler system. The turbine building, which adjoins the auxiliary building, is provided with automatic fire detection and automatic water suppression for most areas where combustible loading is high. Transient combustibles and hot work activities are controlled by plant administrative procedures. OPPD management personnel are required by Standing Order G-6 to perform regular plant inspections for general housekeeping. An explicit purpose stated for this inspection is to "reduce to a minimum the amount of combustible material stored in safety related areas."

Many of the fire barrier penetrations determined to be inoperable are related only to licensing commitments made in response to Appendix A to Branch Technical Position 9.5-1. These barriers do not correspond to those committed to under the Fort Calhoun Station 10CFR 50, Appendix R analysis, and thus are not required to preserve safe shutdown capability. These barriers do not separate redundant trains of safe shutdown equipment and, therefore, the postulated breach of these barriers by a fire would have minimal safety impact.

The results of the fire barrier walkdown and assessment effort have been handled conservatively. As immediate corrective action, applicable technical specification LCO action statements were implemented for all fire barrier penetrations considered nonfunctional (inoperable). These measures will remain in place until the affected penetrations are restored to a functional (operable) status.

It is estimated that approximately 35 percent of the penetrations can be evaluated as functional. Guidance given in NRC Generic Letter 86-10 allows for evaluations to be performed for penetrations not sealed to the fire rating required of the boundaries. The purpose of the evaluation is to determine whether the fire area boundaries are sufficient to withstand the hazards associated with the fire area. Some barrier penetrations may be evaluated as justifiable in their current configuration. This work is on-going through 1991. Restoration of these penetrations to operable status through engineering evaluation is expected to be fully complete within 2 months following the end of the 1991 refueling outage.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 LRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

Fort Calhoun Station No. 1

YEAR SEQUENTIAL REVISION
NUMBER NUMBER NUMBER

0 5 0 0 0 2 8 5 9 0 - 0 2 2 - 0 2 0 5 OF 0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The approximately 65 percent of installed fire barrier penetrations which cannot be evaluated as functional will be repaired or replaced. A modification (MR-FC-90-072) has been initiated to perform this work. Implementation of this modification will be on-going through 1991. Because certain nonfunctional penetration sealing devices are inaccessible due to plant radiological conditions and energized electrical equipment, a plant outage will be required to implement required repairs or replacements. For this reason, the modification is expected to be completed within 2 months following the end of the 1991 refueling outage.

The upgrade of procedural controls and fire barrier as-built drawing information will be completed concurrent with the engineering evaluations and modification implementation discussed above. Drawings reflecting as-built configurations for repaired or replaced penetration sealing devices will be processed as part of the modification closeout. Upgrades planned for existing procedures with respect to fire barrier configuration control will be implemented separately but concurrently with the activities described above.

Other Special Reports have been submitted because of non-related instances of inoperable fire barriers; however, there have been no Special Reports or LERs submitted due to a generic cause affecting many barriers.