

**CONTROL BLOCK:**

					(1)
--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	(2)	0	0	-	0	0	0	0	0	-	0	0	(3)	4	1	1	1	1	(4)			(5)
7	8	9	LICENSEE CODE	14	15	LICENSE NUMBER	25	26	LICENSE TYPE	30	57	CAT	58																

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	8	7	1	0	2	3	8	1	8	1	1	0	4	8	1	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE					REPORT DATE									

0 2 | During normal operation at 0250, Instrument and Control personnel dis-

0 3 | covered that the Component Cooling Isolation valve to the containment,

0 4 | CC-3832-CV would fail open on a loss of instrument air or a loss of AC

0 5 | power, failing the valve in the unconservative position. The valve was

0 6 | immediately declared inoperable (T.S. 3.7.3.1). The valve was modified

0 7 | and tested before being declared operable at 0930. Similar event:

0 8 | 50-317/81-73.

SYSTEM CODE W B (11)		CAUSE CODE B (12)		CAUSE SUBCODE A (13)		COMPONENT CODE V A L V E X (14)		COMP. SUBCODE B (15)		VALVE SUBCODE D (16)	
EVENT YEAR 8 1 (22)		SEQUENTIAL REPORT NO. 0 4 5 (26)		OCCURRENCE CODE 0 1 (29)		REPORT TYPE T (31)		REVISION NO. 0 (32)			
ACTION TAKEN F (18)		FUTURE ACTION X (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22)		ATTACHMENT SUBMITTED Y (23)	
NPRD-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER N (25)		COMPONENT MANUFACTURER F 1 2 7 (26)							

1 0 Valve in question has been configured to fail open on a loss of  
1 1 instrument air or a loss of electrical power since before commercial  
1 2 operation began. A facility change request to modify the valve to  
1 3 fail closed on a loss of instrument air or a loss of electrical  
1 4 power was initiated in 1976, but not performed until 10-23-81. The

1 5 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Technician Observation 32

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NA NA

PERSONNEL EXPOSURES										
NUMBER		TYPE		DESCRIPTION						
1	7	0	0	0	37	2	0	0	0	NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

19		LOSS OF OR DAMAGE TO FACILITY		(43)
		TYPE	DESCRIPTION	
1	9	Z	(42)	NA

7 8 9 10  
 PUBLICITY  
 ISSUED DESCRIPTION (45)  
 (2) (0) N (44) NA  
 8111130427 811104  
 PDR ADOCK 05000318  
 S PDR  
 NRC USE ONLY  
 68 69 70

NAME OF PREPARER

G. S. Pavis

PHONE \_\_\_\_\_

301-269-4742

LER NO. 81-45/1T  
DOCKET NO. 50-318  
LICENSE NO. DPR-69  
EVENT DATE 10-23-81  
REPORT DATE 11-04-81  
ATTACHMENT

00130  
I 101037  
07 0 11 0 101107

#### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (CONT'D)

On October 22, 1981, after the discovery at 1530 that the Component Cooling Isolation valve to the Unit No. 1 containment, 1-CC-3832-CV, failed in the unconservative position on a loss of instrument air (LER 50-317/81-73), Instrument and Control (I&C) personnel were sent to determine the failed position of the corresponding Unit No. 2 valve. Based on the tubing arrangement to the solenoid valve, the Component Cooling Isolation Valve to the Unit No. 2 containment, 2-CC-3832-CV, was determined to fail in the conservative position (closed on a loss of instrument air) and thus, the valve remained operable. On October 23, 1981, after modifications to 1-CC-3832-CV were complete, the Resident Inspector requested that BG&E reverify the failed position of 2-CC-3832-CV. I&C personnel were immediately sent to determine the failed position of the valve. It was discovered and reported at 0230 that 2-CC-3832-CV would fail open on a loss of instrument air or a loss of electrical power. No actual loss of instrument air or electrical power occurred. The valve was declared inoperable at that time. The valve was modified and tested before being declared operable at 0930, thus terminating the event. Similar event: 50-317/81-73.

#### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

Plant Operating and Experience Assessment Committee (POEAC) is presently evaluating the circumstances surrounding the delay in implementing the FCR and determining what corrective action will be required. An updated LER will be submitted by December 1, 1981.