

CONTROL BLOCK: 

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

U.P.O. 917-926

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 81057 Technical Specification Involved Table 3.2.B

Reported Under Technical Specification 6.7.2.b(2) \*Date due NRC: 11/6/81

Date of Occurrence 10/7/81 Time of Occurrence 1030 Unit 3

Identification and Description of Occurrence:

Reactor water level switch LIS-3-58D switch #1 setpoint was found outside of limits of T.S. Table 3.2.B by 1.8 inches of water.

Conditions Prior to Occurrence:

Unit 1 at 46%.

Unit 2 at 100%.

Unit 3 at 92%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Instrument Drift.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

The switch was inspected, calibrated, successfully tested, and returned to service. DCR 1398 replaces this switch with an analog transmitter and trip switch.

Failure Data:

BFRO-50-260/80056.

\*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: SA