

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

09		SYSTEM CODE S F		11	CAUSE CODE X		12	CAUSE SUBCODE Z		13	COMPONENT CODE I N S T R U					14	COMP. SUBCODE S		15	VALVE SUBCODE Z		16	
7	8	9	10		11		12		13					14			15			16			
17		LER/RO REPORT NUMBER		EVENT YEAR 8 1		21	22	SEQUENTIAL REPORT NO. 0 9 4		24	25	26	OCCURRENCE CODE 0 3		28	29	REPORT TYPE L		30	REVISION NO. 0		32	
ACTION TAKEN B		18	FUTURE ACTION Z		19	EFFECT ON PLANT Z		20	SHUTDOWN METHOD Z		21	HOURS 0 0 0 0		22	ATTACHMENT SUBMITTED Y		23	NPRO-4 FORM SUB. Y		24	PRIME COMP. SUPPLIER N		25
32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

9	10	8111130611 811103										80
PUBLICITY		PDR ADOCK 05000324										NRC USE ONLY
ISSUED	DESCRIPTION	S PDR										
N	(44)	JA										
9	10	68 69										80

PHONE: (919) 457-9521

LER ATTACHMENT - RO #2-81-94

Facility: BSEP Unit No. 2

Event Date: 10/14/81

During the investigation of this event, an inspection of the switch housing cover and gasket revealed proper penetration integrity with no visible evidence of moisture invasion into the switch housing. It is suspected that prior to the initiation of a current program by a dedicated plant group to ensure proper seal integrity on electrical enclosures, regardless of environment type, as a result of IE Bulletin 79-01B, the housing cover and gasket of the N002 instrument manufactured by Robertshaw Company, may not have been securely fastened. Consequently, this could have permitted moisture to enter the switch housing and cause the observed corrosion which resulted in this event.

As a result of IE Bulletin 79-01B, plant maintenance practices have been revised to ensure proper penetration integrity following routine or repair maintenance to plant equipment. It is felt this will help in the prevention of similar events.