

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ALBRF3 200-000000-0003 411111 45  
7 8 9 14 15 25 30 57 CAT 58

CON'T  
01 REPORT SOURCE L 605000296 7101281 8110981 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, while performing SI 4.5.F.1.d & e, reactor core isolation  
03 cooling (RCIC) system, valve 3-FCV-71-34 failed to close. (T.S. 3.5.F.2) There was  
04 no danger to the health or safety of the public. Redundant systems were available  
05 and operable. There were no previous similar events.  
06  
07  
08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
9 10 11 12 13 14 15 16  
C E E A C K T B R K B Z  
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
21 22 23 24 25 26 27 28 29 30 31 32  
8 1 0 5 2 0 3 L 0  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
E Z Z Z 0 0 0 0 Y N L G 0 8 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The arcing shield was binding the contactor. The General Electric 600 volt, FVR,  
11 model IC 2800 1607 contactor was freed and properly aligned and successfully cycled  
12 several times, and SI's 4.5.F.1.c, and 4.5.F.1.d & e, performed to prove the RCIC  
13 operable. This is considered a random failure and no further recurrence control is  
14 required.  
15

16 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
E 0 9 1 NA B Surveillance test.  
17 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
Z Z NA NA  
18 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
48 49 50 51 52 53 54 55 56 57 58 59 60  
0 0 0 Z NA  
19 PERSONNEL INJURIES NUMBER DESCRIPTION  
61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
0 0 0 NA  
20 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
81 82 83 84 85 86 87 88 89 90  
Z NA  
21 PUBLICITY ISSUED DESCRIPTION  
91 92 93 94 95 96 97 98 99 100  
N NA

8111200620 811109  
PDR ADDOCK 05000293  
S PDR

Gene Holder

PHONE: (205) 729-614

LER SUPPLEMENTAL INFORMATION

BFRO-50-296/81059 Technical Specification Involved 3.5.F.2

Reported Under Technical Specification 6.7.2.b.2 \*Date due NRC: 11/11/81

Date of Occurrence 10/12/81 Time of Occurrence 1030 Unit 3

Identification and Description of Occurrence:

Valve 3-FCV-71-34 failed to close.

Conditions Prior to Occurrence:

Unit 1 at 99%.

Unit 2 at 81%.

Unit 3 at 91%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

The arcing shield was binding the contactor.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

The contactor was freed, properly aligned and successfully cycled several times and SI's 4.5.F.1.c., d, and e were performed to prove the RCIC operable. This is considered a random failure and no further recurrence control is required.

Failure Data: None

\*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: SLY