

CONTROL BLOCK:

						(1)
--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01		A L B R F 2		2000-0000-0000		34111111		45	
7		9		14		15		25	
L		6		05000260		7103081		8111281	
7		8		60		61		68	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	
01		01		01		01		01	
7		8		14		15		25	

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81059 Technical Specification Involved Table 3.2.B

Reported Under Technical Specification 6.7.2.A(5) *Date due NRC: 11/13/81

Date of Occurrence 10/30/81 Time of Occurrence 0820 Unit 2

Identification and Description of Occurrence:

Reactor low-pressure switch #1 of PS-3-74A and switch #1 of PS-68-95 were found out of T.S. limits.

Conditions Prior to Occurrence:

Unit 1 at 98%.

Unit 2 at 89%.

Unit 3 at 85%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Setpoint drift.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Setpoints were reset to the proper values, and the surveillance instruction completed satisfactorily, a design change request (DCR 1398) has been initiated to replace these switches with analog transmitters with trip switches.

FAILURE DATA: BFRO-50-259/78016, 79008, 80058, 81029; 260/78002, 79017, 79024, 80022, 80057, 81023, 81028; 296/79007, 79012, 79028, 80022, 80030, 80045, 80052, 81007,

*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: SLY