

# LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 T N S N P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

01 REPORT SOURCE L 6 0 5 0 0 0 3 2 7 7 1 0 2 5 8 1 9 1 1 2 3 8 1 2  
 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 0126 CST on 10/25/81 with Unit 1 in Mode 3, RCS temperature and pressure  
 03 at 390 degrees F and 1200 psig, auxiliary feedwater pump (AFWP) 1B-B would  
 04 not start after receiving a controller disagreement signal. This required  
 05 entry into the action statement of LCO 3.7.1.2. There was no effect on public  
 06 health or safety. Previous occurrences - none.  
 07  
 08  
 09

09 SYSTEM CODE C H 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE R E L A Y X 14 COMP SUBCODE A 15 VALVE SUBCODE Z 16  
 17 LER/RO REPORT NUMBER 8 1 21 22 1 3 0 23 24 0 3 25 26 L 27 28 0 29 30 31 0 32 33  
 ACTION TAKEN E 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUT/DOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 APPLICABLE FORM SUB N 24 PRIME COMP. SUPPLIER I 25 COMPONENT MANUFACTURER G 0 8 0 44  
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 Investigation revealed that the breaker would not operate due to the latching  
 1 relay being out of adjustment. The relay was adjusted, functionally tested,  
 2 and the pump was placed back in service at 1300 (CST) on 10/26/81.  
 3  
 4

5 FACILITY STATUS C 28 POWER 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32  
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
 6 ACTIVITY CONTENT RELEASED OR RELEASE Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36  
 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39  
 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41  
 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43  
 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ISSUED DESCRIPTION N/A 45  
 8112010671 811123  
 PDR ADOCK 05000327  
 S PDR  
 Name of Preparer W. D. Romine /M. R. Harding  
 Phone: (615) 842-8317  
 NRC USE ONLY