

[illegible]

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	5	4	7	1	0	2	7	8	1	8	1	1	1	0	8	1	9
60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

0 2 | On October 27, 1981, while performing a surveillance test on the Electrohydraulic  
0 3 | Control low pressure scram pressure switches, pressure switch 1-560C-PS-3 tripped  
0 4 | at 876 psig. The Technical Specification Table 3.1-3 requirement is greater than  
0 5 | or equal to 900 psig. The other switches in the one-out-of-two-twice logic were  
0 6 | found to trip above 900 psig; therefore, the consequences of the occurrence are  
0 7 | minimal. The system would have initiated a Reactor scram within the Technical  
0 8 | Specification limits.

SYSTEM CODE 0 9		CAUSE CODE I A		CAUSE SUBCODE E		COMPONENT CODE I N S T R U				COMP SUBCODE E		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER 17		EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 2 1		OCCURRENCE CODE /		REPORT TYPE L		REVISION NO. 0			
21	22	23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN E		FUTURE ACTION A		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB Y	
33	34	35	36	37	38	39	40	41	42	43	44	PRIME COMP. SUPPLIER N	
33	34	35	36	37	38	39	40	41	42	43	44	COM. INENT MANUFACTURER B 0 7 0	
33	34	35	36	37	38	39	40	41	42	43	44	26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 0 | The cause of this occurrence is instrument setpoint drift. The pressure switch

1 1 | was immediately recalibrated and functionally tested. This instrument has had an

1 2 | unsatisfactory history of drifting out of calibration and will be replaced.

1 3 | A new instrument has been ordered from the vendor and will be replaced during the

1 4 | next convenient outage following delivery.

8 9  
FACILITY STATUS      % POWER      OTHER STATUS (30)  
1 5 E (28) 0 9 7 (29) NA 44  
7 8 9 10 11 12 13

METHOD OF DISCOVERY      DISCOVERY DESCRIPTION (32)  
B (31) Routine Surveillance 80  
45 46

ACTIVITY CONTENT      (35)  
RELEASED OF RELEASE      AMOUNT OF ACTIVITY  
1 6 Z (33) Z (34) NA 44  
7 8 9 10 11 12 13

LOCATION OF RELEASE (36)  
NA 80  
45

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	000	(37) Z (38) NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	NA

1		9		Z		42		NA	
---	--	---	--	---	--	----	--	----	--

8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45)  
2 0 N (44) NA  
NRC USE ONLY

NRC USE ONLY

8112040227 811110  
PDR ADOCK 05000254  
S PDR

D. Hannum

PHONE 309-654-2241, ext. 193

CPO 91-7-426

- I. LER NUMBER: LER/RO 81-21/03L-0
- II. LICENSEE NAME: Commonwealth Edison Company  
Quad-Cities Nuclear Power Station
- III. FACILITY NAME: Unit One
- IV. DOCKET NUMBER 050-254
- V. EVENT DESCRIPTION:

On October 27, 1981, while performing surveillance test QIS-39, Loss of Electrohydraulic Control Fluid Pressure Scram, pressure switch 1-5/00-PS-3 was found to trip at 876 psig. This is 14 psig below the 900 psig setpoint requirement of Technical Specification Table 3.1-3. The other three pressure switches were found to be within the Technical Specification limit. Work Request Q15465 was written to investigate the problem.

VI. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

The four pressure switches are arranged in a one-out-of-two-twice logic to initiate a Reactor Protection System function upon loss of EHC pressure. Redundant switches were demonstrated to be within allowable limits; therefore, low EHC fluid pressure would have been sensed at the proper setpoint and a Reactor scram would have been initiated. Safe operation of the Reactor was not affected at any time.

VII. CAUSE:

The cause of this occurrence was instrument setpoint drift. The pressure switch is model C-9612-2, manufactured by Barksdale Company.

VIII. CORRECTIVE ACTION:

The immediate corrective action was to recalibrate the pressure switch setpoint. A functional test was then successfully performed to demonstrate the operability of the pressure switch. This pressure switch has a history of instrument drift and will be replaced like-for-like with a new pressure switch at a convenient outage following delivery of the new instrument from the vendor.