



Nuclear Group
P.O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 393-6000

April 30, 1990
ND3MNO:2058

Beaver Valley Power Station, Unit No. 1
Docket No. 50-334, License No. DPR-64
LER 90-007-00

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Gentlemen:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report is submitted:

LER 90-007-00, 10 CFR 50.73.a.2.iv, "Reactor Trip on "C" Steam Generator Low Level and Steam Flow/Feedwater Flow Mismatch Due to Closure of "C" Main Feedwater Regulating Valve".

Very truly yours,

T. P. Noonan
General Manager
Nuclear Operations

JT/sl

Attachment

9005030270 900430
PDR ADDCK 05000334
S PDC

IK22
11

April 30, 1990

ND3MNO:2058

Page two

cc: Mr. William T. Russell
Regional Administrator
United States Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, PA 19406

C. A. Roteck, Ohio Edison
76 S. Main Street
Akron, OH 44308

Mr. Peter Tam, BVPS Licensing Project Manager
United States Nuclear Regulatory Commission
Washington, DC 20555
J. Beall, Nuclear Regulatory Commission,
BVPS Senior Resident Inspector

Dave Amerine
Centerior Energy
6200 Oak Tree Blvd.
Independence, Ohio 44101

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

G. E. Muckle,
Factory Mutual Engineering, Pittsburgh
3 Parkway Center
Room 217
Pittsburgh, PA 15220

Mr. J. N. Steinmetz, Operating Plant Projects Manager
Mid Atlantic Area
Westinghouse Electric Corporation
Energy Systems Service Division
Box 355
Pittsburgh, PA 15230

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange Suite 245
270 Farmington Avenue
Farmington, CT 06032

Mr. Richard Janati
Department of Environmental Resources
P. O. Box 2063
16th Floor, Fulton Building
Harrisburg, PA 17120

Director, Safety Evaluation & Control
Virginia Electric & Power Co.
P.O. Box 26666
One James River Plaza

LICENSEE EVENT REPORT (LER)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--|--------|-----------|--------------|-------------------|-------|--------|-----------|--------------|---|--|--------|-----------|--------------|-------------------|-------|--------|-----------|--|-------------------|--|--------|-----------|--------------|-------------------|-------|--------|--|--------------|-------------------|--|--|--|--|--|--|--|--|--|--|
| FACILITY NAME (1) Beaver Valley Power Station, Unit 1 | | | | | | | | | | DOCKET NUMBER (2) 0 5 0 0 0 3 3 4 | | | | | | | | | | PAGE (3) 1 OF 0 3 | | | | | | | | | | | | | | | | | | | |
| TITLE (4) Reactor Trip on "C" Steam Generator Low Level and Steam Flow/Feedwater Flow Mismatch Due to Closure of "C" Main Feedwater Regulating Valve. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| EVENT DATE (5) MONTH DAY YEAR 0 3 3 0 9 0 9 0 | | | | | | | | | LER NUMBER (6) YEAR SEQUENTIAL NUMBER REVISION NUMBER 0 0 7 0 0 0 4 | | | | | | | | | REPORT DATE (7) MONTH DAY YEAR 9 0 | | | | | | | | | OTHER FACILITIES INVOLVED (8) FACILITY NAMES DOCKET NUMBER(S) N/A 0 5 0 0 0 0 N/A 0 5 0 0 0 0 | | | | | | | | | | | | |
| OPERATING MODE (9) 1 | | | | | | | | | | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| POWER LEVEL (10) 1 0 0 | | | | | | | | | | 20.402(b) 20.406(a)(1)(i) 20.406(a)(1)(ii) 20.406(a)(1)(iii) 20.406(a)(1)(iv) 20.406(a)(1)(v) | | | | | | | | | | 20.406(e) 50.36(e)(1) 50.36(e)(2) 50.73(a)(2)(i) 50.73(a)(2)(ii) 50.73(a)(2)(iii) | | | | | | | | | | <input checked="" type="checkbox"/> 50.73(a)(2)(iv) 50.73(a)(2)(v) 50.73(a)(2)(vi) 50.73(a)(2)(vii)(A) 50.73(a)(2)(viii)(B) 50.73(a)(2)(ix) 73.71(b) 73.71(c) OTHER (Specify in Abstract below and in Text, NRC Form 306A) | | | | | | | | | |
| LICENSEE CONTACT FOR THIS LER (12) NAME Thomas P. Noonan, General Manager Nuclear Operations | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | TELEPHONE NUMBER AREA CODE 4 1 2 6 4 3 - 1 2 5 8 | | | | | | | | | |
| COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| CAUSE | SYSTEM | COMPONENT | MANUFAC TURE | REPORTABLE TO NRC | CAUSE | SYSTEM | COMPONENT | MANUFAC TURE | REPORTABLE TO NRC | CAUSE | SYSTEM | COMPONENT | MANUFAC TURE | REPORTABLE TO NRC | CAUSE | SYSTEM | COMPONENT | MANUFAC TURE | REPORTABLE TO NRC | CAUSE | SYSTEM | COMPONENT | MANUFAC TURE | REPORTABLE TO NRC | CAUSE | SYSTEM | COMPONENT | MANUFAC TURE | REPORTABLE TO NRC | | | | | | | | | | |
| X | SIJ | TID | F | 1 3 0 | N | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SUPPLEMENTAL REPORT EXPECTED (14) | | | | | | | | | | | | | | | | | | | | EXPECTED SUBMISSION DATE (15) MONTH DAY YEAR | | | | | | | | | | | | | | | | | | | |
| YES (if yes, complete EXPECTED SUBMISSION DATE) | | | | | | | | | | | | | | | | | | | | <input checked="" type="checkbox"/> NO | | | | | | | | | | | | | | | | | | | |

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 3/30/90 at 1541 hours, with the Unit in Power Operation at 100% reactor power, alarms indicating a Loop "C" steam flow/feedwater flow mismatch, followed by a "C" steam generator (SG) level deviation were received. The operators noted closure of the "C" Main Feedwater Regulating Valve, FCV-FW-498. The operator tried to manually open FCV-FW-498, however, the valve would not respond. At 1544 hours, a reactor trip on "SG "C" Low Level & Feedwater Flow Low" occurred. Control Room personnel entered Emergency Operating Procedures, E-0 and ES-0.1, to stabilize the plant in Hot Standby. The cause for the reactor trip was the closure of FCV-FW-498, in response to insufficient instrument air pressure supplying the valve positioner. Air pressure had degraded due to moisture in the filter in the instrument air regulator for the valve positioner. High moisture was present due to the instrument air dryer being unavailable. The moisture in the instrument air system has been removed and the instrument air dryer has been returned to service. There were no safety implications as a result of this event. The plant systems responded as designed (all rods inserted, turbine trip occurring and auxiliary feedwater initiating on low SG level), with the exception of FCV-FW-498, to place the plant in Hot Standby. This event is bounded by Updated Final Safety Analysis Report, Section 14.1.8.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| FACILITY NAME (1) | DOCKET NUMBER (2) | LER NUMBER (6) | | | PAGE (3) | | |
|-------------------------------------|-------------------|----------------|-------------------|-----------------|----------|----|-----|
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| Beaver Valley Power Station, Unit 1 | 0 5 0 0 0 3 3 4 | 9 0 | — 0 0 7 | — 0 0 | 0 2 | OF | 0 3 |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION

On 3/30/90 at 1541 hours, with the Unit in Power Operation (Operating Mode 1) at 100% reactor power, Control Room personnel received an annunciator indicating a Loop "C" steam flow/feedwater flow mismatch, followed by a "C" steam generator (SG) level deviation. The operators observed the "C" Loop feedwater flow and noted that the "C" SG feedwater flow and the level were rapidly decreasing. The operator also noted closure of the "C" Main Feedwater Regulating Valve, FCV-FW-498, even though the valve positioner controller was outputting a 100% full open signal. Using the manual controller, the operator tried to manually open FCV-FW-498, however, the valve would not respond. At 1544 hours, a reactor trip on "SG "C" Low Level & Feedwater Flow Low" occurred. Control Room personnel entered Emergency Operating Procedure, E-0 "Reactor Trip and Safety Injection" and transitioned to ES-0.1 "Reactor Trip Response", after verifying that a Safety injection Signal was not required, to stabilize the plant in Hot Standby (Operating Mode 3).

CAUSE OF THE EVENT

The cause for the reactor trip was the partial closure of the "C" Main Feedwater Regulating Valve, FCV-FW-498. The closure of FCV-FW-498 resulted from an insufficient supply of instrument air to the valve positioner. Moisture in the instrument air supply had plugged the filter in the air regulator for the current-to-pneumatic valve positioner for FCV-FW-498, causing the valve to close. This moisture was present in the instrument air system as a result of the instrument air dryer being out of service. While the air dryer was out of service, the air compressors' discharge was directed through the instrument air bypass filters. These filters are two-stage filters consisting of a wool felt pad and an absorbent silica gel canister. Although the filters are not as efficient as the dryer at removing moisture, they are capable of providing dry air on a temporary basis. On 3/21/90, the air dryer was removed from service for maintenance. The instrument air bypass filters remained in service for an extended period of time. During this period, although the station initiated the vendor recommended compensatory actions of blowing down the filter once per eight hours, moisture accumulated in the air lines, resulting in this event.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

| | | | | | | | |
|--|--|----------------|-------------------|-----------------|----------|----|-----|
| FACILITY NAME (1) Beaver Valley Power Station, Unit 1 | DOCKET NUMBER (2) 0 5 0 0 0 3 3 4 | LER NUMBER (6) | | | PAGE (3) | | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| | | 9 0 | 0 0 7 | 0 0 | 0 3 | OF | 0 3 |

TEXT (If more space is required, use additional NRC Form 360A's) (17)

CORRECTIVE ACTION

The following corrective actions have been taken as a result of this event:

1. Operations personnel, utilizing the Emergency Operating Procedures, stabilized the plant in Hot Standby.
2. Air operated valves in the Turbine Building and Primary Auxiliary Building were blown down to remove any moisture within the instrument air lines. Small amounts of moisture was found in various valves within both buildings.
3. The Main Feedwater Regulating Valves were inspected and repaired as necessary. The instrument air lines for these valves were blown down to remove any moisture.
4. The instrument air dryer was returned to service.
5. A temporary diesel air compressor was placed in service to supplement the existing station air compressors and to allow the use of an additional air dryer, which could not be used because the station air compressors did not have sufficient capacity to supply the new air dryer and maintain instrument air pressure.
6. An engineering evaluation of the instrument air system is being performed.
7. The anti-rotation pin in the plug assembly for the "C" Main Feedwater Regulating Valve was repaired.

SAFETY IMPLICATIONS

There were no safety implications as a result of this event. The plant systems responded as designed (all shutdown bank and control rods inserted, turbine trip occurring and auxiliary feedwater initiating on low SG level following the SG level "shrink" resulting from the loss of secondary load), with the exception of the "C" Main Feedwater Regulating Valve which did not fully close and was isolated by closing the motor operated feedwater isolation valve, to place the plant in Hot Standby (Operating Mode 3) conditions. This event, feedwater perturbations due to valve malfunctions, is bounded by the Updated Final Safety Analysis Report (UFSAR), Section 14.1.8, "Loss of Normal Feedwater".

REPORTABILITY

This event was reported to the Nuclear Regulatory Commission at 1810 hours on 3/30/90, in accordance with the requirements of 10 CFR 50.72.a.2.ii. This written report is being submitted in accordance with the requirements of 10 CFR 50.73.a.2.iv.