

1992

SPECIAL EDITION

NATIONAL BOARD BULLETIN



An Official Publication of The National Board of Boiler and Pressure Vessel Inspectors

SPECIAL REPORT:

THE CHINESE FLANGE
INVESTIGATION


9304080060 930318
PDR ADOCK 05000443
U PDR

BULLETIN

1992 • VOLUME 48 • NUMBER 2

SPECIAL EDITION

LETTER FROM THE ACTING EXECUTIVE DIRECTOR	1
PREFACE	3
LAB REPORTS	7
MILL REPORTS	43
MARKINGS, DESCRIPTIONS & PHOTOGRAPHS	49
LETTER OF RESPONSE FROM CBPVI	55

Since 1919  The
National
Board
of Boiler
and Pressure
Vessel Inspectors

A. M. Matthews, Jr.
Acting Executive Director
P.D. Brennan, APR,
Director of Communications
J. M. Webster, *Administrative Assistant*
L. C. Nixon, *Publications Assistant*

Board of Trustees

R. A. Coomes, *Chairman*
H. T. McEwen, *First Vice Chairman*
M. E. Skarda, *Second Vice Chairman*
A. M. Matthews, Jr., *Secretary-Treasurer*
W. E. Brown, *Member at Large*
M. H. Diehl, Jr., *Member at Large*
M. Kotb, *Member at Large*
A. J. Justin, *Past Chairman*

Advisory Committee

R. L. Allison, *representing boiler manufacturers*
M. J. Boede, *representing organized labor*
W. D. Doty, *representing welding industries*
R. C. Howard, *representing authorized (insurance companies) inspection agencies*
E. C. Kistner, *representing boiler and pressure vessel users*
R. I. Mullican, *representing pressure vessel manufacturers*
R. H. Murray, *representing boiler and pressure vessel users*

The National Board of Boiler and Pressure Vessel Inspectors was organized for the purpose of promoting greater safety to life and property by securing concerted action and maintaining uniformity in the construction, installation, inspection and repair of boilers and other pressure vessels and their appurtenances; thereby

assuring acceptance and interchangeability among jurisdictional authorities responsible for the administration and enforcement of the various sections of the ASME Boiler and Pressure Vessel Code.

The *Bulletin* is published quarterly by The National Board of Boiler and Pressure Vessel Inspectors, 1055 Crupper Ave., Columbus, Ohio 43229-1183. 614/888-8320. Postage paid at Columbus, Ohio.

Postmaster: Send address changes to The National Board of Boiler and Pressure Vessel Inspectors, 1055 Crupper Ave., Columbus, Ohio 43229-1183.

Points of view, ideas, products or services featured in the *Bulletin* do not necessarily constitute endorsement by the National Board, which disclaims responsibility for authenticity or accuracy of information contained herein. Address all correspondence to the Publications Department, The National Board of Boiler and Pressure Vessel Inspectors, at the above address.



The
National
Board
of Boiler
and Pressure
Vessel Inspectors

September 1992

Dear BULLETIN Readers:

A. M. Matthews, Jr., Acting Executive Director

For approximately the last year, The National Board of Boiler and Pressure Vessel Inspectors has been investigating flanges - made in China and distributed in the United States, Canada and possibly Central and South America - that may be a considerable threat to both lives and property.

By publishing this BULLETIN Special Report, it is our intent to impart the Board's findings in an objective, factual manner. What follows is a series of reports and photos that illustrate the nature of our investigation.

Because of the poor reproductive quality of many of the materials we have gathered, you will note that some sections of this Special Report are not up to the BULLETIN's usual standards. In this single instance, we felt it was more important to present much of the factual material in its original form without benefit of editorial or graphic enhancement. Such is our commitment to letting the reader draw his or her own conclusions.

ONE SIGNIFICANT CAUTION: these suspect flanges are not unique to industrial operations. They may be found anywhere pressure piping, boilers and pressure vessels are employed, including many public institutions. We remind the reader that heat numbers are of particular importance when identifying suspect flanges.

Any questions concerning flanges manufactured in China should be forwarded to the office of the National Board director of inspections at 614/888-8320. Written correspondence may be sent to the National Board at 1055 Crupper Avenue, Columbus, OH 43229-1183. The National Board has contacted China's State Council of the Communist Party Central Committee and the China Centre of Boiler and Pressure Vessel Inspection and Research (CBPVI) of the Ministry of Labour P.R.C.

On August 31, the National Board office received correspondence from CBPVI. The State Import and Export Commodities Inspection and Testing Bureau has issued an order that as of January 1, 1993, flanges, fittings and tubes for boiler and pressure vessel use will require mandatory inspection and testing by the CBPVI and/or other Chinese government inspection agencies. These inspected products will bear the inspection mark of the respective agency. A copy of this correspondence is included as the closing section of this Special Edition. We intend to meet with the CBPVI early in October to obtain details of this plan and to obtain facsimiles of the inspection marks for publication in the Winter 1993 BULLETIN.

The National Board extends its genuine gratitude to Mr. Al Justin, chief boiler inspector, State of Minnesota, for bringing this potentially dangerous problem to our attention.

Although our investigation has been long and arduous, we at the National Board now have sufficient information to alert our membership, BULLETIN readers, and the world of this relatively little-known but potentially explosive situation.

For 73 years, the National Board has monitored the boiler and pressure vessel industry to assure that when it comes to safety, there are no compromises.

It is not our promise. It is our commitment.

Sincerely,

A. M. Matthews, Jr.

A. M. Matthews, Jr.
Acting Executive Director

1055 Crupper Avenue
Columbus, Ohio 43229-1183 U.S.A.

Board
of
Trustees

E. A. COOMBS
Chairman
Commonwealth of Kentucky

First Vice Chairman

Phone (614) 888-8320
FAX (614) 888-0750 (Executive)

M. E. SCARDA
Second Vice Chairman
State of Arkansas

W. E. BROWN
Member at Large
State of Kansas

M. H. DINI, Jr.
Member at Large
State of Maryland

M. KON
Member at Large
Province of Quebec

A. J. JARA
Past Chairman
State of Minnesota

FAX (614) 847-1825 (Technical)
FAX (614) 848-3474 (Pres. Relief Dept.)

PREFACE

This special edition of the *BULLETIN* has been published in the interest of public safety. The National Board has, for the past several months, been conducting an extensive investigation of flanges produced in China and identified as conforming to ANSI B16.5 and ASTM A105.

In the opinion of the National Board, the flanges identified in this special edition may not meet the criteria of the ANSI standard or ASTM specification noted above. Furthermore, use of these products which are subject to stress due to pressure, may create an extreme hazard to personal safety and property. Within the pages of this *BULLETIN*, we are presenting complete and/or partial copies of laboratory test reports of various flanges carried out by the National Board and other groups. These reports identify flanges that have been fabricated from two (2) pieces of steel, and flanges that have had voids filled with steel rods and face welded to give the appearance of being solid. We also possess a report concerning the use of unknown specifications of steel plate being used to produce flanges of various types. In reading this *BULLETIN*, you will learn of all problems reported to and uncovered by the National Board.

Where possible, we have identified the manufacturer of the flanges. One problem encountered as this investigation proceeded was the lack of evidence that any flange was marked with the manufacturer's name or trademark, as required by ANSI B16.5. In fact, the National Board representative conducting this investigation was informed that a Hong Kong trader was specifying to the flange manufacturer exactly what marks to stamp on each flange. The flanges observed by or reported to the National Board are for the most part, marked with initials that are mistakenly thought to be manufacturers. Some flanges do not even have initials.

The marks and test reports that appear in this article do have a value in that they are consistent in use. That is, the flanges produced by SHOU GANG MACHINERY ENGINEERING CO. and further reported in this *BULLETIN* have slugged weld repairs. These flanges are marked with a heat number 1-406 and are expected to appear on 150 flanges, as reported on that line item of the SHOU GANG MACHINERY ENGINEERING CO. test report.

This same trading company representative reported to the National Board that the steel mills in China do not produce ASTM A105 forgings. One Chinese agency also reported that Chinese-produced ASME boilers and pressure vessels contain flanges not produced in China but rather imported from other countries. At this time, the National Board has not determined the validity of this statement. If so, the chances of purchasing flanges produced in China that are in compliance with the ANSI B16.5 standard or ASTM A105 are indeed remote.

Finally, the National Board was informed that the material used by DING XINANG NAN XI LI FLANGE FACTORY was NOT ASTM A105 although the product is clearly marked A105. It was reported the material used was either 25MN or 16MN, both Chinese steel specifications, and not identical to A105. It was also reported that DING XINANG NAN XI LI FLANGE FACTORY

shipped six or seven containers of flanges, each weighing 17 tons. Although it is reported that each flange is marked both B16 and A105, according to the information, no flange was produced using A105 material.

On May 28, 1992, a representative from the National Board met in Beijing, China with members of the State Council of the Peoples Republic of China and the Centre of Boiler and Pressure Vessel Inspection and Research. This meeting was in response to correspondence addressed to Mr. Su Rung Ju, Vice Premier, Peoples Republic of China, from the National Board. This correspondence was drafted when it was learned that the Vice Premier had recently initiated a quality program to further China's entry into the world market. The program is titled "Quality Long March," after Mao Tse Tung's long march during the revolution. Since that meeting, there has been considerable contact between various agencies of the Chinese government and the National Board. To date, no solution has been found. However, several additional agencies have become involved in an attempt to provide solutions.

Information has been provided to the United States Customs Service and the Nuclear Regulatory Agency, to alert the various agencies of the information received by the National Board on these products. In the interim, the National Board has been advised of several failures of different types of equipment involving flanges produced in China. Fortunately, the failures reported have been found during hydrostatic tests or during in process inspections. Inservice failure of equipment has, to date, not been reported.

LAB REPORTS

FAILURE ANALYSIS OF A SLIP-ON FLANGE

The installation of a 14" slip-on flange in a pipeline was recently witnessed by Al Justin, chief inspector for the State of Minnesota. The flange originally had a 14-3/4" inside diameter, which was reduced by welding a 3/4" ring and machine welding. The ring, however, separated from the flange, giving the appearance of a crack. The flange is reported to have been manufactured in the People's Republic of China.




Figure 1: Gasket side of flange.

Several such flanges have been reported in the field. All individuals in the industry should be on the alert for these flanges.

The following is a report by Columbus Metallurgical Services, Inc. on the failure analysis of a slip-on flange.

A "cracked" 14" diameter slip-on flange was non-destructively inspected by using magnetic particle, dye penetrant and ultrasonic test methods. The flange was also checked for material chemical analysis and macro and microstructure. On the basis of the results and observations reported, the following conclusion is drawn:

The subject slip-on flange is not an integral forging or a casting. It has been fabricated by welding and machining a ring insert within a large diameter flange. The flange "cracked" because the welds between the flange and the insert were inadequate to withstand the bolting pressures.




Figure 2: A close-up of the gasket side showing the "crack" indication.

BACKGROUND

The "cracked" slip-on flange was received by Columbus Metallurgical Services, Inc. in one piece. It had two diametrically opposite cracks located on pipe and gasket sides. It has been reported that several such flanges are in the field. The subject flange has the following engraved markings on the outside diameter (OD):

"14 300 SO RF B16.5 A105 848 CHINA 02F"

To identify the cause of the failure it was planned to perform dye penetrant, dry magnetic particle, ultrasonic and radiographic tests on the subject flange.

NON-DESTRUCTIVE TESTS

First, the flange was UT tested from the OD. The indications were rather puzzling because the reflections were consistently from a cylindrical surface about 3.75" from the OD. A dry magnetic particle examination confirmed that the cracks extended more or less continuously in a circular path. The NDT examination was concluded with dye penetrant tests as shown in the photographs in Figures 1 through 4. It was quite evident that the flange was not a single piece component. A large inside diameter (ID) flange was reduced to a 14" ID unit by welding a 0.75" thick ring. The welding faces had been machined.




Figure 3: Pipe side of flange.

CHEMICAL ANALYSES AND METALLOGRAPHY

The flange was sectioned into four pieces to obtain specimens for chemistry, as well as for macro and microscopic examination. The original engraved markings have been retained on one of the segments. The chemical analyses are as follows:

C	Mn	P	S	Si	Cu	Sn	Ni	Cr	Mo	Al	V
Main Flange Steel											
.23	.62	.024	.038	.24	.27	.016	.094	.079	.026	.006	.003
Welded Insert Steel											
.26	1.02	.017	.039	.28	.063	.003	.050	.046	.032	.008	.000
ANSI/ASTM A 105											
.35	.60-1.05	.040	.050	.35	[.4*		.4*	.3*	.12*		.03*]

* Sum shall not exceed 1.00%. Indicates maximum percent allowable.



Figure 4: A close-up of the pipe side showing the "crack".




Figure 5: A macro of a radial section. Etched 50% HCl, 15 minutes.

Figure 5 shows the radial macro section of the flange. Note the insert ring welded to the main flange. When another similar piece was further sectioned to retrieve specimens for mounting and polishing, the insert separated from the main flange. The general microstructure (ferritic-pearlitic) at 25X (Nital etch) is shown in Figure 6.

ROCKWELL HARDNESS TEST

Main Flange:	72,69,70 HRB	Ave =
	70 HRB	
Insert:	76,78,80 HRB	Ave =
	78 HRB	

No further work was deemed necessary❖




Figure 6: Photo showing general microstructure in the main flange (lower half), insert (upper half) and weld metal (left edge), 25X, Nital etch.

REPORT

EVALUATION

OF

FLANGE B16.5 105 N SO 81D 1-406
AND BLANK PF 105 B16.5 012 CHINA BL

prepared for

THE NATIONAL BOARD OF BOILER AND
PRESSURE VESSEL INSPECTORS

by

WELDING CONSULTANTS, INCORPORATED

June 3, 1992

EXECUTIVE SUMMARY

Welding Consultants, Inc. received, 5/12/92, a portion of a flange and blank for analysis. It is suspected the material is either not forged ASTM A105 material as was specified or was misfabricated and "slugged" (addition of non-homogeneous filler) to correct for under dimensioning or local defects.

The scope of this evaluation is the following:

1. Photograph portions of the flange which appear to have some type of "slugging".
2. Perform chemical analysis of the flange and blank material and compare with the accepted ranges for ASTM A105.
3. Perform tensile tests for each component and compare with the ASTM specification for A105.
4. Cross section and metallurgically prepare the flange and blank to observe the microstructural characteristics which would indicate the material had or had not been forged.

The non-fused filler or "slugging" appears to be two 1/8 inch diameter rounds welded in place and subsequently machined. See photographs in Figure 2.

It can be seen the "slugging" has resulted in very little substratum for the fillet weld shown in Figure 2a.

The chemical analysis revealed only one discrepancy between ASTM A105 and the material tested: the sulfur content for the flange was found to be 0.075% compared to 0.050% maximum as listed in the specification. See Table I. It could be argued that this high sulfur content is significant when one considers the tendency of steels to hot crack when the sulfur content approaches the accepted maximums of 0.04% to 0.05%, sulfur content of 0.075% becomes more suspect.

The tensile test results comply with the ASTM A105 specification.

The cross sectioning of the flange and blank revealed microstructure consistent with hot rolled plate steel. See Figure 2a and 2b. It should be noted the chemistry of the materials tested comply with the compositional requirements of A105 with the exception of the sulfur content of the flange.

INTRODUCTION

On June 12, 1991, Welding Consultants, Inc. received a section of a suspect flange and blank for analysis. The material was supposed to have been forged ASTM A105 steel.

The compliance of this material with the A105 specification will be tested by chemical analysis and by tensile tests.

Often times, a forging is specified for a particular application because of the desirable orientation of grains. A crane hook, for example, may have a forging procedure designed to increase its resistance to opening. That is, it will contain residual stresses which will tend to pull the hook closed. Evidence of the forging operation can be detected by polishing and etching a cross section and observing the appearance and orientation of the grains.¹

In this case, it is suspected the flange and blank have been fabricated from rolled plate rather than a forging. This will be proven by cross sectioning and etching each component and observing the microstructure.

Lastly, evidence has been found which would indicate the outer rim of the flange face has been built up by the addition of some form of non-fused filler or "slugging". The danger of this situation is obvious.

The nature of the "slugging" will be evaluated here.

1. Reference - American Society of Metals, Metals Handbook Volume 9, USA, 1985, Page 176.

PROCEDURE

The analysis of the flange and blank material proceeded as follows:

1. Chemical analysis was performed using an Angstrom V-70 Vacuum Spectrometer.
2. Tensile testing was performed according to ASTM A370 using a Southwark Emary 200,000 pound tensile machine.
3. The cross sectioning of the flange material was accomplished using a Marvel band saw. The polishing was accomplished in two steps: 1. the samples pictured in Figure 1a and 1b were prepared using rotary sanding equipment; 2. a final polish was accomplished using nap cloth and 15 micron alumina powder. The samples were etched using 5% Nital.

RESULTS

The type of material was tested by chemical analysis and tensile tests. The results are contained in Table I and Appendix I respectively. The sole discrepancy between the ASTM specification and the analysis is the sulfur content of the flange: actual analysis = 0.075% S compared to 0.050% S maximum according to ASTM A105. It could be argued that this high sulfur content is significant when one considers the tendency of steels to hot crack when the sulfur content approaches the accepted maximums of 0.04% of 0.05%, sulfur content of 0.075% becomes more suspect.

The suspicion is that the material was not forged, but was fabricated from rolled plate. The decision was made to cross section and metallurgically prepare portions of the material to observe the nature of the microstructure. The photomicrographs shown in Figure 1a and 1b are evidence the flange and blank, respectively, are fabricated from rolled plate. The somewhat elongated grains particularly noticeable in the photomicrograph of the blank are typical of hot rolled steel.

Finally, the nature of the non-fused filler was to be determined. By simply cross sectioning the flange, the sample picture in Figure 2c was easily separated from the rest of the flange manually. The non-fused filler was found to be a pair of 1/8 inch rounds evidently welded to increase the size of or repair defects in the flange. Figure 2b shows the "slugging" extending around the flange. This situation was found in several other locations around the circumference.






Figure 1. Appearance of Grain Structure of a) the Flange, and b) the Blank Showing Elongated and Grains Indicative of Hot Rolled Plate.


It can be seen the "slugging" has resulted in very little substratum for the fillet weld shown in Figure 2a and 2b.



2a



2b



2c

Figure 2. Appearance of Non-fused Filler or Slugging.

TABLE I. Results of Chemical Analysis


ID	C	MN	P	S	Si	Cu	Sn	Ni	Cr	Mo	Al
Flange	.31	.84	.040	.075	.25	.16	.015	.051	.14	.016	.033
Blank	.21	.89	.019	.037	.22	.16	.017	.051	.027	.017	.033
A105 Spec.	.035*	.6-1.05	.040*	.050*	.35*	.40*	--	.40*	.30*	.12*	--
	V	Nb	Zr	Ti	B	Ca	Co	Pb			
	.001	.000	.000	.001	.0002	.0005	.011	.00			
	.000	.000	.000	.001	.0001	.0005	.012	.00			
	.030*	.02*	--	--	--	--	--	--			

* Indicates maximum percent allowable
 -- Indicates no specified limit



CONCLUSIONS

The conclusions of this study are the following:

1. Neither the flange nor the blank were forged steel. It is evident they were both fabricated by machining hot rolled plate.
2. The flange was built up by the insertion of a non-homogeneous filler which was intended to either repair defects in the original fabrication or to compensate for under dimensioning. The filler or "slugging" appear to be two 1/8" diameter rounds welded in place (poorly) and subsequently machined.



Slip-on raised-face flange.



Blind flange marked as A105 is a rolled plate product.

Welding Consultants, Inc.

Professional Engineering and Inspection Services Worldwide

July 30, 1992

The National Board of Boiler and Pressure Vessel Inspectors
Attn: Mr. A. M. Matthews, Jr.
1055 Crupper Avenue
Columbus, OH 43229

SUBJECT: CHINESE FLANGE ANALYSIS
FLANGE ID: 4-300 B16 A105N W/N STD 4-1 CHINA WW

Doc:

Per your request, an analysis has been conducted on the above-referenced weld neck flange that was picked up at your office on Monday, July 27, 1992. The following is a summary of the work performed and the results of the investigation. Figure 1 below shows the layout of the flange and the locations of test samples.




Figure 1, Flange layout and sample locations

When the flange was first received, a visible crack was evident at the transition between the flange and the weld neck. There also appeared to be machining grooves in this same vicinity. To verify the extent of cracking, the flange was subjected to penetrant testing. As can be seen in Figures 2 and 3 below, there was more cracking evident than could be detected visually. In fact, more than 75% of the circumference exhibited cracking.

CHINESE FLANGE ANALYSIS
Flange ID: 4-300 B16 A105N W/N STD 4-1 CHINA WW
July 30, 1992




Figure 2, Penetrant test indications




Figure 3, Penetrant test indications

CHINESE FLANGE ANALYSIS

Flange ID: 4-300 B16 A105N W/N STD 4-1 CHINA WW

July 30, 1992

Section A was removed from the region identified in Figure 1. This section was polished and etched to for metallurgical examination. Of initial interest was whether the flange had been fabricated from more than one piece of material. Once the etched surface was visually examined, it was apparent that the flange had been machined from a single piece of metal.

Next, it was necessary to determine whether the flange was a forged material or whether it had been machined from a plate product or a casting. This information was provided once Section A was examined under a microscope. Figure 4 shows the microstructure of the material in the vicinity of the visible crack at the weld neck-flange transition.




Figure 4, Section A microstructure at visible crack location
(50X, Nital etch)

Figure 4 vividly depicts the presence of material flow lines which is indicative of a forged material. Further, the fact that the grain structure appears relatively equiaxed indicates that this material was most likely subjected to a normalizing heat treatment following the forging operation. Another observation here is the fact that the apparent crack did not appear to have a sharp end condition, plus it was quite wide compared to its depth. Neither of these characteristics are typical for a crack.

CHINESE FLANGE ANALYSIS

Flange ID: 4-300 B16 A105N W/N STD 4-1 CHINA WW

July 30, 1992

To obtain some additional information, a second section was removed at location B (see Figure 1). At this location, a crack had been noted during penetrant testing; however, it appeared to be much tighter than that appearing at Section A. Once removed, this section was also subjected to metallurgical polishing and etching. The result appears in Figure 5.




Figure 5, Section B microstructure at crack location
(50X, Nital etch)

This cross section also shows an uncharacteristic crack indication. Further, there is increased evidence of flow lines at the end of the indication. Based on these observations, it is felt that the indications noted on this flange are the result of poor forging practice which resulted in a forging lap at the weld neck-flange transition.

The final information to be gained from this analysis involves the material chemistry. This will help determine whether this flange material is in compliance with the chemical requirements for SA105 material. The results of this chemical analysis appear in the table on the following page.

Looking at those results, it is apparent that this flange material has a chemical composition that complies with the requirements of SA105.

Chemical Composition

Element	Amount Present	SA105 Requirement
Carbon	0.19	0.35 max
Manganese	0.71	0.60 - 1.05
Phosphorus	0.020	0.040 max
Sulfur	0.021	0.050 max
Silicon	0.31	0.35 max
Copper	0.15	0.40 max
Nickel	0.063	0.40 max
Chromium	0.043	0.30 max
Molybdenum	0.016	0.12 max
Vanadium	0.002	0.03 max
Columbium	0.000	0.02 max

Conclusions

Based on this analysis, the following conclusions can be made:

- 1) This flange is a forgir.g.
- 2) It was normalized following the forging operation.
- 3) The material complies with the chemical composition requirements of SA105.
- 4) The crack-like indications are forging laps resulting from poor forging practices.

CHINESE FLANGE ANALYSIS

Flange ID: 4-300 B16 A105N W/N STD 4-1 CHINA WW


July 30, 1992

Doc, hopefully this information will be sufficient at this time. Should you require any further information or analysis, just give me a call. I will be returning all of the sample pieces to your office.

Thank you for allowing us to provide this service.

Sincerely,

WELDING CONSULTANTS, INC.

A handwritten signature in black ink, appearing to read 'R. Holdren', written over the printed name.

Richard L. Holdren, P.E.

Vice President/Welding Engineer

Welding Consultants, Inc.

Professional Engineering and Inspection Services Worldwide

August 28, 1992

Mr. John D. McLoughlin
The National Board of Boiler and Pressure Vessel Inspectors
1055 Crupper Avenue
Columbus, OH 43229

SUBJECT: ANALYSIS OF CHINESE FLANGES

John:

Per your instructions, an analysis has been performed on two flanges produced by two Chinese manufacturers. One was a slip-on configuration while the other was a weld neck type flange. The identification markings are as shown below:

Weld Neck: DSI 4-150 RF B16 A105N W/N STD 075 CHINA

Slip-on: LEO 4-150 RFSO B16 A105N T M1-300 CHINA *

* The "N" had been "x"-ed out with a steel stamp.

Our goal was to determine if the chemistries comply with SA105 requirements, whether the material had been forged, and if the material had been normalized. The results of these analyses appear on page 2 of this report.

As can be seen from the chemical analyses, the compositions are acceptable with respect to the requirements of SA105 with the exception of the excessive amount of manganese present in the slip-on flange.

Brinell hardness tests were performed on each of the samples. The weld neck flange exhibited an average hardness of 158 BHN which is approximately equivalent to 78,000 psi. The slip-on flange had an average hardness of 176 BHN, or an equivalent tensile strength of approximately 85,000 psi. Both of these values are in compliance with the strength requirements of SA105 material.

Chemical Analyses

Element	SA105 Requirement	Weld Neck Composition	Slip-on Composition
Carbon	0.35 max.	0.23	0.28
Manganese	0.60 - 1.05	0.69	1.17
Phosphorus	0.040 max.	0.017	0.013
Sulfur	0.050 max.	0.03	0.03
Silicon	0.35 max.	0.21	0.29
Copper	0.40 max.	0.083	0.19
Nickel	0.40 max.	0.072	0.016
Chromium	0.30 max.	0.039	0.010
Molybdenum	0.12 max.	0.019	0.011
Vanadium	0.03 max.	0.000	0.000
Columbium	0.02 max.	0.000	0.000

Cross sections were removed from each of the flanges and polished to reveal the materials' microstructures. Figures 1 through 4, on the following pages, illustrate the polished and etched surfaces of each sample at both 50X and 100X magnifications.




Figure 1, Weld Neck, 50X, Nital Etch




Figure 2, Weld Neck, 100X, Nital Etch




Figure 3, Slip-on, 50X, Nital Etch




Figure 4, Slip-on, 100X, Nital Etch


Several features are revealed through these photomicrographs. First, the material does not appear to be a forging, nor do they appear to be normalized. However, it is difficult to determine from this brief analysis whether the materials are rolled plate or cast. The presence of extensive numbers of spherical inclusions, and the microstructural appearance suggests the possibility of these being cast materials; however, it is difficult to positively determine without further polishing and microstructural analysis. Should you wish to pursue this further, please let us know. The fact that there is no sign of flow lines is evidence that these are not forgings.

John, hopefully this information will be satisfactory for your present needs. Should you require anything further, just give me a call.

Thank you for allowing us to perform this analysis.

Sincerely,

WELDING CONSULTANTS, INC.



Richard L. Holdren, P.E.
Vice President/Welding Engineer

MSCM Note No. 92-7394

To: MSIP/H

Written by: J. L. Hau

From: MSCM

Date: June 5th, 1992

Approved by MSCM:

Subject: Leaking piping fittings found in new 92'HDS complex revamp piping installations.

Copy to: HL, MS, MA, SIP, SIP/QC, MSIP

Several carbon steel pipe fittings leaked during hydrostatic testing done in new sections, recently fabricated during the Hydroprocessing Rationalization Project, hereafter referred to as HDS 1992 revamp. Up to now, the following items have been identified:

No	Item	Standard ⁽¹⁾	UNIT	Remarks
1	4" Weld Neck Flange	A 105	LDHT	Weld repaired and in service
2	6" Weld Neck Flange	A 105	-	Withdrawn and sent to MSCM Lab
3	8" Weld Neck Flange	A 105	HDS	Withdrawn and sent to MSCM Lab
4	4" T-Joint	A 234 WPB	-	Withdrawn and sent to MSCM Lab
(1) 5	ASTM 6" Elbow			

FINDINGS

1. All defective fittings are carbon steel and are Made in China.
2. Defects were identified as forging laps (folds) or seams, which are internal discontinuities with a crack-like appearance produced during manufacturing of these components.
3. In the case of the flanges, the defects appeared to be located in the neck, near the edge that is to be welded to the pipe.
4. One of the examined flange also contained a very coarse Widmanstätten type of structure, typical of improper manufacturing practices (i.e. too high hot working temperature during forging).

CONCLUSIONS

1. Leaks during hydrostatic testing were produced in through-thickness forging defects, referred to as laps, folds and/or seams.

2. The presence of these through-thickness crack-like defects suggests a lack of quality control during manufacturing and poor workmanship, typical of low quality products, which have recently flooded in the world market.

RECOMMENDATIONS

1. The purchasing and the use of these and probably other low quality and presumably cheap items Made in China should be avoided since their poor quality could compromise the safety of operation.
2. Hydrostatic testing is a proven technique that gives adequate guarantee that the pipe lines and fittings are in serviceable conditions and that no through-thickness defects are present now. However, in the case of undetected subsurface forging defects which do not completely go through thickness and hence that did not produce leaks during hydrotesting, corrosion in the course of operation may reach such defects and hence future leakages in service can not be discarded all together.
3. Hence, identification and the exact location of other pipe fittings Made in China and that were recently installed in the HDS complex should be followed by radiography inspection to ascertain whether or not they contain gross forging defects that could develop leaks or failures in service.

DEFINITIONS

Forging Defects: The forging as well as some other hot working shaping operations can produce mechanical defects known as laps and seams.


Laps: also called folds, occurs as the results of a protrusion of hot metal being folded over and forged into the surface. Some decarburization and oxidation usually occurs in these protrusions. The oxide present on the internal surface of the lap prevents the metal from joining during further forging. A discontinuity with a crack-like appearance is thus created, usually containing trapped oxide inclusions and with some decarburization being evident in the lap surface.

Seams: are similar to laps in nature and effect. They appear as closed-up surface cracks and are attributable to hot surface tears in the original ingot and to embedded scale that has been torn out leaving a cavity with oxidized wall, which then are prevented from healing during forging. A surface discontinuity with a crack-like appearance is thus created.


Widmanstätten Structure: this is known as an overheated structure and results from heating well above the upper critical temperature when large austenite grains form and upon cooling this gives rise to this type of Widmanstätten structure, characteristically showing both lack of ductility and resistance to shock.

ATTACHMENTS

See attached photographs for findings and evidences.



(a)



(b)

Fig. 1. This is a 6" weld neck flange that leaked during hydrostatic testing. An attempt was made to remove and weld repair the defect but because it went deeper into the neck, the attempt was abandoned.

- (a) A general view showing the flange on the side where the repair was attempted. The hole just above the ruler is the excavation left after attempting to remove the defect.
- (b) A close-up view of the excavation showing the crack-like forging defect (indicated by an arrow) and also some slag or oxide inclusions (indicated by two arrows) which looked like porous in the material.

SLAG





Fig. 2. This is a 4" Tee Joint that leaked during hydrostatic testing.



- (a) A general view showing the ^{T-joint} flange on the side where the words Made in China was stamped. The side where the defect was found is indicated by an arrow.
- (b) A front view of the side where the defect was found. The V cut was done in an attempt to obtain a small sample of the defective area for metallographic examination.
- (c) Sketch showing the original shape and appearance of the defect, as seen from the outside surface.
- (d) While attempting to remove the V sample, spontaneous separation of the sample occurred through the crack.
- (e) Photograph of the metallographic sample showing the crack-like forging defect.

← Main crack also
seen in Fig. 2e.



Hardness 133-134 HV

(a)



(b)




Fig. 3. Photomicrograph through the crack as shown in Fig. 2e. The right-hand side edge of (a) continues on the left-hand side edge of (b). Notice that the decarburization (lack of pearlite) associated with the lap surface as well as the presence of slag or oxide inclusions. This is a minor lap attached to the main crack, which is indicated above.




Fig. 4. Metallographic samples taken from the 8" weld neck flange that leaked during hydrostatic testing. The neck of the flange was radiographed near the weld joining it to the pipe and a area 110 mm long was found with crack-like indications and cavities or porous. These were oxide inclusions embedded in the metal at the neck of the flange.

Metallographic examination was carried out on the spots indicated by the arrows. That on the left is shown in Fig. 5; the arrow on the right-hand side corresponds to the area shown in Fig. 6.



Fig. 5. Photomicrograph taken on the spot indicated with an arrow in Fig. 4. Notice that the cavities were filled with oxide but later on partially removed by polishing and metallographic etching. Also notice that the magnification used is relatively low and yet the Widmanstätten microstructure can be clearly seen. This gives an idea of the coarseness of this type of structure.



Fig. 6. Photomicrograph taken on the spot indicated with the arrow on the right-hand side of Fig. 4, showing other discontinuities found in the 8" flange. Notice that the Widmanstätten microstructure can be clearly seen despite the relatively low magnification used.






Fig. 7. Widmanstätten and very coarse structure found in the 8" flange and indicating overheating during the manufacturing process. This type of structure is usually associated with low impact properties and ductility. Hardness taken on this sample was 146-152 HV.




中国机械进出口总公司
CHINA MACHINERY ENGINEERING CO.

MILL TEST CERTIFICATE ASTM A-105


100





8" Weld Neck Flange



MARKING: 4" STD A 234 WPB (D) CHINA



4" Tee Joint



6" Weld Neck Flange

- ① Crack-like feature
- ② Porous-like feature

MILL REPORTS

Since ANSI B 16.5 and A 105 require heat number identification to appear on each flange, the following photographs and copies of mill reports can be used to identify products in the field.

Each mill test report has been annotated to identify where it or the product associated with it fails to comply with either ANSI B 16.5 or ASTM A 105. The photographs are included to illustrate various types of defects found.

MILL REPORT NO. 1

BC AK 2

43

MILL TEST CERTIFICATE

NO. 30211
DATE Dec 9, 1992

FACTORY ORDER NO. FLOWER
 INVOICE NO. 20-91401
 DESCRIPTION 48 FLANGES
 SIZE 20"
 QUANTITY 48 PCS

Cracks in Face
48 Flanges

THE BASE MATERIAL FOR THIS ITEM MEETS THE PROPERTIES OF A105-04
 THE TEST FOR TEST MATERIAL ACCORDS THE FOLLOWING INFORMATION:


WHAT MEASURES	MILL	CHEMICAL COMPOSITION %										TENSILE PROPERTIES		TENSILE Elongation			
		C	Mn	P	S	Si	Ni	Cr	Mo	Cu	F	TS	Yield				
20A	WANG	0.24	0.28	0.02	0.05	0.27	0.24	0.21	0.09	0.11	0.006	0.007	530 MPa	570 MPa	25	14	140(100)

WE CERTIFY THAT THE ITEM DESCRIBED ABOVE CONFORMS WITH THE REQUIREMENTS OF A105-04


DING XIANG NAI XI LI FLANGE FACTORY
 DING XIANG NAI XI LI
 SIGNATURE *Yan Jie Song*

Province of SHANXI

Amir Shari



1. The signature on this report is not the flange manufacturer. It is reported to be a trading company representative.
2. The sum of the chromium and molybdenum is .35% Maximum permitted by A-105 is .32%.
3. Flange exhibits inclusions.
4. Tian Gong (trading co.) representative reported that Tai Gong is not the producing mill.
5. The trading company reported that Ding Xiang Flange Company did not use A-105 but instead used 25MN to produce all of its flanges (117-139 ions).



MILL REPORT NO. 2

MILL TEST REPORT

REPORT NO. 90062 *Qc: Qund*
 CUSTOMER IND-PTT *996: Kully Osm*
 MATERIAL ASTM A302 ALUM. BL WDS *P.O.# M18862*
 ORDER NO. 90062 *33036-40*

ISSUED BY: WETTING ENGINEER
 PROCEED VOUCHER
 Enclosed to change *2/12/78*

DATE: Nov 15, 1991

Description	Heat No.	Mechanical Properties					Chemical Composition									
		Y. T.		Elong	R.A.	Hardness	C	Si	Mn	P	S	Ni	Cu			
		psi	ksi											%	%	%
100 1/2" 6" 30 30 30 30	550	155	41247	78794	51	51	84	22	19	74	21	21				
" 30"	550	154	41245	73536	50	50	83	21	20	80	21	21				
" 4" 30 30 30 30	550	155	42610	72603	29	51	170	25	25	82	20	51				
" 6"	550	156	42610	71961	51	52	712	25	25	89	20	51				
500 1/2" 5" 30 30 30 30	10	156	42670	71961	51	52	712	25	25	89	20	51				
" 3" 30 30 30 30	50	154	42670	71961	51	50	712	25	25	89	20	51				
" 4"	8	157	44092	74245	27	49	174	22	24	73	25	30.8				
" 6"	10	157	44092	74245	27	49	174	22	24	73	25	30.8				
" 8"	10	157	44092	74245	27	49	174	22	24	73	25	30.8				
" 10"	10	157	44092	74245	27	49	174	22	24	73	25	30.8				
" 12"	400	157	41814	73545	51	50	84	25	21	73	25	30.8				
" 14"	500	157	41814	73545	51	50	84	25	21	73	25	30.8				
" 16"	500	155	41670	71961	50	50	83	25	21	73	25	30.8				
" 18"	50	155	41247	71259	51	51	84	25	21	73	25	30.8				
" 20"	50	155	40536	71961	25	48	171	26	24	74	23	25				
" 22"	50	155	40536	71961	25	48	171	26	24	74	23	25				
" 24"	50	155	40536	71961	25	48	171	26	24	74	23	25				

We hereby certify that the material described herein has been tested and reported with satisfactory results in accordance with the requirements of the above specification.

材料 試驗 報告
MATERIAL TEST REPORTS

0 1) CONTACT: (80)0E1409W 266 P.O.NO. 109636
 2) MANUFACTURER: STEEL BONE
 3) CUSTOMER: STEEL VALVE CORPORATION
 4) ADDRESS: 10000 AVENUE POK
 5) MATERIAL: ALU
 6) INSPECTION DATE: 10-10-1990

TYPE.	W.D. 4
NAME OF PART. PLACES	CHEOL DA HO, LA THAO THONG

牌 号		化 学 成 分 CHEMICAL COMPOSITIONS					机 械 性 质 MECHANICAL PROPERTIES					说 明 书 号 SPECIFICATION OF PART		
D. 号		C	Si	Mn	P	S	抗拉强度 屈服点	延伸率	断面收缩率	冲击功	LOT NO OF MEAT	材 质	零件重量 公斤	
MEAT							R _m	R _s	ELONG	RA	100	SPECIFICATION	PART	
NO		%	%	%	%	%	T _{0.2}	T _{0.01}	%	%	TREATMENT		Q7	
		%	%	%	%	%	MPa	MPa	%	%			KG	
1-344	0.24	0.27	0.80	0.024	0.014	56.5	33.6	75.4	33.0	168		16" 130F 5/8 R/R	140	
1-406	0.27	0.23	0.80	0.017	0.022	45.6	44.8	26.4	30.2	169		16" 130F 5/8 R/R	150	
1-405	0.24	0.23	0.79	0.021	0.018	58.4	31.4	30.0	32.0	170		20" 130F 5/8 R/R (77)	116	
2-284	0.25	0.24	0.78	0.017	0.021	55.7	33.9	31.0	31.0	168			170	
3-309	0.25	0.26	0.78	0.025	0.030	60.3	31.4	28.0	30.0	170			200	

上海机械工业公司
检验专用章
2013年10月

SHANGHAI MACHINERY
INSPECTION CO., LTD.
FOR EXAMINATION ONLY

NOTE: THIS REC is extracted from the original REC and REC 310.3.

OTHERS:

46

MILL REPORTS No. 4 (A-E)

1. Do not identify unspecified elements.
2. Do not indicate normalizing.

PO 35344 Stock

INTERNATIONAL STEEL

SHOP ORDER

DATE: 9, 1985

CERTIFICATE NUMBER: 500-9

MATERIAL SPECIFICATION: ASTM A-105

OTHER SPECIFICATIONS: NONE

NO.	SIZE	WEIGHT	YIELD	TENSILE	ELONG.	REDUCED	CHARPY	TEMP.	NOTCH	TEMP.	NOTCH	
NO-134	4"	400 LBS	23	6.74	1.20	0.015	0.031	0.21	534 Kpsi	290 Kpsi	38.55	164
NO-135	4"	400 LBS	23	6.77	0.42	0.019	0.034	0.29	534 Kpsi	285 Kpsi	37.58	157
NO-141	4"	400 LBS	270	6.26	1.38	0.015	0.031	0.29	521 Kpsi	322 Kpsi	35.43	162
NO-99	4"	400 LBS	270	6.27	1.85	0.011	0.030	0.25	529 Kpsi	303 Kpsi	37.43	238
NO-95	4"	400 LBS	270	6.74	1.37	0.016	0.031	0.27	515 Kpsi	300 Kpsi	35.41	223
NO-141	4"	400 LBS	270	6.26	1.10	0.015	0.031	0.29	521 Kpsi	322 Kpsi	37.43	162
NO-132	4"	400 LBS	270	6.27	1.10	0.014	0.031	0.29	525 Kpsi	291 Kpsi	34.34	153
NO-135	4"	400 LBS	270	6.25	0.98	0.012	0.034	0.25	537 Kpsi	320 Kpsi	36.42	253

MEETS ASME SPECIFICATIONS

APPROVED: [Signature]

DATE: 22 Jan/91

SIGNED BY: [Signature]

THE INFORMATION HEREON IS CERTIFIED TO BE A CORRECT AND TRUE TRANSLATION OF THE ORIGINAL MILL TEST REPORTS.

PO 32377

SHOP ORDER

Tag No.

CERTIFICATE NUMBER: 1945

MATERIAL SPECIFICATION: ASTM A-105

OTHER SPECIFICATIONS: NONE

ITEM	NO.	WEIGHT	YIELD	TENSILE	ELONG.	REDUCED	CHARPY	TEMP.	NOTCH	TEMP.	NOTCH
1	1194	650946	RPW IS (600)	0.27	0.64	0.002	0.015	0.27	372.8	501.2	25.5
2	29	650946	RPW STD (CLASS 600)	0.27	*	*	*	*	*	*	*
3	86	610504	"	0.24	0.70	0.019	0.013	0.26	385.2	521.7	25.7
4	81	680051	"	0.24	0.61	0.014	0.016	0.26	385.2	521.7	26.0
5	625	*	"	*	*	*	*	*	*	*	*
6	530	*	"	*	*	*	*	*	*	*	*
7	711	640403	"	0.25	0.67	0.017	0.007	0.30	436	566.4	25.5
8	135	*	"	*	*	*	*	*	*	*	*
9	207	61000	"	0.24	0.72	0.017	0.011	0.28	397.7	546.8	25.2
10	290	6101004	"	0.28	0.70	0.024	0.011	0.32	345.1	551.3	22.2
11	203	610926	"	0.24	0.70	0.017	0.015	0.27	406.7	526.5	26.8
12	196	661424	"	0.24	0.63	0.017	0.011	0.22	347.2	524.7	26.6
13	185	661134	"	0.25	0.66	0.016	0.012	0.27	384.5	520.0	26.6
14	196	610400	"	0.29	0.66	0.025	0.025	0.28	346.0	517.7	24.3
15	204	651010	"	0.24	0.72	0.022	0.016	0.34	434.0	536.5	28.3
16	207	*	"	*	*	*	*	*	*	*	*

WE HEREBY CERTIFY THAT THE INFORMATION CONTAINED ON THIS REPORT IS CORRECT

DATE: 22 Jan/91

MILL REPORTS NO. 4

MILL TEST REPORT

Shop ORDER No. 31793

ANALYST: John F. H. H. H. TAG NO. 31793

DATE: 7-28-78 CUSTOMER ORDER NO.: 72721

MATERIAL SPECIFICATION: ASTM A554 OTHER SPECIFICATION: ASME B 1.5 CERTIFICATE NUMBER: NC 1354

ITEM	SIZE	SHAPE	MATERIAL	CHEMICAL COMPOSITION										TENSILE	YIELD	ELONG.	REDUCED	IMP.	
				C	Mn	P	S	Si	Al	N	As	Se	Ag						
1	9	12	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05
2	317	04	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05	
3	144	05	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05	
4	150	06	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05	
5	150	07	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05	
6	150	08	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05	
7	150	09	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05	
8	150	10	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05	
9	150	11	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05	

NOTE: THIS REPORT IS VALID FOR THE MATERIAL SPECIFICATION AND THE ANALYST'S SIGNATURE ONLY. IT IS NOT VALID FOR THE MILL'S OWN USE.

ANALYST: John F. H. H. H. DATE: 7-28-78

C

MILL TEST REPORT

Shop ORDER No. 1267

ANALYST: John F. H. H. H. TAG NO. 1267

DATE: 7-28-78 CUSTOMER ORDER NO.: 72721

MATERIAL SPECIFICATION: ASTM A554 OTHER SPECIFICATION: ASME B 1.5 CERTIFICATE NUMBER: NC 1354

ITEM	SIZE	SHAPE	MATERIAL	CHEMICAL COMPOSITION										TENSILE	YIELD	ELONG.	REDUCED	IMP.
				C	Mn	P	S	Si	Al	N	As	Se	Ag					
1	150	12	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
2	150	13	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
3	150	14	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
4	150	15	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
5	150	16	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
6	150	17	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
7	150	18	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
8	150	19	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
9	150	20	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05

NOTE: THIS REPORT IS VALID FOR THE MATERIAL SPECIFICATION AND THE ANALYST'S SIGNATURE ONLY. IT IS NOT VALID FOR THE MILL'S OWN USE.

ANALYST: John F. H. H. H. DATE: 7-28-78

D

MILL TEST REPORT

Shop ORDER No. 1267

ANALYST: John F. H. H. H. TAG NO. 1267

DATE: 7-28-78 CUSTOMER ORDER NO.: 72721

MATERIAL SPECIFICATION: ASTM A554 OTHER SPECIFICATION: ASME B 1.5 CERTIFICATE NUMBER: NC 1354

ITEM	SIZE	SHAPE	MATERIAL	CHEMICAL COMPOSITION										TENSILE	YIELD	ELONG.	REDUCED	IMP.
				C	Mn	P	S	Si	Al	N	As	Se	Ag					
1	150	12	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
2	150	13	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
3	150	14	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
4	150	15	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
5	150	16	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
6	150	17	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
7	150	18	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
8	150	19	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05
9	150	20	2	150	ASTM A554	105	126	0.03	0.04	0.02	0.04	0.05	0.05	0.05	0.05	0.05	0.05	0.05

NOTE: THIS REPORT IS VALID FOR THE MATERIAL SPECIFICATION AND THE ANALYST'S SIGNATURE ONLY. IT IS NOT VALID FOR THE MILL'S OWN USE.

ANALYST: John F. H. H. H. DATE: 7-28-78

E

no photos available

MARKINGS,
DESCRIPTIONS
& PHOTOGRAPHS

Flanges with the following markings have been reported to the National Board as problematic. This information should prove useful since flanges from the same heat should carry markings identical to these.

DSI 4 300 RF B16 A-105N STD.345 CHINA

Cracked in heat affect zone

- Hardness at fracture edge into the hub, range from over 500 to over 260 BHN.
- Chemical analysis was as follows C -.38, Mn -.82, P -.028, S -.037, Si -.030, Ni -.40, Cr -.40, Mo -.15, Cu -.47
- The microstructure of the flange forging indicates an improper heat treatment after forging and certainly did not depict a normalized structure as would be expected from the "N" stamp on the forging.

B-16.5 072 LEO STD TMI 454 CHINA

- Cracking with inclusions. Cracks ground to .375" and increased in size.

LEO 4" 150 RFWN STD B-16 A-105 TB-511 CHINA

(TWO FOUND)

- Had been repaired by welding and had not been stress relieved or stamped per ASTM.

4" 150 N B-16 A-105 DZ44 GJ CHINA

- Cracked in the weld neck and had inclusions in two locations.

4" 300 STD A-105 57 CHINA

- Weld neck cracked while welding.

A-105 LEO 6 150 RFWN STD B-16

- Numerous inclusions in face.
- Inclusions in flange wall.

4 300 STD B-16 A-105 N W/N 58 CHINA

- Deformed bolt hole.
- Chip in the raised face.
- Gouges in the weld neck.


QD CHINA 6 150 A105 90-610 B16.5

- [6] is in error. This blind flange is 8" size.
- Flange leaked in approximately 16 separate places.
- Flange showed evidence of extensive welding.
- Weld repairs were not identified with a letter "W" as required by A105.


18 2 150 RFSO B16 A105 109MI 292 CHINA

- radial crack from bore to bolt hole – visible from both sides – found during hydro.


We have reason to believe one facility, as a result of mill test reviews, has rejected 5,000 China flanges, 3,000 of which had already been welded on pipe spools. Subsequent tests at an independent laboratory revealed that chemistry was out of spec on more than 50% of 31 heats. In addition, the macroetch revealed a number of the flanges had not been normalized although the letter "N" was stamped on the flange per ASTM.




Flange exhibits laps or seams to an edge depth of approximately 50% of wall thickness.




The following four photographs are of a 14" slip-on flange found in Alberta, Canada. This flange is identified with the following markings:




Full flange



SXM A105 B16.5 150 SO RF 14 B913725 CHINA



Gasket side



Other side

LETTER OF RESPONSE FROM CBPVI



CENTRE OF BOILER & PRESSURE VESSEL INSPECTION &
RESEARCH OF THE MINISTRY OF LABOUR, P. R. C.

FACSIMILE TRANSMISSION:

TO: Mr. John D. McLoughlin
NBBZ

FROM: Wang Hannuo

Director of CBPVZ

FAX NO: 614 888-0750

DATE SENT: Aug. 31, 1993

ATTENTION: _____

NO. OF PAGES (inc. over-sheet) 1

PLEASE ADVISE AS SOON AS POSSIBLE IF ALL PAGES ARE NOT RECEIVED

Dear Mr. McLoughlin,

I have read your letter to Mr. Zhang Lianhai (CBPVI's vice Director) on Aug. 6th, 1992 as well as the copy of your letter to Mr. Zheng Youmei (the State Council of P.R.C.). For the importance of the matter, Mr. Zhang Lianhai has reported me all the details about it, and I also have got the information about the discussion between you and our Liao Ning Province delegation just in U.S.. As the director of CBPVI, I'd like to inform you something about the quality of the flange made in China.

How to result the problem of the quality of the flange made in China? Thank for your and our great efforts. The State Import and Export Commodities Inspection and testing Bureau of P.R.C. has issued a order about it. The main points of the order is as follow:

In order to ensure the quality, since Jan. 1st, 1993, all the flange, elbow, tube for boiler and pressure vessel made in China for export must be compelled to be inspected and tested by CBPVI or some other inspective units according to the international standards or the standards of the imported countries. Would you be so kind to inform these to your colleagues as well as the companies concerned in your convenience, to add the clause about this mandatory inspection in their contracts concerned, and to make sure the inspective marks on the commodities concerned.

I am looking forward to hearing from you soon!

With my best regards,

Your sincerely

王韩挪
Wang Hannuo
Director of



8° Ji Chang Nan
Tel. (01) 4665500

FAX

Don Zhu Men Wai Niu Wang Miao
(01) 4665303, (01) 4665296

Beijing 100027
Cable: BEIJING 6932

page 1

THE NATIONAL BOARD OF BOILER
AND PRESSURE VESSEL INSPECTORS
1055 CRUPPER AVENUE
COLUMBUS, OHIO 43229-1183

ADDRESS CORRECTION REQUESTED
RETURN POSTAGE GUARANTEED

BULK RATE
U.S. POSTAGE
P A I D
COLUMBUS, OHIO
PERMIT NO. 117