



Nuclear Group
P.O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 393-6000

April 2, 1993
ND3MNO:3440


Beaver Valley Power Station, Unit No. 2
Docket No. 50-412, Licensee No. NPF-73
LER 93-005-00

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Gentlemen:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report is submitted:

LER 93-005-00, 10 CFR 50.73.a.2.v.D, "Potential for Inadequate Core Cooling Flow During Hot Leg Recirculation."


L. R. Freeland
General Manager
Nuclear Operations

DJM/sl

Attachment

9304080219 930402
PDR ADDCK 05000412
S PDR

IE22
11

April 2, 1993
ND3MNO:3440
Page 2

cc: Mr. T. T. Martin, Regional Administrator
United States Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, PA 19406

Mr. G. E. Edison, BVPS Licensing Project Manager
United States nuclear Regulatory Commission
Washington, DC 20555

Larry Rossbach, Nuclear Regulatory Commission,
BVPS Senior Resident Inspector

J. A. Holtz, Ohio Edison
76 S. Main Street
Akron, OH 44308

Larry Beck
Centerior Energy
6200 Oak Tree Blvd.
Independence, OH 44101-4661

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

Mr. Robert Barkanic
Department of Environmental Resources
P.O. Box 2063
16th Floor, Fulton Building
Harrisburg, PA 17120

Director, Safety Evaluation & Control
Virginia Electric & Power Co.
P.O. Box 26666
One James River Plaza
Richmond, VA 23261

W. Hartley
Virginia Power Company
5000 Dominion Blvd.
2SW Glenn Allen, VA 23060

April 2, 1993
ND3MNO:3440
Page 3

J. M. Riddle
Halliburton NUS
Foster Plaza 7
661 Anderson Drive
Pittsburgh, PA 15220

Bill Wegner, Consultant
23 Woodlawn Terrace
Fredricksburg, VA 22405

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Beaver Valley Power Station Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 4 1 2 1				PAGE (3) OF 0 3									
TITLE (4) Potential for Inadequate Core Cooling Flow During Hot Leg Recirculation																							
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)													
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES N/A				DOCKET NUMBER(S) 0 5 0 0 0										
0	3	0	4	9	3	9	3	0	0	5	0	0	0	4	0	2	9	3	0	5	0	0	0
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)																					
1		20.402(b)				20.405(c)				50.73(a)(2)(iv)				73.71(b)									
POWER LEVEL (10)		20.405(a)(1)(i)				50.38(a)(1)				X 50.73(a)(2)(vi)				73.71(c)									
1 0 0		20.405(a)(1)(ii)				50.38(a)(2)				50.73(a)(2)(vii)				OTHER (Specify in Abstract Below and in Text, NRC Form 368A)									
		20.405(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(viii)(A)													
		20.405(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)													
		20.405(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(ix)													
LICENSEE CONTACT FOR THIS LER (12)																							
NAME L. R. Freeland, General Manager Nuclear Operations										TELEPHONE NUMBER AREA CODE 4 1 2 6 4 3 - 1 2 5 8													
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																							
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC				
B	B	P	X	X	X	X	X	X	X	N													
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)		MONTH		DAY		YEAR							
YES (If yes, complete EXPECTED SUBMISSION DATE)										X NO													

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

The Westinghouse Electric Corporation recently notified Duquesne Light Company of an issue related to supplying sufficient flow to the reactor coolant system to maintain adequate core cooling following a postulated loss of coolant accident (LOCA). A Duquesne Light engineering evaluation of this information determined that inadequate core cooling could exist due to the postulated single failure of a motor operated valve (MOV) in the low head safety injection (LHSI) system. Approximately fourteen (14) hours following a large break LOCA, the safety injection system is transferred from the cold leg recirculation mode to the hot leg recirculation mode. This is performed to terminate boiling and to prevent boron precipitation in the core. During the realignment of the LHSI system, failure of the discharge MOV to open would prevent LHSI flow to the hot legs. If the operators did not restore the LHSI flow to the cold legs, and if the break was located on a hot leg (such that full high head safety injection (HHSI) flow did not reach the core) then adequate core cooling could not be assured. In order to prevent this situation, the emergency procedures have been revised to direct the operators to immediately restore cold leg recirculation flow from the LHSI system if hot leg flow can not be established.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Beaver Valley Power Station Unit 2	0 5 0 0 0 4 1 2	9 3	— 0 0 5	— 0 0	0 2	OF 0 3	

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Description of Event:

The Westinghouse Electric Corporation recently notified Duquesne Light Company of an issue related to supplying sufficient flow to the reactor coolant system to maintain adequate core cooling following a postulated loss of coolant accident (LOCA). A Duquesne Light engineering evaluation of this information determined that inadequate core cooling could exist due to the postulated single failure of a motor operated valve (MOV) in the low head safety injection (LHSI) system. Approximately fourteen (14) hours following a large break LOCA, the safety injection system is transferred from the cold leg recirculation mode to the hot leg recirculation mode. This is performed to terminate boiling and to prevent boron precipitation in the core. During the realignment of the LHSI system, failure of the discharge MOV to open would prevent LHSI flow to the hot legs. If the operators did not restore the LHSI flow to the cold legs, and if the break was located on a hot leg (such that full high head safety injection (HHSI) flow did not reach the core) then adequate core cooling could not be assured. In order to prevent this situation, the emergency procedures have been revised to direct the operators to immediately restore cold leg recirculation flow from the LHSI system if hot leg flow can not be established.

Cause of The Event

This event was caused by inadequate analysis of the affect of a failure of the LHSI hot leg discharge MOV. The single failure of the LHSI hot leg discharge MOV was previously analyzed and it was believed that the system would still meet the required level of performance for core cooling. Recent Westinghouse analysis indicates that this is incorrect.

Corrective Actions

Immediate: The appropriate valves were administratively controlled to prevent realigning the LHSI system to the hot leg recirculation path until the emergency procedure could be revised.

Long Term: The emergency procedure which controls the transfer to hot leg recirculation was revised to direct the operators to immediately restore cold leg recirculation flow from the LHSI system if hot leg flow cannot be established.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Beaver Valley Power Station Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 4 1 2	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 3	— 0 0 5	— 0 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Previous Similar Events

There have been no previous reportable events similar to this one.

Reportability

The single failure of the LHSI system hot leg discharge MOV is an event or condition that alone could have prevented the fulfillment of the safety function of a system needed to mitigate the consequences of an accident. As such, this report is being submitted in accordance with 10CFR50.73.a.2.v.D.

Safety Implications

The potential for inadequate core cooling during the hot leg recirculation phase of a LOCA was increased due to this event. If the LHSI hot leg discharge MOV failed to open when aligning for hot leg recirculation, and if the operator did not restore cold leg flow, and if the break existed on a hot leg such that full HHSI flow was not available to the core, adequate core cooling could not be assured. However, the transfer to hot leg recirculation occurs fourteen hours after the LOCA, at which time the Technical Support Center staff would be available to evaluate the situation and advise the operators. Additionally, the core exit temperatures are monitored and the function restoration procedures would be implemented to correct an inadequate core cooling condition.