



**CENTERIOR
ENERGY**

Donald C. Shelton
Vice President - Nuclear
Davis-Besse

300 Madison Avenue
Toledo, OH 43652-0001
(419) 249-2300

Docket Number 50-346

License Number NPF-3

Serial Number 2133

April 12, 1993

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Technical Specification 4.4.5.5a Report of Steam Generator
Tube Plugging

Gentlemen:

This letter is submitted in accordance with the requirements of the Davis-Besse Nuclear Power Station (DBNPS) Unit Number 1, Operating License, Appendix A, Technical Specifications. Technical Specification 4.4.5.5a requires Toledo Edison to report to the Nuclear Regulatory Commission (NRC) the number of tubes plugged in each steam generator (SG) following each inservice inspection of steam generator tubes.

The Eighth Refueling Outage SG tube inservice inspection was completed on March 26, 1993. As a result of the inspection findings, 43 tubes were plugged in SG 1-1 and 321 tubes were plugged in SG 1-2. In addition, preventive sleeving was installed in 213 tubes in SG 1-1.

Toledo Edison will provide the complete results of the steam generator tube inservice inspection in accordance with Technical Specifications 4.4.5.5b and 6.9.1.5b. This report will include: 1. The number and extent of tubes inspected, 2. The location and percent of wall-thickness penetration for each indication of an imperfection, and 3. The identification of tubes plugged or sleeved. This report is submitted on an annual basis and is due March 31, 1994.

190159

9304200025 930412
PDR ADOCK 05000346
P PDR


Operating Companies:
Cleveland Electric Illuminating
Toledo Edison

ADD 1/0

Docket Number 50-346
License Number NPF-3
Serial Number 2133
Page 2

Should further information be required, please contact
Mr. Robert W. Schrauder, Manager - Nuclear Licensing, at (419)
249-2366.

Very truly yours,


MKL/dlc

cc: A. B. Davis, Regional Administrator, NRC Region III
J. B. Hopkins, NRC Senior Project Manager
S. Stasek, DB-1 NRC Senior Resident Inspector
Utility Radiological Safety Board