

Report No. 2-80-27/1T

1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

14 25 25 30 57 CAT 58

LICENSE NUMBER LICENSE TYPE

01 02 07 71 10680 8112080 9
SOCKET NUMBER EVENT DATE REPORT DATE

During reactor startup from hot standby, the number three main steam bypass valve exhibited erratic operation. Reactor power was reduced until the source of the problem was identified. The bypass valve was purposely failed closed, thereby slightly reducing main steam bypass capability. The event has no applicable Technical Specification. This report is made under the reporting requirements of Bulletin 80-17.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP SUBCODE		VALVE SUBCODE			
0	0	11	E	12	A	13	E	L	S	C	O	N	14	Z	15	Z	16
17		18		19		20		21		22		23		24		25	
YEAR		MONTH		DAY		HOUR		MINUTE		SECOND		MILLISECOND		MICROSECOND		NANOSECOND	
8	0	26	0	2	7	27	0	1	28	0	1	29	T	30	—	31	0
32		33		34		35		36		37		38		39		40	
41		42		43		44		45		46		47		48		49	
50		51		52		53		54		55		56		57		58	
59		60		61		62		63		64		65		66		67	
68		69		70		71		72		73		74		75		76	
77		78		79		80		81		82		83		84		85	
86		87		88		89		90		91		92		93		94	
95		96		97		98		99		100		101		102		103	
104		105		106		107		108		109		110		111		112	
113		114		115		116		117		118		119		120		121	
122		123		124		125		126		127		128		129		130	
131		132		133		134		135		136		137		138		139	
140		141		142		143		144		145		146		147		148	
149		150		151		152		153		154		155		156		157	
158		159		160		161		162		163		164		165		166	
167		168		169		170		171		172		173		174		175	
176		177		178		179		180		181		182		183		184	
185		186		187		188		189		190		191		192		193	
194		195		196		197		198		199		200		201		202	
203		204		205		206		207		208		209		210		211	
212		213		214		215		216		217		218		219		220	
221		222		223		224		225		226		227		228		229	
230		231		232		233		234		235		236		237		238	
239		240		241		242		243		244		245		246		247	
248		249		250		251		252		253		254		255		256	
257		258		259		260		261		262		263		264		265	
266		267		268		269		270		271		272		273		274	
275		276		277		278		279		280		281		282		283	
284		285		286		287		288		289		290		291		292	
293		294		295		296		297		298		299		300		301	
302		303		304		305		306		307		308		309		310	
311		312		313		31											

A lug connector in the wiring from the bypass valve linear variable differential transformer to the valve control circuitry was found to be broken. The connector was replaced. On November 17, 1980 the circuit card was replaced, proper valve operation verified, and the valve restored to service.

GENERAL STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)	
1	2	3	4	5	6
		N/A	A	(11)	Operator Observation
AMOUNT OF ACTIVITY (35)		LOCATION OF RELEASE (36)			
		N/A			N/A
DESCRIPTION (33)					
		N/A			
REMARKS (34)					
		N/A			
REMARKS (34)					
		N/A			

8012010455

N/A

M. J. Cooney

PHONE

(215) 841-5020