

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

10

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	6	0	7	0	1	0	2	8	1	8	0	1	2	9	8	1	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND POSSIBLE CONSEQUENCES	
0 3	During normal operation while performing SI 4.1.A-8, scram discharge instrument volume
0 3	rod block level switch (25 gal) 2-LS-85-45E was found set at 27 gallons. In addition,
0 4	2-LS-85-45F (3 gal) alarm switch remains inoperable as reported on 260/8058. There
0 5	are no redundant systems. There was no effect on the health or safety of the public.
0 6	Previous events: 260/8052, 260/8058, and 260/8101. This item reported under
0 7	NRCB 80-14.

SYSTEM CODE I B 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE S 15		VALVE SUBCODE Z 16	
EVENT YEAR 8 1 21		SEQUENTIAL REPT. NO. 0 0 2 24		OCCURRENCE CODE 0 3 27		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN E 18		FUTURE ACTION F 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED Y 23	
NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER L 25		COMPONENT MANUFACTURE # R 2 2 9 0 26							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The Robertshaw model SL-305-EI-X setpoint had drifted. The switch was recalibrated,
11 functionally tested and returned to service. This switch will be replaced as part
12 of CRD improvement DCR 2203.
13
14

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	2	3	4	5	6	7	8	9	10
E	28	1	0	0	29	NA	B	31	Surveillance Testing
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	2	3	4	5	6	7	8	9	10
Z	33	Z	34	NA		NA			
PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBLICITY		NRC USE ONLY	
1	2	3	4	5	6	7	8	9	10
0	0	0	0	37	Z	38	NA		
0	0	0	0	40			NA		
0	0	0	0	43			NA		
0	0	0	0	45					
0	0	0	0	44			NA		

NAME OF PREPARER

PHONE

POOR ORIGINAL

San Joaquin Valley Authority
Ferry Nuclear Plant

Form BF-17
BF 10.2
1/10/79

LER SUPPLEMENTAL INFORMATION

Item # 260 8102 Technical Specification Involved NA
Under Technical Specification NRCB 80-14
Date of Occurrence 1/7/81 Time of Occurrence 0945 Unit 2

Item and Description of Occurrence:

While performing SI 4.1.A-8, SDV tank level switch (25 gal) 2-LS-85-45E was found set at 27 gallons. In addition 2-LS-85-45F (3 gal) switch remains inoperable.

Conditions Prior to Occurrence:

Unit 1 at 96% power.

Unit 2 at 100% power.

Unit 3 refueling.

Item specified in the Technical Specification Surveillance Requirements met
Inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Instrument drift.

Apparent Consequence:

There was no danger to the health or safety of the public, no release of activity, no damage to plant or equipment and no resulting significant chain of events.

Corrective Action:

The switch was recalibrated, functionally tested for repeatability and returned to service. The switch will be reevaluated under DCR 2203.

260/8052, 260/8058 and 260/8101

Time Period - Lifetime; Responsibility - Administrative Supervisor

