

Tennessee Valley Authority
Brown's Ferry Nuclear Plant

Form BF-17
BF 15.2
1/10/79

LER SUPPLEMENTAL INFORMATION

Reference - 260 / 8051 Technical Specification involved 3.2.B

Reported Under Technical Specification 6.7.2.b(1)

Date of Occurrence 11/21/80 Time of Occurrence 1500 Unit 2

Identification and Description of Occurrence:

During heatup after a refueling outage while performing SI 4.2.B-1, level switch 2-LIS-3-58C, switch 4 (LPCI initiation) was found not to operate at the proper setpoint.

Conditions Prior to Occurrence:

Unit 1 at 99% power.

Unit 2 startup after refueling.

Unit 3 at 84% power.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Redundant switch in same trip channel and in redundant trip channel were operable.

Apparent Cause of Occurrence:

Dirty switch contacts.

Analysis of Occurrence:

There was no damage to the plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health and safety of the public.

Corrective Action:

Cleaned the switch and functionally tested at the proper setpoint several times.

Failure Data:

260/805, 260/801, and 259/7437.

*Initiation: Period - Lifetime; Responsibility - Administrative Supervisor

POOR ORIGINAL