

## UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH March (Revised)

DOCKET NO. 50-313  
 UNIT NAME ANO Unit 1  
 DATE 4/27/81  
 COMPLETED BY L. S. Bramlett  
 TELEPHONE (501) 968-2519

No.	Date	Type <sup>1</sup>	Duration (Hours)	Reason <sup>2</sup>	Method of Shutting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
* 81-01	810102	S	<u>431.1</u>	C	<u>4</u>	None	Z	ZZZZZZ	Refueling
	810318	F	1.72	G	<u>9</u>	None	Z	ZZZZZZ	Operations inadvertently tested the manual trip switch on the new anticipatory RPS trip module while attempting to reset the modules for startup. The modules were tagged with caution cards until they can be relabeled.
81-02	810319	F	3.05	G	3	None	Z	ZZZZZZ	The turbine tripped during the replacement of a blown indicator bulb in the turbine control circuit. The wrong bulb was inadvertently used.
81-03	810319	S	.56	B	1	None	Z	ZZZZZZ	The unit was taken off line for the turbine overspeed test.
* Underline indicates change made.									

<sup>1</sup>  
 F: Forced  
 S: Scheduled

<sup>2</sup> Reason:  
 A-Equipment Failure (Explain)  
 B-Maintenance of Test  
 C-Refueling  
 D-Regulatory Restriction  
 E-Operator Training & License Examination  
 F-Administrative  
 G-Operational Error (Explain)  
 H-Other (Explain)

<sup>3</sup> Method:  
 1-Manual  
 2-Manual Scram.  
 3-Automatic Scram.  
 4-Continuations  
 5-Load Reduction  
 9-Other

<sup>4</sup> Exhibit G - Instructions  
 for Preparation of Data  
 Entry Sheets for Licensee  
 Event Report (LER) File (NUREG-  
 0161)

<sup>5</sup> Exhibit I - Same Source