

**Detroit  
Edison**

Donald A. Wells  
Manager Quality Assurance  
(313) 237-9657  
2000 Second Avenue  
Detroit, Michigan 48226  
(313) 237-8000



April 30, 1982  
EF2-58066

Mr. James G. Keppler, Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Subject: Interim Report of 10CFR50.55(e) Item on Core Spray Pump Motor  
Damage (#66)

Dear Mr. Keppler:

On April 1, 1982, Project Quality Assurance's Mr. E.L. Thompson, Acting Supervisor-Construction Quality Assurance, telephoned Mr. J. Konklin of NRC Region III, to report on a problem with Core Spray Pump Motor damage at the Fermi 2 site.

This item deals with a gouge discovered in the shaft of a core spray pump motor. Because of the size and depth of the gouge, Edison Engineering decided that the possibility of internal damage existed and the motor was shipped off-site to a General Electric Repair Shop. Investigation is being conducted to determine the cause of the gouge. Reportability will be determined by the results of the investigation.

Another report on this item, either interim or final, is scheduled to be sent to you on or before August 27, 1982. If you have questions concerning this matter, please contact Mr. H.A. Walker, Supervisor-Construction Quality Assurance.

Very truly yours,

DAW/HAW/cp

cc: Mr. Richard DeYoung, Director  
Office of Inspection and Enforcement  
Division of Reactor Inspection Programs  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Bruce Little, Resident Inspector  
U.S. Nuclear Regulatory Commission  
6450 North Dixie Highway  
Newport, Michigan 48166

8205140492 820430  
PDR ADOCK 05000341  
S PDR

IE27  
S110  
~~IE19~~  
MAY 10 1982